

# Dell Endpoint Security Suite Enterprise

## Technical Advisories v3.18

## Notes, cautions, and warnings

 **NOTE:** A NOTE indicates important information that helps you make better use of your product.

 **CAUTION:** A CAUTION indicates either potential damage to hardware or loss of data and tells you how to avoid the problem.

 **WARNING:** A WARNING indicates a potential for property damage, personal injury, or death.

<b>Chapter 1: Technical Advisories.....</b>	<b>7</b>
Contact Dell ProSupport for Software.....	7
New Features and Functionality v3.18.....	7
Resolved Security Advisories v3.18.....	7
Resolved Technical Advisories v3.18.....	7
Technical Advisories v3.18.....	8
New Features and Functionality v3.12.1.....	9
Resolved Security Advisories v3.12.1.....	9
Resolved Technical Advisories v3.12.1.....	9
Technical Advisories v3.12.1.....	10
New Features and Functionality v3.11.....	10
Resolved Security Advisories v3.11.....	10
Resolved Technical Advisories v3.11.....	10
Technical Advisories v3.11.....	11
New Features and Functionality v3.10.2.....	12
Resolved Security Advisories v3.10.2.....	12
Resolved Technical Advisories v3.10.2.....	12
Technical Advisories v3.10.2.....	13
New Features and Functionality v3.10.1.....	13
Resolved Security Advisories v3.10.....	13
Resolved Technical Advisories v3.10.1.....	13
Technical Advisories v3.10.1.....	14
New Features and Functionality v3.10.....	15
Resolved Security Advisories v3.10.....	15
Resolved Technical Advisories v3.10.....	15
Technical Advisories v3.10.....	16
New Features and Functionality v3.9.....	17
Resolved Security Advisories v3.9.....	17
Resolved Technical Advisories v3.9.....	17
Technical Advisories v3.9.....	18
New Features and Functionality v3.8.1.....	18
Resolved Security Advisories v3.8.1.....	18
Resolved Technical Advisories v3.8.1.....	18
Technical Advisories v3.8.1.....	19
New Features and Functionality v3.8.....	20
Resolved Security Advisories v3.8.....	20
Resolved Technical Advisories v3.8.....	20
Technical Advisories v3.8.....	21
New Features and Functionality v3.7.1.....	21
Resolved Security Advisories v3.7.1.....	22
Resolved Technical Advisories v3.7.1.....	22
Technical Advisories v3.7.1.....	22
New Features and Functionality v3.7.....	23
Resolved Security Advisories v3.7.....	23
Resolved Technical Advisories v3.7.....	23

Technical Advisories v3.7.....	24
New Features and Functionality v3.6.....	25
Resolved Security Advisories v3.6.....	25
Resolved Technical Advisories v3.6.....	25
Technical Advisories v3.6.....	26
New Features and Functionality v3.9.....	27
Resolved Security Advisories v3.5.....	27
Resolved Technical Advisories v3.5.....	27
Technical Advisories v3.5.....	28
New Features and Functionality v3.4.....	29
Resolved Security Advisories v3.4.....	29
Resolved Technical Advisories v3.4.....	29
Technical Advisories v3.9.....	30
New Features and Functionality v3.3.....	31
Resolved Security Advisories v3.3.....	31
Resolved Technical Advisories v3.3.....	31
Technical Advisories v3.3.....	32
New Features and Functionality v3.2.....	33
Resolved Security Advisories v3.2.....	33
Resolved Technical Advisories v3.2.....	33
Technical Advisories v3.2.....	34
New Features and Functionality v3.1.....	35
Resolved Security Advisories v3.1.....	35
Resolved Technical Advisories v3.1.....	35
Technical Advisories v3.1.....	36
New Features and Functionality v3.0.....	37
Resolved Security Advisories v3.0.....	38
Resolved Technical Advisories v3.0.....	38
Technical Advisories v3.0.....	39
New Features and Functionality v2.9.....	40
Resolved Security Advisories v2.9.....	40
Resolved Technical Advisories v2.9.....	40
Technical Advisories v2.9.....	42
New Features and Functionality v2.8.....	42
Resolved Security Advisories v2.8.....	43
Resolved Technical Advisories v2.8.....	43
Technical Advisories v2.8.....	44
New Features and Functionality v2.7.....	45
Resolved Technical Advisories v2.7.....	46
Technical Advisories v2.7.....	48
New Features and Functionality v2.5.....	49
Resolved Technical Advisories v2.5.....	49
Technical Advisories v2.5.....	50
New Features and Functionality v2.4.....	51
Resolved Technical Advisories v2.4.....	52
Technical Advisories v2.4.....	54
New Features and Functionality v2.3.....	55
Resolved Technical Advisories v2.3.....	55
Technical Advisories v2.3.....	57
New Features and Functionality v2.2.1.....	57

Resolved Technical Advisories v2.2.1.....	58
Technical Advisories v2.2.1.....	58
New Features and Functionality v2.2.....	59
Resolved Technical Advisories v2.2.....	59
Technical Advisories v2.2.....	60
New Features and Functionality v2.1.....	60
Resolved Technical Advisories v2.1.....	61
Technical Advisories v2.1.....	61
New Features and Functionality v2.0.1.....	62
Resolved Technical Advisories v2.0.1.....	62
Technical Advisories v2.0.1.....	63
New Features and Functionality v2.0.....	63
Resolved Technical Advisories v2.0.....	64
Technical Advisories v2.0.....	64
New Features and Functionality v1.8.....	65
Resolved Technical Advisories v1.8.....	67
Technical Advisories v1.8.....	68
New Features and Functionality v1.7.2.....	69
Resolved Technical Advisories v1.7.2.....	69
Technical Advisories v1.7.2.....	70
New Features and Functionality v1.7.1.....	71
Resolved Technical Advisories v1.7.1.....	71
Technical Advisories v1.7.1.....	72
New Features and Functionality v1.7.....	72
Resolved Technical Advisories v1.7.....	73
Technical Advisories v1.7.....	74
New Features and Functionality v1.6.....	74
Resolved Technical Advisories v1.6.....	75
Technical Advisories v1.6.....	76
New Features and Functionality v1.5.....	78
Resolved Technical Advisories v1.5.....	78
Technical Advisories v1.5.....	79
New Features and Functionality v1.4.....	81
Resolved Technical Advisories v1.4.....	81
Technical Advisories v1.4.....	83
New Features and Functionality v1.3.....	84
Resolved Technical Advisories v1.3.....	84
Technical Advisories v1.3.....	88
Resolved Technical Advisories v1.2.....	89
Technical Advisories v1.2.....	93
New Features and Functionality v1.1.1.....	93
Resolved Technical Advisories v1.1.1.....	94
Technical Advisories v1.1.1.....	94
New Features and Functionality v1.1.....	94
Resolved Technical Advisories v1.1.....	95
Technical Advisories v1.1.....	96
Resolved Technical Advisories v1.0.1.....	97
Technical Advisories v1.0.1.....	99
New Features and Functionality v1.0.....	99
Technical Advisories v1.0.....	100

Previous Technical Advisories.....	101
<b>Chapter 2: Workarounds.....</b>	<b>111</b>
<b>Chapter 3: Software and Hardware Compatibility.....</b>	<b>112</b>

# Technical Advisories

Endpoint Security Suite Enterprise offers advanced threat protection at the operating system and memory layers, authentication, and encryption, all centrally-managed from the Security Management Server or Security Management Server Virtual. With centralized management, consolidated compliance reporting, and console threat alerts, businesses can easily enforce and prove compliance for all of their endpoints. Security expertise is built in with features such as pre-defined policy and report templates, to help businesses reduce IT management costs and complexity.

See KB [301500](#) to view FIPS compliance status for the data security line of products.

## Contact Dell ProSupport for Software

Before contacting Dell Support, run SupportAssist for a quick self-diagnostic test. Run [SupportAssist Quick Test](#).

For additional assistance, visit [dell.com/support](#). Online support at [dell.com/support](#) provides access to drivers, manuals, technical advisories, FAQs, and information on emerging issues.

When contacting Dell Support, keep your Service Tag or Express Service Code ready. This helps route your request to the appropriate technical expert quickly.

For international contact details, see [Dell ProSupport for Software international phone numbers](#).

## New Features and Functionality v3.18

Dell systems with Intel Core Ultra Series 3 processors with vPro are currently not compatible with DDPE. On these systems, Intel Total Storage Encryption (TSE) is enabled by default in the BIOS and is therefore also enabled in Windows.

When TSE is enabled, Pre-boot Authentication (PBA) activation fails. As a result, DDPE installation on these systems is blocked until the incompatibility is resolved.

**Workaround:** If DDPE installation is required, disable Intel TSE in the BIOS, reinstall the Windows operating system, and then install and activate DDPE.

## Resolved Security Advisories v3.18

- No security advisories exist.

## Resolved Technical Advisories v3.18

### Advanced Threat Prevention v3.18

- No technical advisories exist.

### Firewall and Web Protection v3.18

- No technical advisories exist.

### Encryption v3.18

- No technical advisories exist.

## Pre-boot Authentication v3.18

- No technical advisories exist.

## SED Manager v3.18

- No technical advisories exist.

## Full Disk Encryption v3.18

- No technical advisories exist.

## BitLocker Manager v3.18

- No technical advisories exist.

# Technical Advisories v3.18

## Advanced Threat Prevention v3.18

- No technical advisories exist.

## Firewall and Web Protection v3.18

- No technical advisories exist.

## Encryption Client v11.18

- No technical advisories exist.

## Pre-boot Authentication v3.18

- No technical advisories exist.

## SED Manager v3.18

- No technical advisories exist.

## Full Disk Encryption v3.18

- No technical advisories exist.

## BitLocker Manager v3.18

- No technical advisories exist.

## New Features and Functionality v3.12.1

- Security issues fix to improve user experience.
- The current Portable Git version (2.42.0) has one high or critical CVE compared to the latest stable version (2.51.0).
- The current Expat version (2.5) has five high or critical CVEs compared to the latest stable version (2.7.1).

## Resolved Security Advisories v3.12.1

- Fixed a security vulnerability issue in the Dell Encryption installer (`DDSSetup.exe`) that allowed privilege escalation through symbolic link manipulation. The installer now verifies log file paths to prevent unauthorized file creation or overwrite during setup. [DDPC-14289]
- Fixed an issue by removing all TSS (SI) components from DDPC to improve platform compatibility, eliminate royalties, and resolve security risks. [DDPC-14272]

## Resolved Technical Advisories v3.12.1

### Advanced Threat Prevention v3.12.1

- No technical advisories exist.

### Firewall and Web Protection v3.12.1

- No technical advisories exist.

### Encryption v3.12.1

- Fixed an issue where remnants of Dell Encryption caused Blue Screen errors (BSOD) on approximately 150 endpoints after upgrading to Windows 11 version 24H2. [DDPC-14172]
- Fixed an issue where symlink detection failed during installation of version 11.10.1. [DDPC-14221]

### Pre-boot Authentication v3.12.1

- No technical advisories exist.

### SED Manager v3.12.1

- No technical advisories exist.

### Full Disk Encryption v3.12.1

- No technical advisories exist.

### BitLocker Manager v3.12.1

- No technical advisories exist.

## Technical Advisories v3.12.1

### Advanced Threat Prevention v3.12.1

- No technical advisories exist.

### Firewall and Web Protection v3.12.1

- No technical advisories exist.

### Encryption Client v11.12.1

- No technical advisories exist.

### Pre-boot Authentication v3.12.1

- No technical advisories exist.

### SED Manager v3.12.1

- No technical advisories exist.

### Full Disk Encryption v3.12.1

- No technical advisories exist.

### BitLocker Manager v3.12.1

- No technical advisories exist.

## New Features and Functionality v3.11

- Support for clean installation and upgrade to Windows 11 version 24H2.

## Resolved Security Advisories v3.11

- No security advisories exist.

## Resolved Technical Advisories v3.11

### Advanced Threat Prevention v3.11

- No technical advisories exist.

## Firewall and Web Protection v3.11

- No technical advisories exist.

## Encryption v3.11

- No technical advisories exist.

## Pre-boot Authentication v3.11

- No technical advisories exist.

## SED Manager v3.11

- No technical advisories exist.

## Full Disk Encryption v3.11

- No technical advisories exist.

## BitLocker Manager v3.11

- No technical advisories exist.

## **Technical Advisories v3.11**

### Advanced Threat Prevention v3.11

- No technical advisories exist.

### Firewall and Web Protection v3.11

- No technical advisories exist.

### Encryption Client v11.11

- The Smart App Control feature may not be supported during clean installations or operating system upgrades. If Smart App Control is enabled and causes operational issues, Dell Technologies recommends to disable the feature. However, once Smart App Control is turned off, it cannot be re-enabled.

### Pre-boot Authentication v3.11

- No technical advisories exist.

### SED Manager v3.11

- No technical advisories exist.

## Full Disk Encryption v3.11

- No technical advisories exist.

## BitLocker Manager v3.11

- No technical advisories exist.

## **New Features and Functionality v3.10.2**

- Issue fixes to improve the user experience.

## **Resolved Security Advisories v3.10.2**

- An issue is fixed where the product upgrade between 11.10 and 11.10.1 was not working.

## **Resolved Technical Advisories v3.10.2**

### Advanced Threat Prevention v3.10.2

- No technical advisories exist.

### Firewall and Web Protection v3.10.2

- No technical advisories exist.

### Encryption v3.10.2

- No technical advisories exist.

### Pre-boot Authentication v3.10.2

- No technical advisories exist.

### SED Manager v3.10.2

- No technical advisories exist.

### Full Disk Encryption v3.10.2

- No technical advisories exist.

### BitLocker Manager v3.10.2

- No technical advisories exist.

## Technical Advisories v3.10.2

### Advanced Threat Prevention v3.10.2

- No technical advisories exist.

### Firewall and Web Protection v3.10.2

- No technical advisories exist.

### Encryption Client v11.10.2

- No technical advisories exist.

### Pre-boot Authentication v3.10.2

- No technical advisories exist.

### SED Manager v3.10.2

- No technical advisories exist.

### Full Disk Encryption v3.10.2

- No technical advisories exist.

### BitLocker Manager v3.10.2

- No technical advisories exist.

## New Features and Functionality v3.10.1

- Issue fixes to improve the user experience.

## Resolved Security Advisories v3.10

- No security advisories exist.

## Resolved Technical Advisories v3.10.1

### Advanced Threat Prevention v3.10.1

- No technical advisories exist.

## Firewall and Web Protection v3.10.1

- No technical advisories exist.

## Encryption v3.10.1

- An issue is fixed where the SED or FDE plus Shield are preventing the system to shutdown. [DDPC-13948]
- An issue is fixed where the SED or FDE plus Shield are preventing the system to Hibernate. [DDPC-14021]

## Pre-boot Authentication v3.10.1

- No technical advisories exist.

## SED Manager v3.10.1

- No technical advisories exist.

## Full Disk Encryption v3.10.1

- No technical advisories exist.

## BitLocker Manager v3.10.1

- No technical advisories exist.

# Technical Advisories v3.10.1

## Advanced Threat Prevention v3.10.1

- No technical advisories exist.

## Firewall and Web Protection v3.10.1

- No technical advisories exist.

## Encryption Client v11.10.1

- When you upgrade the operating system to Win11 24H2, the operating system reverts back to the previous version (Win 11 23H2).
- Product upgrade from 11.10.0.1 to 11.10.1.1 will not work as expected. Customers with 11.10.0.1 who needs to upgrade to 11.10.1.1 will have to uninstall 11.10.0.1 and install 11.10.1.1. A future release will take care of this issue.

## Pre-boot Authentication v3.10.1

- No technical advisories exist.

## SED Manager v3.10.1

- No technical advisories exist.

## Full Disk Encryption v3.10.1

- No technical advisories exist.

## BitLocker Manager v3.10.1

- No technical advisories exist.

## New Features and Functionality v3.10

- Issue fixes to improve the user experience.
- SED PBA multi-disk does not support encryption when the system has RAID 0/1/5/10 configuration.
- Dell Encryption is enhanced to block the uninstallation based on a password that is set on the client by policy from the Dell Security Management Server. When a user attempts to uninstall Dell Encryption without the password, it fails and notifies the Windows Notification sub-system. This functionality is available only in case of EMAgent, MI and DDPSuite installation.
- Dell Encryption is enhanced to ensure communication with an authentic DDPE server during pre-boot authentication for FDE or SED. In Enterprise mode, PBA (pre-boot auth) fetches and compares the server's certificate and hash of Public key that is shared and received from the server.

## Resolved Security Advisories v3.10

- No security advisories exist.

## Resolved Technical Advisories v3.10

### Advanced Threat Prevention v3.10

- No technical advisories exist.

### Firewall and Web Protection v3.10

- No technical advisories exist.

### Encryption v3.10

- An issue is fixed where a blue screen (BSOD) error occurs when you install DDPE 11.9 or earlier versions on Win 11 24H2 systems. Hence, Dell Technologies recommends using DDPE v11.10 on systems using Windows 11 24H2 operating system. [ DDPC-13918]

### Pre-boot Authentication v3.10

- No technical advisories exist.

## SED Manager v3.10

- No technical advisories exist.

## Full Disk Encryption v3.10

- No technical advisories exist.

## BitLocker Manager v3.10

- No technical advisories exist.

# Technical Advisories v3.10

## Advanced Threat Prevention v3.10

- No technical advisories exist.

## Firewall and Web Protection v3.10

- No technical advisories exist.

## Encryption Client v11.10

- After upgrading to Win11 24H2, either a blue screen error (BSOD) is occurred or the operating system reverts back to the previous version(Win 11 23H2). [DDPC-13941]
- When a user attempts to hibernate the system having PBA(FDE/SED) + Shield combination with Windows 11 24H2 operating system, the system doesn't hibernate instead it goes to sleep and doesn't shut down. [DDPC-14021]
- When a user attempts to shut down the system having PBA(FDE/SED) + Shield combination with Windows 11 24H2 operating system, the system doesn't shut down instead it goes to sleep. [ DDPC-13948]

**i** **NOTE:** The Hibernation and Shutdown issue will be resolved in DDPE 11.10.1. Until then, for hibernation issue, the system having PBA(FDE/SED) + Shield combination with Windows 11 24H2 operating system should avoid re-enabling hibernation. For shutdown issue, Dell Technologies recommends to disable the Fast Startup option in BIOS to make shutdown work.

## Pre-boot Authentication v3.10

- No technical advisories exist.

## SED Manager v3.10

- No technical advisories exist.

## Full Disk Encryption v3.10

- No technical advisories exist.

## BitLocker Manager v3.10

- No technical advisories exist.

## New Features and Functionality v3.9

- Bug fixes to improve user experience.
- Upgraded all server and client ISMs to Installshield 2023 R2.

## Resolved Security Advisories v3.9

- Earlier Dell Encryption allows any user to access application install directory during the installation. This issue is resolved by setting the Access Control List on application install directory in the start of the installation or upgrade process. [DDPC-13786]

## Resolved Technical Advisories v3.9

### Advanced Threat Prevention v3.9

- No technical advisories exist.

### Firewall and Web Protection v3.9

- No technical advisories exist.

### Encryption v3.9

- An issue is resolved where a temp folder is created during the Dell Encryption installation as the Access Control List is not configured properly. [DDPC-13619]
- An issue is resolved where the Symlink error is not displayed after the installation is complete. [DDPC-13821]

### Pre-boot Authentication v3.9

- No technical advisories exist.

### SED Manager v3.9

- No technical advisories exist.

### Full Disk Encryption v3.9

- No technical advisories exist.

### BitLocker Manager v3.9

- No technical advisories exist.

## Technical Advisories v3.9

### Advanced Threat Prevention v3.9

- No technical advisories exist.

### Firewall and Web Protection v3.9

- No technical advisories exist.

### Encryption Client v11.9

- The Symlink is not getting detected in the C:\custom folder of your system. [DDPC-13822]

### Pre-boot Authentication v3.9

- No technical advisories exist.

### SED Manager v3.9

- No technical advisories exist.

### Full Disk Encryption v3.9

- No technical advisories exist.

### BitLocker Manager v3.9

- No technical advisories exist.

## New Features and Functionality v3.8.1

- Bug fixes to improve user experience.

## Resolved Security Advisories v3.8.1

- An issue is resolved where the Dell Encryption Installer does not verify if Symlink is available in the ProgramData folder, resulting in creation of random files. [DDPC-13644]

## Resolved Technical Advisories v3.8.1

### Advanced Threat Prevention v3.8.1

- No technical advisories exist.

## Firewall and Web Protection v3.8.1

- No technical advisories exist.

## Encryption v3.8.1

- No technical advisories exist.

## Pre-boot Authentication v3.8.1

- No technical advisories exist.

## SED Manager v3.8.1

- No technical advisories exist.

## Full Disk Encryption v3.8.1

- No technical advisories exist.

## BitLocker Manager v3.8.1

- No technical advisories exist.

## **Technical Advisories v3.8.1**

### Advanced Threat Prevention v3.8.1

- No technical advisories exist.

### Firewall and Web Protection v3.8.1

- No technical advisories exist.

### Encryption Client v11.8.1

- For Dell Precision 7875 workstations, Dell Technologies recommend to use the Dell Encryption client version 11.6 or earlier to avoid the possible black or blue screen problem. [DDPSUS-3295]

### Pre-boot Authentication v3.8.1

- No technical advisories exist.

### SED Manager v3.8.1

- .No technical advisories exist.

## Full Disk Encryption v3.8.1

- No technical advisories exist.

## BitLocker Manager v3.8.1

- No technical advisories exist.

## New Features and Functionality v3.8

- Integrated Package Key Destruction Utility tool in the latest installer of Dell Encryption.

## Resolved Security Advisories v3.8

- No security advisories exist.

## Resolved Technical Advisories v3.8

### Advanced Threat Prevention v3.8

- No technical advisories exist.

### Firewall and Web Protection v3.8

- No technical advisories exist.

### Encryption v3.8

- An issue that results in cmgshieldsvc.exe crash after user logs on is resolved. [13098]
- An issue that results in system BSOD when a composite device is disconnected from VirtualBox is resolved. [13535]
- An issue that results in application service not getting removed from machine using uninstall command is resolved. [11770]

### Pre-boot Authentication v3.8

- An issue that results in PBA not loaded on computers protected by SED Manager when multi-disk encryption is enabled and an additional unencrypted disk is added or replaced is resolved. [DDPC-13358]

### SED Manager v3.8

- An issue that results in PBA not loaded on computers protected by SED Manager when multi-disk encryption is enabled and an additional unencrypted disk is added or replaced is resolved. [DDPC-13358]

### Full Disk Encryption v3.8

- No technical advisories exist.

## BitLocker Manager v3.8

- An issue that results in enabling the user to modify the status of BitLocker in the Control Panel even after the BitLocker Encryption is set to **Turn On Encryption** is resolved. [11717]

## Technical Advisories v3.8

### Advanced Threat Prevention v3.8

- No technical advisories exist.

### Firewall and Web Protection v3.8

- No technical advisories exist.

### Encryption Client v11.8

- No technical advisories exist.

### Pre-boot Authentication v3.8

- No technical advisories exist.

### SED Manager v3.8

- .No technical advisories exist.

### Full Disk Encryption v3.8

- No technical advisories exist.

### BitLocker Manager v3.8

- No technical advisories exist.

## New Features and Functionality v3.7.1

- The internal Windows feature providing user information from Windows to Dell Encryption is scheduled for deprecation but an exact date for the removal is unknown. The Dell Encryption client v11.7 includes a feature to address the loss of this functionality in Windows by implementing a custom Credential Provider. An issue was encountered in cases when other installed products were using a custom Credential Provider on the computer. In these instances, the Windows login process could be disrupted.

To address this, Dell Encryption 11.7.1 returns to use the previous internal Windows function to avoid any potential custom Credential Provider conflicts. If you require the use of custom Credential Providers for third-party applications and updated to Endpoint Security Suite Enterprise v3.7, it is recommended that you update Endpoint Security Suite Enterprise v3.7.1.

## Resolved Security Advisories v3.7.1

- No security advisories exist.

## Resolved Technical Advisories v3.7.1

### Advanced Threat Prevention v3.7.1

- No technical advisories exist.

### Firewall and Web Protection v3.7.1

- No technical advisories exist.

### Encryption v3.7.1

- No technical advisories exist.

### Pre-boot Authentication v3.7.1

- No technical advisories exist.

### SED Manager v3.7.1

- No technical advisories exist.

### Full Disk Encryption v3.7.1

- No technical advisories exist.

### BitLocker Manager v3.7.1

- No technical advisories exist.

## Technical Advisories v3.7.1

### Advanced Threat Prevention v3.7.1

- No technical advisories exist.

### Firewall and Web Protection v3.7.1

- No technical advisories exist.

## Encryption Client v11.7.1

- No technical advisories exist.

## Pre-boot Authentication v3.7.1

- No technical advisories exist.

## SED Manager v3.7.1

- SED Manager requires the use of the Dell custom Credential Provider to synchronize Windows password changes and data encryption keys. If you require use of third-party applications that use custom Credential Providers running on computers protected SED Manager, you must initiate Windows password changes through the Data Security Console. For information about changing your password in the Data Security Console, see the *Password* chapter in the [Data Security Console User Guide](#).

## Full Disk Encryption v3.7.1

- Full Disk Encryption requires the use of the Dell custom Credential Provider to synchronize Windows password changes and data encryption keys. If you require use of third-party applications that use custom Credential Providers running on computers protected Full Disk Encryption, you must initiate Windows password changes through the Data Security Console. For information about changing your password in the Data Security Console, see the *Password* chapter in the [Data Security Console User Guide](#).

## BitLocker Manager v3.7.1

- No technical advisories exist.

## New Features and Functionality v3.7

- Windows 7 is no longer supported.
- Windows 10 2016 LTSC is no longer supported.

## Resolved Security Advisories v3.7

- Endpoint Security Suite Enterprise third-party components have been updated.

## Resolved Technical Advisories v3.7

### Advanced Threat Prevention v3.7

- No technical advisories exist.

### Firewall and Web Protection v3.7

- No technical advisories exist.

## Encryption v3.7

- Files that are required for installation are now properly removed after Encryption is uninstalled. [DDPC-12745]
- A message no longer displays and prompts for restart as a result of a Windows 10 upgrade after running WSDeactivate. [DDPC-12755]
- If Hibernation is enabled, the Hibernation option in the Windows Power menu now displays as expected. [DDPC-13376]
- The 32-bit and 64-bit Dell Encryption child installers details now display the following: **Dell Encryption Installer** [DDPC-13510]
- An issue resulting in inaccessible System Data Encryption keys and boot loop on computers protected by Policy-Based Encryption is resolved. [DDPC-13515, DDPSUS-3205]
- An issue resulting in incomplete and repeated encryption sweeps is resolved. [DDPC-13521, DDPSUS-3207, DDPSUS-3244]

## Pre-boot Authentication v3.7

- An issue resulting in failure to sync passwords if using a third-party credential provider is resolved. [DDPC-13414, DDPSUS-3168]
- The PBA environment now displays the correct error if an incorrect password is entered. [DDPC-13454]

## SED Manager v3.7

- An issue resulting in failure to sync passwords if using a third-party credential provider is resolved. [DDPC-13414, DDPSUS-3168]
- The PBA environment now displays the correct error if an incorrect password is entered. [DDPC-13454]

## Full Disk Encryption v3.7

- An issue resulting in failure to sync passwords if using a third-party credential provider is resolved. [DDPC-13414, DDPSUS-3168]
- The PBA environment now displays the correct error if an incorrect password is entered. [DDPC-13454]

## BitLocker Manager v3.7

- An issue resulting in a repeating log message in the Data Security Console is resolved. [DDPC-13203, DDPC-13410]

## Technical Advisories v3.7

### Advanced Threat Prevention v3.7

- No technical advisories exist.

### Firewall and Web Protection v3.7

- No technical advisories exist.

### Encryption Client v11.7

- No technical advisories exist.

## Pre-boot Authentication v3.7

- The PBA currently does not load on computers protected by SED Manager when multi-disk encryption is enabled and an additional unencrypted disk is added or replaced. As a workaround, bypass the PBA using Recovery. For more information, see *Perform a SED Recovery* in [Encryption Recovery](#). [DDPC-13358]

## SED Manager v3.7

- The PBA currently does not load on computers protected by SED Manager when multi-disk encryption is enabled and an additional unencrypted disk is added or replaced. As a workaround, bypass the PBA using Recovery. For more information, see *Perform a SED Recovery* in [Encryption Recovery](#). [DDPC-13358]

## Full Disk Encryption v3.7

- No technical advisories exist.

## BitLocker Manager v3.7

- No technical advisories exist.

## New Features and Functionality v3.6

- BitLocker Manager now supports setting a delayed PIN prompt. This policy allows administrators to set the number of minutes to delay the BitLocker PIN prompt before it is displayed to the user. For more information, see [AdminHelp > PIN Prompt Delay Policy](#).
- Endpoint Security Suite Enterprise now supports Windows 10 22H2.
- DiagnosticInfo now collects additional logging information for the following:
  - Carbon Black Endpoint Detection and Response
  - Carbon Black AppDefense

## Resolved Security Advisories v3.6

- No security advisories exist.

## Resolved Technical Advisories v3.6

### Advanced Threat Prevention v3.6

- No technical advisories exist.

### Firewall and Web Protection v3.6

- No technical advisories exist.

### Encryption v3.6

- No technical advisories exist.

## Pre-boot Authentication v3.6

- Azure-based domain users with uncached credentials can now login to the PBA as expected. [DDPC-13391]

## SED Manager v3.6

- Computers protected by SED Manager on an Azure-based domain with the *Sync Users at PBA Activation* policy enabled can now use single sign-on. [DDPC-12089]

## Full Disk Encryption v3.6

- Computers protected by Full Disk Encryption on an Azure-based domain with the *Sync Users at PBA Activation* policy enabled can now use single sign-on. [DDPC-12089]

## BitLocker Manager v3.6

- An issue resulting in a repeating log message in the Data Security Console is resolved. [DDPC-13203, DDPC-13410]
- Computers running Windows 11 21H1 and protected by BitLocker Manager can now upgrade to Windows 11 22H2 as expected. [DDPC-13324, DDPC-13365]

## Technical Advisories v3.6

### Advanced Threat Prevention v3.6

- No technical advisories exist.

### Firewall and Web Protection v3.6

- Client Firewall and Web Protection is not supported on Windows 11 22H2 with Smart App Control enabled.

### Encryption Client v11.6

- After uninstalling Dell Encryption, Hibernation may not display in Windows advanced power settings. As a workaround, start command prompt as an administrator then run the following command:

**powercfg.exe /hibernate ON**

[DDPC-13376]

- Computers running new installations of Windows 11 22H2 must install KB2267602 before installing Endpoint Security Suite Enterprise. For more information, see [this Microsoft article](#). [DDPC-13456]

## Pre-boot Authentication v3.6

- Computers protect by the PBA environment and using Windows Hello for Business PIN authentication currently cannot currently use Single Sign-on. [DDPC-13425]
- Computers protected by the PBA environment may not display the PIN authentication option after an operating system upgrade. As a workaround, use password authentication. [DDPC-13453]

## SED Manager v3.6

- No technical advisories exist.

## Full Disk Encryption v3.6

- Computers protected by Multi-disk encryption using the PBA currently lock if Single Sign-on is disabled in the Remote Management Console. As a workaround, recover the computer using the steps in the [Recovery Guide](#). [DDPC-13457]

## BitLocker Manager v3.6

- In rare scenarios, BitLocker Manager may prompt users to change their PIN before the policy duration elapses. [DDPC-13416]
- Computers protected by BitLocker Manager may not display the PIN authentication option after updating from Windows 11 21H2 to Windows 11 22H2. As a workaround, restart the computer. [DDPC-13448]
- In rare scenarios, BitLocker Manager does not initialize an encryption sweep after changing the encryption method in the Remote Management Console. As a workaround, restart the computer. DDPC-13455

## New Features and Functionality v3.9

- Bug fixes to improve user experience.
- Upgraded all server and client ISMs to Installshield 2023 R2.

## Resolved Security Advisories v3.5

- No security advisories exist.

## Resolved Technical Advisories v3.5

### Advanced Threat Prevention v3.5

- No technical advisories exist.

### Firewall and Web Protection v3.5

- No technical advisories exist.

## Encryption v3.5

- A message no longer displays and prompts for restart as a result of a Windows 10 upgrade after running WSDeactivate. [DDPC-12755]
- Verbose logging no longer decreases encryption and decryption sweep speed. [DDPC-13159]
- An issue resulting in accessible files if Fast User Switching is enabled is resolved. [DDPC-13161]
- An issue resulting in intermittent computer crash for Active Directory users is resolved. [DDPC-13164, DDPSUS-3138]
- Activation workflows for computers activated against Security Management Servers leveraging Active Directory Federation Services is now improved. [DDPC-13201]
- A database issue resulting in intermittent computer crashes is resolved. [DDPSUS-3105]

## Pre-boot Authentication v3.5

- The Legacy boot mode PBA environment now displays the correct URL for Dell Support. [DDPC-12536]
- Windows now loads as expected after activating and logging into the PBA using a smart card. [DDPC-13126]

## SED Manager v3.5

- Smart card authentication functions as expected for computers protected by SED Manager after upgrading previous versions of Endpoint Security Suite Enterprise. [DDPC-13149]
- A rare issue resulting in encryption status not displaying in the Data Security Console after a reboot is resolved. [DDPC-13101]

## Full Disk Encryption v3.5

- Smart card authentication functions as expected for computers protected by Full Disk Encryption after upgrading previous versions of Endpoint Security Suite Enterprise. [DDPC-13149]

## BitLocker Manager v3.5

- BitLocker Manager no longer requests for a new PIN when encryption is removed from a drive. [DDPC-12110]
- BitLocker Manager's PIN Rotation now receives policy updates as expected. [DDPC-13075]
- BitLocker Manager's PIN Rotation now uses local time zone per computer. [DDPC-13076]
- BitLocker Manager's PIN Rotation workflow has been hardened. [DDPC-13078]

## Technical Advisories v3.5

### Advanced Threat Prevention v3.5

- No technical advisories exist.

### Firewall and Web Protection v3.5

- No technical advisories exist.

### Encryption Client v11.5

- No technical advisories exist.

### Pre-boot Authentication v3.5

- No technical advisories exist.

### SED Manager v3.5

- No technical advisories exist.

### Full Disk Encryption v3.5

- No technical advisories exist.

### BitLocker Manager v3.5

- Computers running Windows 11 21H1 and protected by BitLocker Manager currently cannot upgrade to Windows 11 22H2. As a workaround, stop the following Dell services then upgrade to Windows 11 22H2:

- DellMgmtAgent
- DellMgmtLoader [DDPC-13324]

## New Features and Functionality v3.4

- Endpoint Security Suite Enterprise now supports Multi-disk encryption.
- Advanced Threat Prevention v2.1.1585 has been integrated into Endpoint Security Suite Enterprise v3.4.
- **NOTE:** The Advanced Threat Prevention component of Endpoint Security Suite Enterprise is End of Maintenance with this release. For more information, see KB article [128563](#).
- Diagnostic Info now collects logging and troubleshooting data for Absolute Device and Data Security.
- DiagnosticInfo now collects logging and troubleshooting data for Dell Threat Defense.
- Dell Encryption now supports Windows 10 LTSC 2021.

## Resolved Security Advisories v3.4

- The log4net component in the Data Security Uninstaller has been updated. [DDPC-13088]

## Resolved Technical Advisories v3.4

### Advanced Threat Prevention v3.4

- No technical advisories exist.

### Firewall and Web Protection v3.4

- No technical advisories exist.

### Encryption v3.4

- The Dell End User License Agreement (EULA) has been updated to 2022 for all products and pages. [DDPC-12052]
- The **Reboot Now** prompt in the notification area now functions as expected for Encryption on Server Operating Systems. [DDPC-12874]
- The Dell Encryption vault file, a secure container that stores policy and key information, is now located in C:\ProgramData\Dell\Dell Data Protection\Encryption\Vault. [DDPC-13005]
- Child installers and master installers are now install the Encryption Management Agent components to C:\Program Files\Dell\Client Security Framework. [DDPC-13006]
- An issue resulting in computer crash and incorrect designation of internal drives as external on computers protected by Encryption External Media is resolved. [DDPSUS-3109]
- An issue resulting in computer crash after updating Endpoint Security Suite Enterprise to v3.4 and applying Encryption External Media policies is resolved. [DDPSUS-3123]

### Pre-boot Authentication v3.4

- If a Windows Feature update is blocked, the DellAgent.log file now includes entries detailing the block. [DDPC-12598]
- An issue resulting in unprinted outputs due to Caps Lock being enabled is resolved. [DDPC-13084]

## SED Manager v3.4

- During uninstallation, SED Manager filter drivers are now properly unmounted. [DDPC-12461, DDPSUS-2925, DDPSUS-3054]
- A rare issue resulting in encryption status not displaying in the Data Security Console after a reboot is resolved. [DDPC-13101]

## Full Disk Encryption v3.4

- An issue resulting in delays in the Pre-boot Authentication environment when using the TB16 dock is resolved. [DDPC-8147, DDPSUS-1923]
- During uninstallation, Full Disk Encryption filter drivers are now properly unmounted. [DDPC-12461, DDPSUS-2925, DDPSUS-3054]
- An issue resulting in unprinted outputs due to Caps Lock being enabled is resolved. [DDPC-13084]
- A rare issue resulting in encryption status not displaying in the Data Security Console after a reboot is resolved. [DDPC-13101]

## BitLocker Manager v3.4

- An inventory issue resulting in incorrect encryption percentages displaying in the Security Management Server is resolved. [DDPC-13071, DDPSUS-3089]
- An issue resulting BitLocker Manager interpreting policies from the Security Management Server as invalid is resolved. [DDPC-13070, DDPC-13091, DDPSUS-3096]
- An issue resulting in failure to apply policy properly because the LastAppliedPolicy registry value was misspelled is resolved. [DDPC-13084]
- A rare issue resulting in encryption status not displaying in the Data Security Console after a reboot is resolved. [DDPC-13101]

## Technical Advisories v3.9

### Advanced Threat Prevention v3.9

- No technical advisories exist.

### Firewall and Web Protection v3.9

- No technical advisories exist.

### Encryption Client v11.9

- The Symlink is not getting detected in the C:\custom folder of your system. [DDPC-13822]

### Pre-boot Authentication v3.9

- No technical advisories exist.

### SED Manager v3.9

- No technical advisories exist.

## Full Disk Encryption v3.9

- No technical advisories exist.

## BitLocker Manager v3.9

- No technical advisories exist.

## New Features and Functionality v3.3

- Dell Encryption on Server Operating Systems now supports Windows Server 2022 Standard and Datacenter editions.
- Client Firewall and Web Protection v10.7.0.141 has been integrated into Endpoint Security Suite Enterprise v3.3.
- DiagnosticInfo collects additional information including:
  - Class filter drivers in use
  - Dell Data Security product versions
  - Hardware serial numbers
  - Installed servers and their availability status
  - Windows build versions
  - Logs for the following:
    - Component-Based Servicing
    - Installed applications
    - Deployment Image Servicing and Management
    - Security Management Server installation
    - Server Configuration Tool and server migration
    - Threat Defense
    - VMware Carbon Black
    - Windows Updates

## Resolved Security Advisories v3.3

- Client Firewall and Web Protection v10.7.0.141 resolves agent vulnerabilities detailed in CVE-2021-31854 and CVE-2022-0166. For more information, see <https://kc.mcafee.com/corporate/index?page=content&id=SB10378>. [DDPC-13008]

## Resolved Technical Advisories v3.3

### Advanced Threat Prevention v3.3

- No technical advisories exist.

### Firewall and Web Protection v3.3

- No technical advisories exist.

### Encryption v3.3

- The Data Security Uninstaller now properly populates the *Device Server URL* field in the uninstallation process. [DDPC-12692]
- DiagnosticInfo now identifies mishandled Command Line entries when run with the */silent* option. [DDPC-10244]
- Uninstalling Dell Encryption now removes all Windows 10 Feature Update supporting folders as expected. [DDPC-12039]

- An issue resulting in an errant directory displaying in Dell Encryption logs is resolved. [DDPC-12854]
- The Data Security Uninstaller now properly populates the Device Server URL field in the uninstallation process. [DDPC-12692]
- Registry modifications are no longer required after installing Dell Encryption using the master installer and using Windows Hello for Business authentication. [DDPC-12885]
- Dell Encryption policy updates initiated in the Security Management no longer triggers errant updates to Client Security Framework features. [DDPC-12886, DDPSUS-3061]

## Pre-boot Authentication v3.3

- An issue resulting in delays in the Pre-boot Authentication environment when using the TB16 dock is resolved. [DDPC-8147, DDPSUS-1923]
- An issue resulting in a freeze in the The Pre-boot Authentication environment is resolved. [DDPC-12758]
- A driver issue resulting in network cards being unavailable in the Pre-boot Authentication environment is resolved. [DDPC-12835, DDPSUS-2959, DDPSUS-2977]

## SED Manager v3.3

- No technical advisories exist.

## Full Disk Encryption v3.3

- An issue resulting in delays in the Pre-boot Authentication environment when using the TB16 dock is resolved. [DDPC-8147, DDPSUS-1923]
- An issue resulting in a freeze in the The Pre-boot Authentication environment is resolved. [DDPC-12758]
- A driver issue resulting in network cards being unavailable in the Pre-boot Authentication environment is resolved. [DDPC-12835, DDPSUS-2959, DDPSUS-2977]

## BitLocker Manager v3.3

- If initialization of BitLocker fails, BitLocker Manager is now engaged to reinitialize encryption. [DDPC-12826]

# Technical Advisories v3.3

## Advanced Threat Prevention v3.3

- No technical advisories exist.

## Firewall and Web Protection v3.3

- No technical advisories exist.

## Encryption Client v11.3

- The notification that prompts users to restart after installing Dell Encryption on a server operating system does not currently restart the computer. As a workaround, manually restart the computer. [DDPC-12874]
- Windows Hello for Business authentication requires the following registry key if you install Endpoint Security Suite Enterprise using the child installers:

```
HKLM\SYSTEM\CurrentControlSet\Services\DellMgmtAgent\Parameters
REG_SZ: NoDDPETray
```

Value: 0 [DDPC-13001]

- When installed with the master installer, the directory in which Client Security Framework components are installed does not currently align with the directory created during installation with the child installers. [DDPC-13006]

## Pre-boot Authentication v3.3

- No technical advisories exist.

## SED Manager v3.3

- No technical advisories exist.

## Full Disk Encryption v3.3

- No technical advisories exist.

## BitLocker Manager v3.3

- No technical advisories exist.

## New Features and Functionality v3.2

- Firewall and Web Protection is now supported with Windows 11 v21H2.
- Firewall and Web Protection is now supported with Windows 10 v21H2.
- Dell Encryption now displays the following message in the notification area if a user attempts to upgrade to an unsupported version of Windows: **Dell Encryption is preventing an upgrade to an unsupported version of Windows. Contact Dell ProSupport for Software for assistance.**
- BitLocker Manager now supports policy-based PIN expiration. This name of this policy is *User PIN lifetime*. By default, BitLocker Manager PINs expire after 90 days of use. This policy requires the Security Management Server v11.2 or later.

## Resolved Security Advisories v3.2

- No security advisories exist.

## Resolved Technical Advisories v3.2

### Advanced Threat Prevention v3.2

- No technical advisories exist.

### Firewall and Web Protection v3.2

- No technical advisories exist.

### Encryption v3.2

- The Data Security Uninstaller now properly populates the *Device Server URL* field in the uninstallation process. [DDPC-12692]

- Dell Encryption now activates as expected against a Security Management Server with the Passwordless Authentication policy disabled when users log in with local credentials. [DDPC-12707]
- An issue that is caused by hardlink mapping mishandling resulting in high CPU use on computers that are protected by Dell Encryption is resolved. [DDPC-12407, DDPSUS-2983]
- Encryption External Media now honors policies more than 500 lines. [DDPC-12553, DDPSUS-2980]
- Files in OneDrive folders now decrypt as expected. [DDPC-12444]
- An issue resulting in computer crash if abnormally large amounts of data were being processed by the file I/O buffer is resolved. [DDPC-12746, DDPSUS-3021]
- An issue resulting in computer crash due to coinciding high file transmission rates and file lock requests is resolved. [DDPC-12753, DDPSUS-3025]
- An issue resulting in locked user accounts due to incorrect credentials being processed during Fast User Switching is resolved. [DDPC-12780, DDPSUS-3026]

## Pre-boot Authentication v3.2

- An issue resulting in delays in the Pre-boot Authentication environment is resolved. [DDPC-12758]

## SED Manager v3.2

- No technical advisories exist.

## Full Disk Encryption v3.2

- An issue resulting in delays in the Pre-boot Authentication environment is resolved. [DDPC-12758]

## BitLocker Manager v3.2

- No technical advisories exist.

# Technical Advisories v3.2

## Advanced Threat Prevention v3.2

- No technical advisories exist.

## Firewall and Web Protection v3.2

- No technical advisories exist.

## Encryption Client v11.2

- After running WSDDeactivate on a computer, a message incorrectly displays and prompts for restart as a result of a Windows 10 upgrade. This message should be ignored. [DDPC-12755]
- If a computer crash occurs before Dell Encryption activates, the vault is corrupted and automatic repair is not attempted. As a workaround, run WSDDeactivate on the affected computer. [DDPC-12779]
- WinPE run on Windows 11 does not automatically mount the target disk. As a workaround, use the following steps:
  1. Type **x** and press Enter to exit to Command line.
  2. To open the Diskpart utility, type **diskpart** and press Enter.
  3. Type **list vol** and press Enter to list the available volumes.
  4. Type **select volume x** where **x** is the volume number.
  5. Use the **assign** command to assign a drive letter to that volume. For example, `assign C` and press Enter.

6. Type **exit** to leave Diskpart.

The target disk is mounted, and recovery can be performed. [DDPC-12848]

## Pre-boot Authentication v3.2

- Dell platform BIOS from mid-2020 and earlier may not align with EFI-based certificate handling recently updated by Microsoft. This may result in the Dell Pre-boot Authentication environment failing to boot. To work around this incompatibility, ensure that the BIOS on your computer is updated. For more information, see this KB article [129365](#). [DDPC-12834]

## SED Manager v3.2

- No technical advisories exist.

## Full Disk Encryption v3.2

- Dell platform BIOS from mid-2020 and earlier may not align with EFI-based certificate handling recently updated by Microsoft. This may result in the Dell Pre-boot Authentication environment failing to boot. To work around this incompatibility, ensure that the BIOS on your computer is updated. For more information, see this KB article [129365](#). [DDPC-12834]

## BitLocker Manager v3.2

- No technical advisories exist.

## New Features and Functionality v3.1

- Installs and upgrades to Windows 11 and Windows 10 21H2 are not blocked with Endpoint Security Suite Enterprise v3.1. Dell does not support preview versions of operating systems and using unsupported operating systems may result in data loss. Go to KB article [156050](#) for additional Information on Windows operating system compatibility.
- The Encryption Management Agent now automatically decrypts then encrypts drives protected by BitLocker Manager when an algorithm is changed from the default in the Dell Server. For more information, see the following in logs:  
**Encryption method is changed. Start decryption and after that encryption with new method.**  
**Note:** Computers encrypted with [BitLocker for OEM](#) will be automatically decrypted and re-encrypted after an update to or newer. You may observe performance impacts during the re-encryption process.
- BitLocker Manager now rotates the RecoveryPassword protector on computers after the password is requested in the Self-Service Recovery Portal in the Dell Server or through the Management Console.

## Resolved Security Advisories v3.1

- The icon and verbiage for failed login attempts in the PBA environment have been aligned. [DDPC-12662]

## Resolved Technical Advisories v3.1

### Advanced Threat Prevention v3.1

- No technical advisories exist.

## Firewall and Web Protection v3.1

- No technical advisories exist.

## Encryption v3.1

- The Encryption Management Agent now creates folders for use with Windows 10 Feature Updates only for the Dell Encryption solutions installed. [DDPC-12038]
- An issue resulting in corruption of hard link files after new data is written is resolved. [DDPC-12079]
- Files in OneDrive folders now decrypt as expected. [DDPC-12444]
- Dell Encryption now uninstalls properly using the Data Security Uninstaller and the **Encryption Removal Agent - Download Keys from Server** option. [DDPC-12520]
- The Data Security Uninstaller now removes all components of the master installer as expected. [DDPC-12521]
- An issue resulting in a customer-facing PIN request prompt after a policy change to decrypt a drive was consumed is resolved. [DDPC-12539]
- Interactive user detection no longer blocks all removable media if multiple users rapidly log in and out of the computer. [DDPC-12561]
- The child installers now extract from the master installer as expected on computers that have the Security Framework installed. [DDPC-12571]
- The Encryption Management Agent now provides the following error when unsupported Windows Feature Updates fail to install: **Dell Encryption is preventing an upgrade to an unsupported version of Windows. Contact Dell ProSupport for Software for assistance.** [DDPC-12597]
- A rare issue resulting in partial file corruption with files containing hard link based on their naming convention in tandem with rapid superceding updates is resolved. [DDPC-12693]

## Pre-boot Authentication v3.1

- No technical advisories exist.

## SED Manager v3.1

- No technical advisories exist.

## Full Disk Encryption v3.1

- Computers protected by Full Disk Encryption now decrypt as expected when a removable drive is present. [DDPC-12494]

## BitLocker Manager v3.1

- PIN prompts no longer display when decrypting a drive protected by BitLocker Manager after selecting the *Use no additional unlock methods* option. [DDPC-12539]

# Technical Advisories v3.1

## Advanced Threat Prevention v3.1

- No technical advisories exist.

## Firewall and Web Protection v3.1

- No technical advisories exist.

## Encryption Client v11.1

- The following error may display if you inspect a policy that exceeds nine KB of data:  
**Invalid Value for 100** [DDPSUS-2980]
- When changing the password for removable media protected by Encrypted External Media, **Password Accepted** displays incorrectly. [DDPC-12721]
- The Data Security Console does not currently display information for protected removable media. [DDPC-12722]
- The Data Security Uninstaller currently does not uninstall properly if using the **Encryption Removal Agent - Import Keys from a File** option. As a workaround, use the **Encryption Removal Agent - Download Keys from Server** option, or uninstall by running the Dell Encryption child installer using the predownloaded key. [DDPC-12723]
- System Data Encryption validation failures on boot do not currently cause a computer crash as expected. An infinite boot logo displays instead. A [System Data Encryption recovery](#) should be performed for resolution. [DDPC-12725]

## Pre-boot Authentication v3.1

- External smart card readers do not currently function properly when used in the Pre-Boot Authentication environment on Dell models that are generated in calendar year 2020 or later due to a change in the BIOS of these computers. [DDPC-12730]

## SED Manager v3.1

- No technical advisories exist.

## Full Disk Encryption v3.1


- No technical advisories exist.

## BitLocker Manager v3.1

- No technical advisories exist.

## New Features and Functionality v3.0

- Firewall and Web Protection v10.7.0.1045.11 has been integrated into Endpoint Security Suite Enterprise v3.0.
- Web Protection now supports Chromium Edge.
- The Kioxia BG4 NVMe is now supported with SED Manager.
- Dell Encryption now supports Windows Hello authentication.
- The interactive installer now includes fields for non-standard ports for the Encryption Management Agent's communication with the Core Server and Security Server.

**Dell Server Setup** 

Please provide the following information about your Dell Server.

Please specify the fully qualified host name of the managing On-Prem Dell Server. This server will be used to activate new users and retrieve their security policies. For example: servername.domain.com

On-Prem Dell Server Name

Core Server Port  Security Server Port

Please verify the fully qualified URL of the Dell Server. This servlet will be used to activate new users.

Dell Server URL

InstallShield

## Resolved Security Advisories v3.0

- The Endpoint Security Suite Enterprise signing certificate is updated.

## Resolved Technical Advisories v3.0

### Advanced Threat Prevention v3.0

- No technical advisories exist.

### Firewall and Web Protection v3.0

- The Web Protection and Client Firewall SDK has been updated. This change ensures compatibility with new Cylance and Dell signing certificates and affects that are protected by Endpoint Security Suite Enterprise v2.9 and older protected by Dell Encryption v10.10 and newer or Cylance v154x and newer. [DDPC-12164]

### Encryption v3.0

- The Encryption External Media service now starts as expected on computers that do not have Dell Encryption installed. [DDPC-12101, DDPC-12196]
- An issue resulting in double-encrypted files with superseding file versions is resolved. [DDPC-12302]
- When installing BitLocker Manager, Dell Encryption, and Encryption External Media using the suite installer, Dell Encryption now installs in the correct configuration. [DDPC-12346]
- External Media Encryption's installation description is updated to clarify functionality of the product. [DDPC-12367, DDPC-12368]
- Copyrights are updated. [DDPC-12378]
- With a global shift to inclusive language, several terms and expressions have been updated. [DDPC-12398]

## Pre-boot Authentication v3.0

- No technical advisories exist.

## SED Manager v3.0

- The Encryption Management Agent now performs additional checks during installation and uninstallation to detect if the computer was rebooted. This prevents an inaccessible boot drive. [DDPC-12390, DDPSUS-2925]

## Full Disk Encryption v3.0

- An issue that is caused by boot sector mapping resulting in the inability to boot into the PBA on a computer that is protected by Dell Encryption is resolved. [DDPC-12303]
- When enabling Full Disk Encryption, the script that is generated to perform the tasks is now signed by Dell's signing certificates, allowing for approval based on script instead of script hash. [DDPC-12320]
- The Encryption Management Agent now performs additional checks during installation and uninstallation to detect if the computer was rebooted. This prevents an inaccessible boot drive. [DDPC-12390, DDPSUS-2925]

## BitLocker Manager v3.0

- When installing BitLocker Manager, Dell Encryption, and Encryption External Media using the suite installer, Dell Encryption now installs in the correct configuration. [DDPC-12346]
- BitLocker Manager no longer prompts for new PIN input for unrelated policy updates. [DDPC-12415, DDPSUS-2937]
- An issue resulting in multiple failures to cancel user dialogue for the Encryption of Fixed Drives policy on computers protected by BitLocker Manager is resolved. [DDPC-12435]

## Technical Advisories v3.0

### Advanced Threat Prevention v3.0

- No technical advisories exist.

### Firewall and Web Protection v3.0

- No technical advisories exist.

### Encryption Client v11.0

- The Dell Encryption Removal agent may not decrypt hydrated OneDrive files. To decrypt these files, either unlink OneDrive, or decrypt these files before uninstall through policy. [DDPC-12444]
- WSDeactivate currently displays a non-functional progress bar. [DDPC-12502]
- To enable Windows Hello authentication, computers must have a registry key set:  
HKLM\SYSTEM\CurrentControlSet\Services\DellMgmtAgent\Parameters  
REG\_SZ: NoDDPETray  
Value: 0 [DDPC-12511]
- External Media Encryption v11.0 cannot currently be upgraded to Endpoint Security Suite Enterprise. To upgrade to Encryption Enterprise, uninstall Encryption External Media and install Endpoint Security Suite Enterprise. [DDPC-12544]

## Pre-boot Authentication v3.0

- Computers leveraging Microsoft-based accounts and protected by SED Manager with the *Sync Users at PBA Activation* policy enabled currently cannot use single sign-on after rebooting. As a workaround, at the Windows sign-in screen, select **Other User** and log in using your user name and password. Single sign-on is functional for the local users and Active Directory domain users if the system is domain-joined. [DDPC-12089]

## SED Manager v3.0

- Computers leveraging Microsoft-based accounts and protected by SED Manager with the *Sync Users at PBA Activation* policy enabled currently cannot use single sign-on after rebooting. As a workaround, at the Windows sign-in screen, select **Other User** and log in using your user name and password. Single sign-on is functional for the local users and Active Directory domain users if the system is domain-joined. DDPC-12089

## Full Disk Encryption v3.0

- Computers leveraging Microsoft-based accounts and protected by Full Disk Encryption with the *Sync Users at PBA Activation* policy enabled currently cannot use single sign-on after rebooting. As a workaround, at the Windows sign-in screen, select **Other User** and log in using your user name and password. Single sign-on is functional for the local users and Active Directory domain users if the system is domain-joined. [DDPC-12089]
- Computers protected by Full Disk Encryption do not currently decrypt properly if removable media is present. As a workaround, disconnect all removable media before removing Full Disk Encryption. [DDPC-12494]

## BitLocker Manager v3.0

- No technical advisories exist.

## New Features and Functionality v2.9

- Endpoint Security Suite Enterprise is now supported with Windows 10 v20H2 (October 2020 Update/20H2).
- Advanced Threat Prevention is now supported with Windows 10 v20H2 (October 2020 Update/20H2).
- Firewall and Web Protection is now supported with Windows 10 v20H2 (October 2020 Update/20H2).
- Advanced Threat Prevention v2.1.1565.1 has been integrated into Endpoint Security Suite Enterprise v2.9.
- Firewall and Web Protection v10.7.0.130 has been integrated into Endpoint Security Suite Enterprise v2.9.
- Endpoint Security Suite Enterprise now supports disks with 4k sector formats.
- The Dell Encryption PBA now supports Brazilian ABNTv2 keyboards.

## Resolved Security Advisories v2.9

- No security advisories exist.

## Resolved Technical Advisories v2.9

### Advanced Threat Prevention v2.9

- If installing Endpoint Security Suite Enterprise interactively, the Advanced Threat Prevention and Web Protection and Firewall component selections can now be selected independently. [DDPC-12114]

## Firewall and Web Protection v2.9

- Web Protection and Firewall can now be installed during a Dell Encryption upgrade. [DDPC-11999]
- When updating Endpoint Security Suite Enterprise interactively, Firewall and Web Protection now upgrades as expected. [DDPC-12022]

## Encryption v2.9

- If a duplicate user attempts to activate with Deferred Activation, the following message displays: **Activation Failed & the user is already activated on this computer.** [DDPC-7456]
- An issue resulting in a memory leak due to file name length is resolved. [DDPC-7569]
- An issue resulting in the Dell DiagnosticInfo utility detecting a client operating system as a server operating system is resolved. [DDPC-11762]
- Encryption External Media now displays on the component selection screen when upgrading Dell Encryption. [DDPC-11998]
- An issue resulting in the inability to use smart card login from a remote location is resolved. [DDPC-12068, DDPC-12290, DDPSUS-2821]
- An issue resulting in incomplete feature installation when installing with the master installer using command-line or interactively is resolved. [DDPSUS-2870, DDPSUS-2908, DDPC-12090]
- Block SID functionality with multiple disks is improved. [DDPC-12183]
- An issue resulting in failed activation of Encryption on server operating systems is resolved. [DDPC-12115]
- An issue resulting in inaccessible data and unresponsive Start menu after Windows 10 Feature Update failure is resolved. [DDPC-12121, DDPSUS-2844, DDPSUS-2854]
- An issue resulting in inaccessible data due to mishandling of System Disk Encryption keys is resolved. [DDPC-12123, DDPSUS-2850]
- An issue resulting in encryption sweep failures on computers protected by Dell Encryption and VMWare Carbon Black Cloud or many anti-virus solutions is resolved. [DDPC-12205, DDPSUS-2883]
- An issue resulting in failed provisioning for computers protected by Dell Encryption is resolved. [DDPC-12289, DDPSUS-2893, DDPSUS-2906]
- An issue resulting in nonfunctional shortcuts after completing an encryption sweep is resolved. [DDPC-12265]
- An issue resulting in failed Dell Encryption reactivation due to a corrupt System Disk Encryption key vault is resolved. [DDPC-12255]
- An issue resulting in failed Windows 10 Feature Updates and computer crash due to a corrupt System Data Encryption key vault is resolved. [DDPSUS-2862]
- An issue resulting in inaccessible files due to System Data Encryption key handling is resolved. [DDPSUS-2867]

## Pre-boot Authentication v2.9

- The Pre-boot Authentication environment now displays the correct version in the *About* section. [DDPC-11995]

## SED Manager v2.9

- No technical advisories exist.

## Full Disk Encryption v2.9

- An issue resulting in incomplete feature installation when installing with the master installer using command-line or interactively is resolved. [DDPSUS-2870, DDPSUS-2908, DDPC-12090]

## BitLocker Manager v2.9

- An issue resulting in incomplete feature installation when installing with the master installer using command-line or interactively is resolved. [DDPSUS-2870, DDPSUS-2908, DDPC-12090]

# Technical Advisories v2.9

## Advanced Threat Prevention v2.9

- No technical advisories exist.

## Firewall and Web Protection v2.9

- No technical advisories exist.

## Encryption Client v10.9

- Devices with multiple disks may not display the status of disks immediately when selecting the Encryption tab in the Data Security Console . [DDPC-11346]
- If Policy-Based Encryption is installed before the Encryption Management Agent, computer crash may occur. This issue is caused by failure to load the encryption Sleep driver which is used to manage the PBA environment. As a workaround, use the master installer or ensure that Policy-Based Encryption is installed after the Encryption Management Agent. [DDPC-12239]

## Pre-boot Authentication v2.9

- No technical advisories exist.

## SED Manager v2.9

- No technical advisories exist.

## Full Disk Encryption v2.9

- No technical advisories exist.


## BitLocker Manager v2.9

- No technical advisories exist.

# New Features and Functionality v2.8

- The Data Security console now displays the encryption technology in use.
- Full Disk Encryption can now be selected in the feature selection screen of the suite installer.
- Full Disk Encryption now writes disk encryption percentage to the registry at the following location: HKLM\SYSTEM\CurrentControlSet\Services\DellMgmtAgent\Parameters
- The DiagnosticInfo utility is now installed when the Encryption Management agent is installed.
- The DiagnosticInfo utility now queries additional registry entries.
- Advanced Threat Prevention v2.0.1561.2 has been integrated into Endpoint Security Suite Enterprise v2.8.
- The suite installer's detection of UEFI and Legacy boot modes is improved.
- BitLocker Manager now displays drive labels and letter assignment.
- In the PBA environment, the network icon now displays with a yellow slash if the PBA detects a network but the network adapter cannot be configured.
- The Dell Encryption WinPE recovery environment verbiage is updated for Self-Encrypting Drives and drives that are protected by Full Disk Encryption.

- The DiagnosticInfo utility now displays the following prompt for Personally Identifiable Information:



- Full Disk Encryption and SED Manager now support the following platforms:
  - Latitude 9510
  - Latitude 9510 2-in-1
  - XPS 15 9500

## Resolved Security Advisories v2.8

- Additional files used during the installation of Endpoint Security Suite Enterprise are now signed. [DDPC-6827]
- Dell has released additional fixes for an improper access control vulnerability in Endpoint Security Suite Enterprise (CVE-2020-5358). See the Dell Security Advisory (DSA-2020-113) at [Dell Security Advisory](#) for affected products, versions, and additional information. [DDPC-11877]

## Resolved Technical Advisories v2.8

### Advanced Threat Prevention v2.8

- No technical advisories exist.

### Firewall and Web Protection v2.8

- When updating Endpoint Security Suite Enterprise interactively, Firewall and Web Protection now upgrades as expected. [DDPC-12022]

### Encryption v2.8

- Custom Support Dialog is now properly consumed against a Security Server with nondefault ports when set. [DDPC-8060]
- Deferred activation now activates properly against a Security Server with nondefault ports. [DDPSUS-2762]
- Unsupported languages no longer display in help directories after installing Endpoint Security Suite Enterprise. [DDPC-10746]
- Reboot prompts no longer display on the login screen after decryption. [DDPC-11940]

## Pre-boot Authentication v2.8

- When using Recovery Questions to log in through the PBA, the password reset prompt now only appears for the first 90 seconds after login. [DDPC-11671]
- Right-clicking the username, password, smart card, pin or recovery answer field in the PBA no longer yields a menu. [DDPC-11795]
- An issue resulting in third-party authentication providers being disabled by default is resolved. [DDPC-12057, DDPSUS-2818]

## SED Manager v2.8

- No technical advisories exist.

## Full Disk Encryption v2.8

- Encryption status now properly displays the status of all encryption technologies in the Data Security Console and for computers that are protected by multiple encryption technologies. [DDPC-11133]

## BitLocker Manager v2.8

- Computers that are protected by Dell Encryption no longer fail PIN creation for BitLocker Manager. [DDPC-10949]
- If the TPM is unmanaged, requiring BitLocker Manager to use the TPM or TPM and PIN now writes the following error to logs: **TPM manager is disabled, therefore TPM-based protector is not allowed!** [DDPC-11960]

## Technical Advisories v2.8

### Advanced Threat Prevention v2.8

- No technical advisories exist.

### Firewall and Web Protection v2.8

- No technical advisories exist.

### Encryption Client v10.8

- During reboot and shutdown, a .NET error may display due to simultaneous shutdown of a Dell Encryption service and Windows WMI service. [DDPC-12054, DDPC-12098, DDPSUS-2807, DDPSUS-2812]
- In rare scenarios, the DiagnosticInfo utility does not collect all logs after Command-line installation and failed exportation errors display in the Command-line window. [DDPC-12090]
- Administrators are currently unable to change disk encryption keys' escrow location after encryption sweeps are complete. [DDPC-12100]

### Pre-boot Authentication v2.8

- No technical advisories exist.

### SED Manager v2.8

- No technical advisories exist.

## Full Disk Encryption v2.8

- No technical advisories exist.

## BitLocker Manager v2.8

- No technical advisories exist.

## New Features and Functionality v2.7

- Windows 10 v2004 (May 2020 Update/20H1) does not support 32-bit architecture. For more information, see <https://docs.microsoft.com/windows-hardware/design/minimum/minimum-hardware-requirements-overview>.
- Endpoint Security Suite Enterprise is now supported with Windows 10 v2004 (May 2020 Update/20H1).
- Advanced Threat Prevention is now supported with Windows 10 v2004 (May 2020 Update/20H1).
- Firewall and Web Protection is now supported with Windows 10 v2004 (May 2020 Update/20H1).
- Advanced Threat Prevention v2.0.1241.1 has been integrated into Endpoint Security Suite Enterprise v2.7.
- Firewall and Web Protection v10.7.0.812.4 has been integrated into Endpoint Security Suite Enterprise v2.7. This version contains fixes for CVE-2020-7250, CVE-2020-7255, CVE-2020-7257 and others. For more information, see <https://kc.mcafee.com/corporate/index?page=content&id=SB10309>.
- Firewall and Web Protection now requires the following Command-line installation syntax:

- **\Threat Protection\EndPointSecurity**

The following example installs the Firewall and Web Protection with default parameters (silent mode, install Client Firewall, and Web Protection, override the Host Intrusion Prevention, no content update, no settings saved with logs in C:\ProgramData\Dell\Dell Data Protection).

```
".\Threat Protection\EndPointSecurity\EPsetup.exe" ADDLOCAL="fw,wc" /override"hips" /nocontentupdate /qb! /L*v"C:\ProgramData\Dell\Dell Data Protection\Installer Logs\"
```

Then:

- **\Threat Protection\ThreatProtection\WinXXR**

- The following example installs the client with default parameters (suppress the reboot, no dialogue, no progress bar, no entry in the Control Panel Programs list).

```
"Threat Protection\ThreatProtection\WinXXR\DellThreatProtection.msi" /qn REBOOT=ReallySuppress ARPSYSTEMCOMPONENT=1
```

Then:

- **\Threat Protection\SDK**

- The following command line loads the certificate default parameters.

```
"Threat Protection\SDK\EnsMgmtSdkInstaller.exe" -LoadCert >"C:\ProgramData\Dell\Dell Data Protection\Installer Logs\McAfeeSDKInstallerBeforeEndPoint.log"
```

Then:

- **\Threat Protection\SDK**

- The following example installs the SDK.

```
"Threat Protection\SDK\EnsMgmtSDKInstaller.exe" -InstallSDK -RemoveRightClick -RemoveMcTray >> "<OUTPUTDIRECTORY>\McAfeeSDKInstallerAfterEndPoint.log"
```

- The Dell DiagnosticInfo utility now collects diagnostic and logging information for Firewall and Web Protection to assist with troubleshooting and diagnostics.
- The Dell DiagnosticInfo utility logging is improved.
- Boot order logging is improved.
- A new RAID controller driver is added to the Dell Encryption Recovery WinPE environment. This enables recovery of disks in newer platforms configured in RAID ON mode.
- Dell Encryption performs a re-analysis of encrypted volumes on key backups to ensure policy is correctly applied to the entire drive. This will appear as a re-sweep of encryption of the disk, which may lead to a temporary increase in system resource use.


- Dell's DiagnosticInfo utility now queries additional registry entries for more comprehensive results.
- Endpoint Security Suite Enterprise can now prompt the user to reboot their computer after the Encryption Removal Agent finishes its final state in the decryption process. This prompt can be disabled by configuring a registry value or enabling *Force Reboot on Update* in the Management Console. When *Force Reboot on Update* is enabled in the Management Console, the following registry entry is created.

HKLM\Software\Dell\Dell Data Protection

"ShowDecryptAgentRebootPrompt"=DWORD

1 = enabled (displays prompt)

0 = disabled (hides prompt)



- Full Disk Encryption and SED Manager now support the following platforms:
  - Latitude 5411
  - Latitude 5511
  - Latitude 9410 2-in-1
  - OptiPlex 5480 All-in-One
  - OptiPlex 7480 All-in-One
  - OptiPlex 7780 All-in-One
  - Precision 3440
  - Precision 3551
  - Precision 7550
  - Precision 7750
  - XPS 15 9500

## Resolved Technical Advisories v2.7

### Advanced Threat Prevention v2.7

- The Advanced Threat Prevention child installers properties now display the correct product name. [DDPC-11557, DDPC-11794]
- The Data Security Uninstaller now uninstalls Advanced Threat Prevention as expected. [DDPC-11728]

### Firewall and Web Protection v2.7

- Direct-access traffic is no longer blocked by Client Firewall, after upgrading from Web Protection and Client Firewall v10.5.4 to v10.7.0
- The Web Control pop-up message is now positioned properly, and the information is readable.
- The Firewall and Web Protection tile in the Data Security Console now displays the correct color scheme. [DDPC-11725]

### Encryption v2.7

- Dell Encryption files are now properly cleaned up during uninstallation. [DDPC-866, DDPC-2548, DDPC-11094, DDPC-11497]
- An issue resulting in the inability to decrypt and uninstall if multiple System Data Encryption keys were present in the registry is resolved. [DDPC-2428, DDPC-11662, DDPSUS-2208]

- An issue resulting in ERR files after changing policy to Single Overwrite Pass during a System Data Encryption sweep is resolved. [DDPC-2751, DDPC-5038, DDPC5148, DDPC-7708, DDPC-8019, DDPC-8116]
- A rare issue resulting in the DiagnosticInfo utility failing to generate a temporary directory for data collection before packaging is resolved. [DDPC-4981]
- The reboot prompt no longer displays off-screen after a policy requiring a reboot is updated. [DDPC-5374, DDPC-5376]
- The Data Security Uninstaller now removes all Dell Encryption registry entries as expected. [DDPC-5410]
- An issue resulting in installation files being improperly flagged as threats is resolved. [DDPC-6827, DDPC-11573, DDPC-11844, DDPC-11846]
- The Data Security Uninstaller now accepts upper case and lower case entries of the *silent* Command-line switch (*Silent* and *silent*). [DDPC-11092]
- Endpoints no longer prompt for authentication multiple times when configured in Deferred Activation mode. [DDPC-11279]
- An issue resulting in failed activation on computers leveraging multiple domains and users is resolved. [DDPC-11479, DDPC-11840, DDPSUS-2648]
- The master installer now displays text correctly in German on the *InstallShield Wizard Complete* screen. [DDPC-11501]
- An issue resulting in computer crash after mounting and unmounting removal media is resolved. [DDPC-11555]
- The HCA driver is no longer installed when installing Endpoint Security Suite Enterprise. [DDPC-11576]
- An issue that triggered System Data Encryption recovery after Windows updates is resolved. [DDPC-11667]
- An issue caused by corrupt vault entries that resulted in cmgshieldsvc.exe and computer crash is resolved. [DDPC-11720]
- The Data Security Uninstaller no longer displays overlapping windows on the Latitude 7370. [DDPC-11791]
- An issue resulting in failed activation due to the inability to locate a user in the vault is resolved. [DDPC-11840, DDPSUS-2734]
- Encryption sweeps no longer yield an error due to a mishandled vault code. [DDPC-11849, DDPSUS-2759]
- Dell has released fixes for an improper access control vulnerability in Endpoint Security Suite Enterprise (CVE-2020-5358). See the Dell Security Advisory (DSA-2020-113) at [Dell Security Advisory](#) for affected products, versions, and additional information. [DDPC-11877]
- An issue resulting in computer crash if the Encryption Management Agent is installed on a computer with Credant Mobile Guardian v7.x is resolved. [DDPC-11890, DDPSUS-2763]
- Files on Demand and .PST file types no longer fail to sync to Onedrive on computers protected by Dell Encryption. [DDPC-11963, DDPSUS-2799, DDPSUS-2800]
- Large recovery bundles no longer encounter a timeout and subsequently fail to download from the Dell Server. [DDPC-11972, DDPSUS-2713]

## Pre-boot Authentication v2.7

- The PBA now properly syncs with the Dell Server if the network cable is plugged in after startup. [DDPC-2773, DDPC-2794]
- PBA configured in UEFI mode on specific BIOS revisions now properly sync with the Dell Server without user intervention. [DDPC-6375, DDPC-7978, DDPC-11236]
- Additional cached smart card credentials are now accessible when selecting **Other user** in the Windows Log in screen. [DDPC-8942, DDPC-11898, DDPSUS-2801]
- Keyboard mapping on Swiss French keyboards now function as expected on the Latitude 7490. [DDPC-11122, DDPSUS-2579]
- A rare issue in which duplicate users are created in the PBA resulting in failed authentication when logging in through the PBA is resolved. [DDPC-11733]

## SED Manager v2.7

- An issue resulting in domain-added users failing to authenticate when a third-party credential provider is in use after an administrator invoked password change is resolved. [DDPC-11654, DDPSUS-2506, DDPSUS-2695]
- An issue resulting in computers starting up automatically after hibernating or shutting down is resolved. [DDPC-11751]
- An issue resulting in the Dell Credential provider resetting the password field as a user attempts to log in after logging off or unlocking the computer is resolved. [DDPC-11826, DDPSUS-2739]

## Full Disk Encryption v2.7

- An issue resulting in a repeating lock screen if the *Sync Users at PBA Activation* policy is enabled is resolved. [DDPC-8195, DDPC-8416, DDPC-8590, DDPC-10038]

- An issue resulting in domain-added users failing to authenticate when a third-party credential provider is in use after an administrator invoked password change is resolved. [DDPC-11654, DDPSUS-2506, DDPSUS-2695]
- In issue resulting in the Dell Credential provider resetting the password field as a user attempts to log in after logging off or unlocking the computer is resolved. [DDPC-11826, DDPSUS-2739]

## BitLocker Manager v2.7

- An issue resulting in deleted registry values after disabling the Reset Platform Validation Data After Recovery policy in the Dell Server is resolved. [DDPC-6150]
- The Encryption Management Agent no longer manages the TPM if TPM management is disabled for BitLocker Manager in the Dell Server. [DDPC-8991, DDPC-11960]
- BitLocker Manager now detects and creates the recovery password protector for non-system drives protected by BitLocker. [DDPC-11126, DDPSUS-2562]
- When installing with the Endpoint Security Suite Enterprise suite installer, the BitLocker Manager tile now properly displays in the Data Security Console if Encryption or External Media Encryption are installed. [DDPC-11874]

## Technical Advisories v2.7

### Advanced Threat Prevention v2.7

- When updating with Endpoint Security Suite Enterprise interactively with Dell Encryption and Firewall and Web Protection installed, Advanced Threat Prevention does not update properly. As a workaround, update Advanced Threat Prevention using the child installers. [DDPC-11997]

### Firewall and Web Protection v2.7

- When updating with Endpoint Security Suite Enterprise interactively with Dell Encryption installed, Firewall and Web Protection does not display in the selection screen. As a workaround, update Firewall and Web Protection using the child installers. [DDPC-11999]

### Encryption Client v10.7

- Dell Encryption cannot be upgraded to v2.7 from versions earlier than v1.6.0. Endpoints running versions prior to v1.6.0 must upgrade to v1.6.0 then upgrade to v2.7 . [DDPC-11576]
- After decrypting a computer, a prompt to reboot the computer may display on the login screen. [DDPC-11940]
- After a successful Windows 10 Feature Update, a rare issue may occur resulting in inaccessible encrypted data. As a workaround, run WSD deactivate on the affected endpoint and force reactivation with the configured Dell Server. For more information on running WSD deactivate, see KB article [SLN298107](#). [DDPC-12013]
- In rare situations, upgrades using the DDSSuite installer fail and an error displays on subsequent update attempts detailing that the application is already updated. As a workaround, upgrade specific components using the child installers. [DDPC-11993]
- If updating an endpoint running Dell Encryption with the DDSSuite installer interactively, the External Media Encryption option may not display in the feature selection screen. [DDPC-11998]

### Pre-boot Authentication v2.7

- If the Authentication Method is set as smart card and the *Sync Users at PBA Activation* policy is enabled in the Dell Server, users cannot use alternate authentication methods to log in. As a workaround, administrators should change the Authentication Method to Password or disable the Sync Users at PBA Activation policy in the Dell Server. [DDPC-11897]
- The *About* section in the PBA environment currently lists the incorrect version number. [DDPC-11995]

## SED Manager v2.7

- No technical advisories exist.

## Full Disk Encryption v2.7

- No technical advisories exist.

## BitLocker Manager v2.7

- If the TPM is unmanaged, requiring BitLocker Manager to use the TPM or TPM and PIN results in a log error that does not clearly specify the state of TPM management. [DDPC-11960]

## New Features and Functionality v2.5

- Swedish keyboards are now supported by the Pre-boot Authentication environment.
- Dell Encryption now supports additional Windows smart card Credential Providers.
- Endpoint Security Suite Enterprise v2.5 now supports Windows 10 v1909 (November 2019 Update\19H2).
- Advanced Threat Prevention agent version 1541.1 now supports Windows 10 v1909 (November 2019 Update\19H2).
- Web Protection and Client Firewall v10.6.1 now supports Windows 10 v1909 (November 2019 Update\19H2).
- Web Protection and Client Firewall v10.6.1 has been integrated into Endpoint Security Suite Enterprise v2.5.
- Full Disk Encryption and SED Manager now support the following platforms:
  - Latitude 3310
  - Latitude 3310 2-in-1
  - Latitude 5401
  - Latitude 5403
  - Latitude 5501
  - Latitude 7220 Rugged Extreme Tablet
  - Latitude 7300
  - OptiPlex 3070 All-in-One
  - OptiPlex 5070 Tower, Small Form Factor, Micro
  - OptiPlex 5270 All-In-One
  - OptiPlex 7070 Tower, Small Form Factor
  - OptiPlex 7770 All-In-One
  - Precision 3431 Desktop Workstation
  - Precision 3540
  - Precision 3541

## Resolved Technical Advisories v2.5

### Advanced Threat Prevention v2.5

- No technical advisories exist.

### Web Protection and Client Firewall v2.5

- Direct-access traffic is no longer blocked by Client Firewall, after upgrading from Web Protection and Client Firewall v10.5.4 to v10.6.1.
- The Web Control pop-up message is now positioned properly, and the information is readable.

## Encryption v2.5

- An issue resulting in corrupted files created by Notepad++ and Onenote is resolved. [DDPC-11440, DDPSUS-2385, DDPSUS-2642]
- An issue resulting in files not encrypting after a change in encryption algorithm is resolved. [DDPC-11460]
- A rare occurrence resulting in the Change Password option to not display at Windows login is resolved. [DDPC-11400]
- Installing Dell Encryption with older versions of Encryption Management Agent now creates independent system tray icons for each product. [DDPC-11052, DDPC-11279]

## Pre-boot Authentication v2.5

- Boot time when the Pre-boot Authentication environment is present is improved. [DDPC-11042, DDPC-11422, DDPSUS-2471]
- Swiss French keyboard mapping now functions as expected in the Pre-boot Authentication environment. [DDPC-11122, DDPSUS-2579]

## SED Manager v2.5

- No technical advisories exist.

## Full Disk Encryption v2.5

- No technical advisories exist.

## Bitlocker Manager v2.5

- No technical advisories exist.

## Technical Advisories v2.5

### Advanced Threat Prevention v2.5

- Advanced Threat Prevention is not currently supported with Windows 10 v1909 (November 2019 Update\19H2).

### Encryption Client v10.5

- Added 12/2019 - In January 2020, SHA1 signing certificates are no longer valid and cannot be renewed. Devices running Windows 7 or Windows Server 2008 R2 must install Microsoft KBs <https://support.microsoft.com/help/4474419> and <https://support.microsoft.com/help/4490628> to validate SHA256 signing certificates on applications and installation packages.

Applications and installation packages signed with SHA1 certificates will function but an error will display on the endpoint during installation or execution of the application without these updates installed.

- In rare occurrences, computers leveraging eMMC drives will crash in Dell.SecurityFramework.Agent.exe, causing a Stop 0x74 CRITICAL\_PROCESS\_DIED BSOD, when restarting the computer after applying encryption. [DDPC-11461]
- The German installer contains improperly formatted text. [DDPC-11501]
- In rare cases, encryption sweeps yield an error due to a mishandled vault code. [DDPC-11849, DDPSUS-2759]

### Pre-boot Authentication v2.5

- When leveraging smart cards for PBA activation, the Sync Users at PBA Activation policy must be disabled in the Dell Server. [DDPC-11543]

## SED Manager v2.5

- No technical advisories exist.

## Full Disk Encryption v2.5


- Full Disk Encryption's encryption status may not properly display in the Data Security Console on computers protected by Dual Encryption. [DDPC-11133]


## Bitlocker Manager v2.5

- No technical advisories exist.

## New Features and Functionality v2.4

- Dell Encryption's DDSSetup and DDSSuite installers have been updated to resolve CVE-2016-2542.
- Dell has added verbosity in the Policy-Based Encryption logs when performing Windows 10 Feature Updates.
- Advanced Threat Prevention v2.0.1541.1 has been integrated into Endpoint Security Suite Enterprise v2.4.
- Web Protection and Client Firewall v10.6.1.127 has been integrated into Endpoint Security Suite Enterprise v2.4.
- Endpoint Security Suite Enterprise v2.4 now supports Windows 10 v1903 (May 2019 Update/19H1)
- The Web Protection and Client Firewall features now support Windows 10 v1903 (May 2019 Update/19H1)
- The Web Protection and Client Firewall features can now be installed with or without Advanced Threat Prevention.
- Read speed on Full Disk Encryption is improved by parallelized decryption routine.
- Mounting a disk protected by Full Disk Encryption in a WinPE is now possible through a GUI.





- Full Disk Encryption and SED Manager now support the following platforms:
  - Latitude 5403
  - Precision 5540
  - Precision 7540
  - Precision 7740
  - XPS 7390
  - XPS 7390 2-in-1
  - XPS 7590

## Resolved Technical Advisories v2.4

### Advanced Threat Prevention v2.4

- The master uninstaller now functions properly on non-English operating systems with Advanced Threat Prevention installed. [DDPC-11338]

### Encryption v2.4

- The master uninstaller now removes all files and folders as expected. [DDPC-9468]
- An issue resulting in the Encryption service failing after activation and, in rare occurrences, operating system crashes is resolved. [DDPC-11011, DDPC-10952, DDPC-10953, DDPSUS-2543]
- Multi-user and domain-based computers no longer invoke activation loss or fail to achieve policy compliance regardless of authentication method or sequence. [DDPC-11053, DDPC-11066]
- A race condition resulting in an unusable system due to no Credential Providers available at the Windows login screen is resolved [DDPC-10936]
- An issue resulting in the Encryption service crashing after attempting to take ownership of a TPM is *Cleared* state is resolved. [DDPC-11095, DDPSUS-2565]
- An issue resulting in failure to write the Encryption mode in use to registry is resolved. [DDPC-11125]
- An issue resulting in a crash if changing crypto libraries with HVCI enabled is resolved. This issue could present when upgrading from versions prior to v10.0 to v10.1 or later. [DDPC-11178, DDPC-11293, DDPC-11506, DDPSUS-2572, DDPSUS-2598]
- An issue resulting in a crash due to failed policy processing is resolved. [DDPC-11207, DDPSUS-2597]
- An issue in Dell Encryption resulting in untranslated text during a Windows 10 Feature Update is resolved. [DDPC-11381]
- An issue resulting in a crash after applying KB4512941 on a computer protected by Encryption is resolved. [DDPC-11320, DDPSUS-2662]

- An issue resulting in the inability to install Cadence, orCAD, and Allegro with Encryption present on the target computer is resolved. [DDPC-11420, DDPSUS-2630]
- An exception resulting in the Encryption service crashing is resolved. [DDPC-11425, DDPSUS-2629]
- An issue resulting in system crash caused by a new file classification starting in KB4515384 and KB4512941 is resolved. For more information, see KB article [SLN318627](#). [DDPC-11505]
- An issue resulting in Encryption moving to an unmanaged state after a Windows Feature Update is resolved. [DDPC-10545, DDPC-10569]

## Pre-boot Authentication v2.4

- An issue resulting in a delay if a Dell Server was unavailable at in the Pre-boot Authentication environment is resolved. [DDPC-4503, DDPC-8098, DDPSUS-2277]
- Challenge/Response Recovery now functions as expected in Legacy boot mode when multiple user certificates are in use. [DDPC-4503, DDPC-10816]
- The Pre-boot Authentication environment no longer freezes when authenticating a user with cached smart-card credentials. [DDPC-8072, DDPC-8696]
- Users can now enroll Recovery Questions using a mouse or keyboard. [DDPC-9143]
- Users can now enroll Recovery Questions as expected. [DDPC-9972, DDPC-10503]
- Legal Notice and Support Information fields in the Pre-boot Authentication environment now display text as expected. [DDPC-11026, DDPSUS-2545]
- The Pre-boot Authentication environment now properly displays copyright dates on the Network and Support pages. [DDPC-10740]
- Challenge/Response Recovery now functions as expected in UEFI boot mode. [DDPC-10815]
- After failing to authenticate in the Pre-boot Authentication environment and failing Challenge Response recovery, user's domain accounts now unlock after successfully logging into Windows. [DDPC-11127]
- An issue resulting in Server Sync failing in the Pre-boot Environment is resolved. [DDPC-11263]
- An issue resulting in duplicate DHCP requests in the Pre-Boot Authentication environment is resolved. This fix reduces boot time. [DDPC-11366]
- An issue resulting in the inability to Single-sign-on through the Pre-boot Authentication environment with a domain user after local administrator activation is resolved. [DDPC-11378]

## SED Manager v2.4

- An issue resulting in smartcard login being unavailable for devices protected by SED Manager after resuming from sleep is resolved. [DDPC-8284]

## Full Disk Encryption v2.4

- An issue resulting in smartcard login being unavailable for devices protected by Full Disk Encryption after resuming from sleep is resolved. [DDPC-8284]
- Installing Policy-Based Encryption and Full Disk Encryption no longer requires the ENABLE\_FDE\_LM=1 parameter during installation for either application. [DDPC-11091, DDPC-11090]
- An issue resulting in access to a drive protected by Full Disk Encryption without the necessary prerequisites is resolved. [DDPC-11424]

## Bitlocker Manager v2.4

- An issue resulting in computers protected by Bitlocker not honoring Bitlocker Manager policies is resolved. [DDPC-11250, DDPSUS-2608]

# Technical Advisories v2.4

## Advanced Threat Prevention v2.4

- No technical advisories exist.

## Encryption Client v10.4

- After installing Dell Encryption, the Support pane in the Data Security Console displays a blank page until the device activates, or an internet connection is available. [DDPC-8059]
- When Policy Based Encryption and any technology managed by the Encryption Management Agent is installed, removable media may not consistently appear as removable in the Data Security Console and the Security Management Server. [DDPC-9736]
- The Encryption Management Agent no longer outputs policies by default. To output current and newly consumed policies, create the following registry key:  
HKLM\Software\Dell\Dell Data Protection\  
DWORD: DumpPolicies  
Value=1  
**Note:** a reboot is not required for this change to take effect. [DDPC-9786]
- When using Policy-Based Encryption with a version prior to v10.0 and the Encryption Management Agent with v10.0 or newer, Policy Based Encryption's status does not properly display in the Data Security Console. [DDPC-11052]
- The following registry key prevents lock screen applications from properly functioning until a user has logged into the device. This key is enabled by default to ensure that user activation and key unlock is not impeded.  
HKLM\SOFTWARE\Microsoft\Windows\CurrentVersion\Policies\System  
DWORD: DisableAutomaticRestartSignOn  
Value: 1 [DDPC-10825]
- The master uninstaller currently requires all lower-case characters with the /silent command. Running with camel-case or upper case characters will prevent the uninstaller from running. [DDPC-11092]
- Before a reboot, Dell recommends properly closing any files open in applications that leverage temporary files to store changes. Failure to properly close these files could result in data loss. [DDPC-11440]

## Pre-boot Authentication v2.4

- The XPS 7390 touchpad functions improperly after the Pre-boot Authentication environment is created. After logging into Windows, the touchpad functions properly. To work around this issue, use the Tab key to transition between dialog boxes and options. [DDPC-11306]
- In rare occurrences, when the Pre-boot Authentication environment is created, the boot order may be set incorrectly on reboot. [DDPC-11504]

## SED Manager v2.4

- No technical advisories exist.

## Full Disk Encryption v2.4

- No technical advisories exist.

## Bitlocker Manager v2.4

- No technical advisories exist.

## New Features and Functionality v2.3

- Pre-boot Authentication now supports block SID features.
- Dell Encryption now supports Micron 1300 self-encrypting drives.
- Dell Encryption now supports the following platforms:
  - Latitude 5300
  - Latitude 5500
  - Latitude 7200 2-in-1
  - Latitude 7400
  - Latitude 7400 2-in-1
- Advanced Threat Prevention 1531.1 has been integrated into Endpoint Security Suite Enterprise v2.3.
- Endpoint Security Suite Enterprise v2.3 now supports Windows Server 2019 (Standard/Datacenter).

## Resolved Technical Advisories v2.3

### Advanced Threat Prevention v2.3

- An issue that caused excessive memory consumption is resolved. [DDPC-10767, DDPSUS-2487]

### Encryption v2.3

- An issue resulting in failed user activation when a smart card is in use with Policy Based Encryption is resolved. [DDPC-9686, DDPC-9808, DDPC-10592, DDPC-10592, DDPSUS-2402, DDPSUS-2425, DDPSUS-2450]
- An issue resulting with Windows 10 Work Folders failing to sync when attempting to sync encrypted files is resolved. [DDPC-10400, DDPSUS-2269, DDPSUS-2394, DDPSUS-2407]
- Decryption of EMS devices from any endpoint is now enabled. [DDPC-10564, DDPC-10781, DDPSUS-2421, DDPSUS-2467]
- An issue resulting in a key icon appearing allowing for local key escrow on a remotely managed device is resolved. [DDPC-10559, DDPSUS-2548]
- An issue resulting in the Encryption Management Agent and Policy Based Encryption installers failing to determine the installation status of newer VC++ 2017 versions is resolved. These prerequisites may be bypassed through MSI installation. Contact Dell ProSupport to acquire MSI installers. [DDPC-10654, DDPC-10888]
- An issue resulting in Dell Encryption not applying EMS policies on the local computer unless *Check for policy update* is selected is resolved. [DDPC-10781, DDPSUS-2421, DDPSUS-2467]
- Encryption sweeps now function as expected after upgrading a computer protected by Dell Encryption in Encryption External Media mode. [DDPC-10828, DDPSUS-2508]
- An issue resulting in a crash if Microsoft's .Net Framework is corrupted on a computer protected by Dell Encryption is resolved. [DDPC-10871, DDPSUS-2519]
- A rare issue resulting in a crash during a Policy Based Encryption upgrade with Secureboot enabled is resolved. [DDPC-10954, DDPSUS-2572, DDPSUS-2534]
- Devices protected by Encryption External Media and white-listed no longer require a manual recovery of the encrypted files on the drive. [DDPC-10957]

### Pre-boot Authentication v2.3

- When enabling the Pre-Boot Authentication environment for Dell Encryption, the boot order no longer reverts to PXE boot when it is enabled in BIOS. [DDPC-4334, DDPC-8377, DDPC-8378, DDPC-10961, DDPSUS-2176, DDPSUS-2456]
- An issue resulting in the Pre-boot Authentication environment failing to properly recognize some keys on non-English keyboards is resolved. [DDPC-8154, DDPC-10713, DDPSUS-1656, DDPSUS-2415]

**NOTE:** This fix requires the BIOS update launched in late April 2019 or in May 2019. The BIOS revision and release date will vary based on the platform affected. If the BIOS update is applied before Dell Encryption v2.3 is installed on devices with US English keyboards, the Pre-boot Authentication environment may not properly translate all characters.

- An issue resulting in an incorrect prompt when a new user attempts authentication with a smart card without connection to the Dell Server is resolved. [DDPC-9351]
- An issue that resulted in the *Challenge Response* screen displaying in place of the password authentication screen after exceeding recovery questions attempts on a Legacy computer with PBA active is resolved. [DDPC-9426]
- An issue resulting in sleep mode failing on an Optiplex 7060 when Dell Encryption and SED management are both activated after an upgrade to Windows 10 October 2018 update is resolved. [DDPC-10410]
- Valid certificates work as expected when a smart card is used. [DDPC-10512]
- An issue resulting in a malformed Pre-boot Authentication database due to incorrect updates to the Pre-boot Authentication environment's datastore is resolved. Primary and secondary datastores now properly validate data and rotate. [DDPC-10757, DDPSUS-2482]
- A delay during login when selecting the option to run as a different user in Windows with Pre-boot Authentication enabled is resolved. [DDPC-10956] [DDPSUS-2531]

## SED Management v2.3

- Dell Encryption now allows registry-based overrides to prevent disabling third-party credential providers after the Pre-boot Authentication environment is enabled. To prevent Dell Encryption from disabling third-party credential providers, create the following registry key:

HKLM\SOFTWARE\Dell\Dell Data Protection\

"AllowOtherCredProviders" = DWORD:1

0=Disabled (default)

1=Enabled

**NOTE:** This value may prevent the Dell credential provider from properly syncing credentials initially due to third-party credential providers being disabled. Ensure the devices using this registry key can properly communicate with the Dell Server. [DDPC-10542, DDPSUS-2410, DDPSUS-2412, DDPSUS-2506]

## Full Disk Encryption v2.3

- Full Disk Encryption is now supported on Optiplex 7460 All-in-one and Optiplex 7760 All-in-one when SATA is set to AHCI. [DDPC-9224]
- Dell Encryption now allows registry-based overrides to prevent disabling third-party credential providers after the Pre-boot Authentication environment is enabled. To prevent Dell Encryption from disabling third-party credential providers, create the following registry key:

HKLM\SOFTWARE\Dell\Dell Data Protection\

"AllowOtherCredProviders" = DWORD:1

0=Disabled (default)

1=Enabled

**NOTE:** This value may prevent the Dell credential provider from properly syncing credentials initially due to third-party credential providers being disabled. Ensure the devices using this registry key can properly communicate with the Dell Server. [DDPC-10542, DDPSUS-2410, DDPSUS-2412, DDPSUS-2506]

- An issue resulting in a malformed Pre-boot Authentication database due to incorrect updates to the Pre-boot Authentication environment's datastore is resolved. Primary and secondary datastores now properly validate data and rotate. [DDPC-10757, DDPSUS-2482]

## Bitlocker Manager

- An issue resulting in Bitlocker Manager detecting removable disks are fixed disks is resolved. Add the following registry key to enable this fix:

HKLM\Software\Dell\Dell Data Protection\

"UseEncryptableVolumeType" = DWORD:1

0=Disabled (default)

1=Enabled

[DDPC-10510, DDPSUS-2279]

- An issue resulting in one minute polling is resolved. [DDPC-10964, DDPSUS-2539]

## Technical Advisories v2.3

### Advanced Threat Prevention v2.3

- No technical advisories exist.

### Encryption Client v10.3

- In rare occurrences, when the TPM is in a cleared state in BIOS, Dell Encryption may attempt to take ownership of the TPM and receives a null value. In this situation the Dell Encryption service may crash, resulting in an operating system crash. As a work around, if the TPM is in a cleared state, fully disable the TPM. [DDPC-11095, DDPSUS-2565]

### Pre-boot Authentication v10.3

- When changing networks on a device with Pre-boot Authentication enabled, if static IP addresses are in use in either connection, users may be unable to connect to the Dell Server. To work around this issue, leverage cached credentials in the Pre-boot authentication environment. [DDPC-6829, DDPSUS-1788]
- In rare instances, when using Recovery Questions in the Pre-Boot Authentication environment, the expected workflow of a password reset is not properly presented once the device transitions into Windows. [DDPC-11660]

### SED Management v10.3

- After logging in through the PBA, the Data Security Console may appear when hotkeys are leveraged within the operating system to close applications. [DDPC-9344]

### Full Disk Encryption v2.3

- No technical advisories exist.

### Bitlocker Manager v10.3

- No technical advisories exist.

## New Features and Functionality v2.2.1

- No technical advisories exist.

## Resolved Technical Advisories v2.2.1

### Advanced Threat Prevention v2.2.1

- No resolved technical advisories exist.

### Encryption v10.2.1

- An incompatibility issue with Windows 10 March Cumulative Update that resulted in UI errors and missing activation information is resolved. [DDPC-10944, DDPSUS-2537]

### Pre-boot Authentication v2.2.1

- No resolved technical advisories exist.

### Full Disk Encryption v2.2.1

- No resolved technical advisories exist.

## Technical Advisories v2.2.1

### Advanced Threat Prevention v2.2.1

- No technical advisories exist.

### Encryption Client v10.2.1

- No technical advisories exist.

### Pre-boot Authentication v10.2.1

- No technical advisories exist.

### SED Management v10.2.1

- No technical advisories exist.

### Full Disk Encryption v2.2.1


- No technical advisories exist.

### Bitlocker Manager v10.2.1

- No technical advisories exist.

## New Features and Functionality v2.2

- Advanced Threat Prevention is now supported on Windows 10 October 2018 Update (Redstone 5 release).
- Advanced Threat Prevention 1511.5 has been integrated into Endpoint Security Suite Enterprise v2.2.
- Optional Firewall and Web Protection features are now supported on Windows 10 October 2018 Update (Redstone 5 release).
- Following Windows 10 feature upgrade, a restart is **required** to finalize Dell Encryption. The following message displays in the notification area after Windows 10 feature upgrades:



## Resolved Technical Advisories v2.2

### Advanced Threat Prevention v2.2

- No resolved technical advisories exist.

### Encryption v10.2

- An issue that caused operating system crash following an Windows update is resolved. [DDPC-5664, DDPC-9457, DDPSUS-1356, DDPSUS-1409, DDPSUS-2216]
- An issue with the Dell Authentication Service resulting in the inability to register recovery questions is resolved. [DDPC-9972, DDPC-10503, DDPC10528, DDPC-10620]
- Added 3/2019 - **Check for Policy Updates** now triggers policy polling as expected with Policy Based Encryption v10.2 and later. [DDPC-9800, DDPSUS-2416]
- Encryption sweeps now process as expected following upgrades. [DDPC-10168]
- An issue that resulted in encryption sweeps pausing after new policies were received is resolved. [DDPC-10025, DDPSUS-2414, DDPSUS-2458]
- An issue resulting in inaccessible files protected by Encryption External Media is resolved. [DDPC-10251, DDPSUS-2318, DDPSUS-2408]
- An issue that resulted in activation loss on Windows 7 has been resolved. [DDPSUS-2459]
- An issue that resulted in repeated activation attempts, inaccessible encrypted files, and activation loss on computers leveraging Deferred activation is resolved. [DDPC-10570, DDPSUS-2445, DDPSUS-2435, DDPSUS-2442]
- An issue resulting in loss of smart card functionality with previously activated users is resolved. [DDPC-10592, DDPSUS-2402, DDPSUS-2425]
- An issue that resulted in intermittently inaccessible Microsoft Office documents following an upgrade to Dell Encryption is resolved. [DDPC-10606, DDPSUS-2392]
- An issue resulting in operating system crash following an encryption policy update is resolved. [DDPC-10610, DDPSUS-2451, DDPSUS-2483]
- An issue that resulted in crashes following an update to Dell Encryption v10.1 is resolved. [DDPC-10676, DDPSUS-2469]
- An issue that resulted in excessive logging is resolved. [DDPC-10679, DDPSUS-2449]

### Pre-boot Authentication v2.2

- An issue that resulted in a parity error after activating pre-boot authentication with Dell Encryption installed on a Latitude 7404, Latitude 7204, or a Latitude 5404 Rugged computer in Legacy boot mode is resolved. [DDPC-9493, DDPC-10748, DDPSUS-2225]

- The K13A Rugged dock (only compatible with Rugged computers) no longer requires the an open lid to display on external monitors. [DDPC-10093]
- A network connectivity issue on the Lenovo Thinkpad T560 with BIOS version N1KET39W (1.26) 2018-05-28 in UEFI mode is resolved. [DDPC-10498]
- Recovery question user experience is improved. [DDPC-10544, DDPC-10543, DDPC-10640]
- The **Sign In** button is no longer enabled following initial activation of the pre-boot authentication. [DDPC-10615]
- An issue in the pre-boot authentication environment that resulted in various keys on Japanese keyboards not displaying or displaying incorrectly on the Latitude E7280 is resolved. [DDPC-10639, DDPSUS-1656]
- Users logging in with recovery questions are now able to change their Windows password as expected. [ ]

## Full Disk Encryption v2.2

- Performance is improved on computers protected by Full Disk Encryption. [DDPC-9748, DDPC-9787, DDPC-9802, DDPC-9821, DDPC-9889]
- Peripherals no longer experience a delay when waking from hibernation on a computer leveraging Full Disk Encryption. [DDPC-10602, DDPSUS-2418]

## Technical Advisories v2.2

### Advanced Threat Prevention v2.2

- Incorrect version information displays in *System Check* when launching *Advanced UI* on a computer. [CYL-866]

### Encryption Client v10.2

- No technical advisories exist.

### Pre-boot Authentication v10.2

- No technical advisories exist.

### SED Management v10.2

- No technical advisories exist.

### Full Disk Encryption v2.2

- No technical advisories exist.

### Bitlocker Manager v10.2

- No technical advisories exist.

## New Features and Functionality v2.1

- Added 12/2018 -
  - Dell Encryption is now supported with Windows 10 October 2018 Update (Redstone 5 release).
  - SED management and Bitlocker manager are now supported with Windows 10 October 2018 Update (Redstone 5 release).
  - Full Disk Encryption is now supported with Windows 10 October 2018 Update (Redstone 5 release).

- Advanced Threat Prevention is now supported on Windows 10 IoT Enterprise.
- Dell Encryption v10.1 and later defaults to leveraging a new cryptographic library, provided by RSA, as well as multiple new options for cryptographic libraries. For more information, see [Dell Encryption FIPS Compliance](#).
- HP EliteBook 840 G4 and HP EliteBook 1040 G3 have been validated with SED and FDE when running in UEFI Boot mode. To ensure full functionality, set the following BIOS settings:
  - In BIOS, navigate to the Advanced tab, select *Secure Boot Configuration*, then select the check boxes labeled *Import Custom Secure Boot keys* and *Enable MS UEFI CA key*.
  - From the drop down menu, select *Legacy Support Disable* and *Secure Boot Enable*.
  - In BIOS, navigate to Advanced tab > Option ROM Launch Policy and select *All UEFI* from the drop down menu.
- Automated in-place upgrades are now supported for Windows 10 on Bitlocker manager, Full Disk Encryption and self-encrypting drives.

## Resolved Technical Advisories v2.1

### Advanced Threat Prevention 2.1

- No resolved technical advisories exist.

### Encryption Client v10.1

- EMS Explorer is now working as expected when connecting an encrypted USB with EMS on a computer without Dell Encryption. [DDPC-5585, DDPSUS-2401]
- Resolved an issue that resulted in the loss of user activation on reboot. [DDPC-6572, DDPSUS-1844]
- Local users can now activate with Dell Encryption installed with Opt-in mode on a computer running Windows April 2018 update and not joined to a domain. [DDPC-9377, DDPSUS-2365, DDPSUS-2387, ]
- The PBA Recovery Question authentication works as expected. [DDPC-9671]
- A timeout no longer occurs for user credentials when waiting some time to provide a new password after passing the recovery questions screen on a computer with Windows April 2018 update in UEFI mode and FDE enabled. [DDPC-9818]
- When child installers fail to install successfully, Dell Encryption will also fail to install and will log these errors. [DDPC-10110, DDPSUS-2379]
- LastSyncTime in the report results for Device Detail is now working as expected. [DDPC-10184, DDPSUS-2388]
- SDE plugins, PBE plugins and Encryption plugins now display the correct versions on the Management Console. [DDPC-10531, DDPSUS-2416]

### Preboot Authentication v10.1

- An issue resulting with a computer running Windows 7 becoming unresponsive during decryption with PBA activated and FDE enabled has been resolved. [DDPC-9237, DDPC-10121]

### Full Disk Encryption v2.1

- An issue resulting with a computer running Windows 7 becoming unresponsive during decryption with PBA activated and FDE enabled has been resolved. [DDPC-9237, DDPC-10121]

## Technical Advisories v2.1

### Advanced Threat Prevention v2.1

- When checking for policy updates from the Encryption icon menu, the application may appear to freeze for a short while. This condition can be safely ignored without closing the Encryption console. [DDPC-10302]

- Windows 10 upgrades on systems running Full Disk Encryption may fail on a computer with Advanced Threat Prevention when script control is enabled and set to *Block* . To work around this issue, exclude the working directories for Windows 10 Updates, or set Script Control to *Alert* mode while the Windows 10 upgrade is running. For more information see: <https://www.dell.com/support/article/us/en/04/sln298382> . [DDPC-10445]

## Encryption Client v10.1

- Usernames with symbols may result with a "System Lock Required" pop-up message after a successful Single Sign On. To work around this issue, unlock and log back into the computer. [DDPC-10485]
- In rare occurrences, users may be unable to enroll in recovery questions due to an unresponsive Dell Authentication Service. To work around this issue, reboot the computer. [DDPC-10503]
- After installing Dell Encryption, an error in DellAgent.log stating "Could not locate saasManager plugin" may be safely ignored. [DDPC-10509]
- When attempting to upgrade Windows to a newer feature update, the feature update processes as expected, but registration is lost after the update. To work around this issue, reboot the computer. [DDPC-10569]

## Preboot Authentication v10.1

- While using a K13A Rugged dock (only compatible with Rugged computers), an open laptop lid may be required for the operating system to populate on some monitors. [DDPC-10093]
- With the latest version of Encryption client installed, an Optiplex 7040 may not properly return from a hibernation or sleep. [DDPC-10181]
- Sleep mode may fail on an OptiPlex 7050 while Full Disk Encryption is in the process of encrypting. [DDPC-10261]
- Network connectivity may not be available when running on Lenovo Thinkpad T560 with BIOS version N1KET39W (1.26) 2018-05-28 in UEFI mode. To work around this issue, connect to a network with a USB dongle that uses Realtek USB GbE Family Controller. [DDPC-10498]

## SED Management v10.1

- No technical advisories exist.

## Full Disk Encryption v2.1

- No technical advisories exist.

## Bitlocker Manager v10.1

- No technical advisories exist.

## New Features and Functionality v2.0.1

- Resolved customer issues.

## Resolved Technical Advisories v2.0.1

### Advanced Threat Prevention 2.0.1

- An issue resulting with the removal of Windows credentials for Digital Persona after an installation of Endpoint Security Suite Enterprise has been resolved. [DDPSUS-2308] ]

## Encryption Client v10.0.1

- Added 12/2018 - Resolved an issue with Dell Encryption and Digital Persona credential providers conflicting. [DDPC-10120]
- The installation of Dell Encryption on a domain controller no longer changes the local machine policies set in the "Default Domain Policy" Group Policy Object. Dell Authentication can handle logging in with no password set when a 0 password length policy is enabled.

For more information, see [Dell Encryption and Dell Endpoint Security Suite Enterprise Security Policy Overwrite Vulnerability](#) . [DDPSUS-2364]

## Technical Advisories v2.0.1

### Advanced Threat Prevention v2.0.1

- No technical advisories exist.

### Encryption Client v10.0.1

- No technical advisories exist.

### Preboot Authentication v10.0.1

- Added 11/2018 - When PBA is used, the Sync All Users policy should be enabled if a computer has multiple users. Additionally, all users must have passwords. Zero-length password users will be locked out of the computer following activation. [DDPC-10114]

### SED Management v10.0.1

- No technical advisories exist.

### Full Disk Encryption v2.0.1

- No technical advisories exist.

### Bitlocker Manager v10.0.1

- No technical advisories exist.

## New Features and Functionality v2.0

- Improvements to Windows Update handling in Self-Encrypting Drives and Full Disk Encryption is supported.
- Full Disk Encryption Device Guard compliance
- Advanced Threat Prevention provisioning into geographical data centers for the Government Cloud is now supported.
- The following non-Dell computers have been validated with SED and FDE when running in Legacy Boot mode:
  - HP EliteBook 1040 G3
  - Lenovo ThinkPad T560
- The following non-Dell computers have been validated with SED and FDE when running in UEFI Boot mode:
  - HP EliteBook 840 G3
  - Lenovo ThinkPadP50
- Endpoint Security Suite is versioned to 2.x. to realign client and Server versioning.

# Resolved Technical Advisories v2.0

## Advanced Threat Prevention 2.0

- An issue resulting with a shift in licensing when an installation of Threat Prevention entitlement used with a non-Dell McAfee version with Endpoint Security Suite Enterprise installed on top has been resolved. [DDPC-9454]

## Encryption Client v10.0

- Added 09/2018- Files synced via OneDrive with "Files On-Demand" enabled, work folders, and other technologies leveraging new APIs for file handling from Microsoft, introduced in a cumulative update for Windows 10 1709 and later, on a system running Dell Encryption are no longer displayed as erroneous text.
- The "enroll" button no longer disappears for recovery questions with encryption client installed on a Windows 10 32-bit machine. [DDPC-8938, DDPC-9199]
- Added 09/2018-Resolved an issue with Dell Encryption and Symantec Endpoint Protection resulting in an intermittent Operating System failure [DDPC-9510]

## Preboot Authentication v10.0

- The mouse now works during the PBA login screen on a Precision M4800 and Latitude 5290 computer with Windows 10 installed in UEFI mode and PBA enabled. [DDPC-6978, DDPC-7032, DDPC-8841]
- The mobile keyboard and touchpad work as expected during the PBA login screen on a Latitude 5290 2-in-1 machine with Windows 10 installed in UEFI mode and PBA enabled. [DDPC-7032]
- An issue resulting with the user name being changed to "SYSTEM" while the password is in the process of being changed using Alt + Ctrl + Delete and PBA is active on a Windows 7 computer has been resolved. [DDPC-8948]
- Multiple "Other User" tiles are no longer created on the Windows 7 login screen after successfully answering Recovery questions and with PBA active. [DDPC-9343]
- An issue resulting with the message of "Username or password is incorrect" on the Windows screen when entering updated credentials after authenticating in PBA with a newly changed password has now been resolved.[DDPC-9483]
- Smartcard is no longer the default login option when password authentication is set for PBA and SmartCardEnabled is set within Windows. The default is PBA authentication. [ DDPC-9497, DDPSUS 2301]

## SED Management v10.0

- Machines with Coffee Lake-H Xeon processors activate with currently shipping enterprise-class or OEM Samsung drives. [DDPC-9348]

## Full Disk Encryption v2.0

- Multiple disks in the computer no longer caused partitioning failures when Legacy full disk encryption in preview. [DDPC-7986]
- FDE activation no longer fails if the primary partition on the disk is over 1.5TB. [DDPC-8020]

# Technical Advisories v2.0

## Advanced Threat Prevention v2.0

- No technical advisories exist.

## Encryption Client v10.0

- In some cases, after changing passwords in Windows, the computer may experience slower logins during the first login or auto-reactivation may occur. To work around this issue, run WSDeactivate after changing the password. [DDPC-9459]
- In rare occurrences, when updating to v10.0, an error may present if the user interface is used for the update. This can be safely closed with no impact to the install. [DDPC-9555]
- Multiple users are given the option to change the password on the Windows login screen when a user has logged into the computer after successfully completing the PBA Recovery Questions. If an account other than the one that authenticated through the PBA with recovery questions is selected, an error message displays "The specified network password is not correct." [DDPC-9650]
- Single Sign On fails when a user authenticates PBA after entering a password into the console using copy+paste with more than the allowed 32 characters for Windows. [DDPC-9700]
- Added 11/2018 - Dell Encryption may introduce changes to how data is protected on your device. To ensure your endpoints are protected, running the "WSPProbe" application that is included with Dell Encryption will perform a validation that all files on the computer are properly encrypted. This may result in a slight performance degradation, but it is generally unnoticed. [DDPC-10168]
- Added 11/2018 - Windows 10 Work Folders may fail to sync when attempting to sync encrypted files. To work around this issue, manually sync each file. [DDPC-10400, DDPSUS-2269, DDPSUS-2394, DDPSUS-2407]

## Preboot Authentication v10.0

- In some cases, the touchpad becomes unresponsive during the PBA login screen on a Precision 7520 and Precision 7720 computer with Windows 10 or Windows 7 installed in legacy mode and PBA enabled. To work around this issue, attach an external mouse or use the tab key to switch through fields. [DDPC-8646]
- Added 11/2018 - Password resets after a local PBA user answers recovery questions is disabled after a minute, 30 seconds. [DDPC-9707]
- In some cases, non-Dell devices have to manually import the Microsoft SecureBoot certificates when these devices are configured for UEFI boot mode with SecureBoot enabled. This process may vary based on the manufacturer and is recommended to refer to the device's documentation for instructions on performing this process. [DDPC-9828]
- Deactivating the PBA needs to be completed before sending the policy to re-activate the PBA. Failure to wait for the deactivation to complete means the subsequent activation may not start. To work around this on a system that is in a bad state, issue another decryption policy to the endpoint. Once that policy has been consumed, re-issue a policy to re-activate either Self-Encrypting Drive Management or Full Disk Encryption management. The endpoint will begin encrypting again. [DDPC-9971]

## SED Management v10.0

- No technical advisories exist.

## Full Disk Encryption v2.0

- When upgrading from Windows 10 to Windows April 2018 update by using the ISO file with FDE installed and the drive encrypted, the Windows Feature Update may fail. To work around this issue, upgrade using Windows 10 installation media tool located at <https://www.microsoft.com/en-us/software-download/windows10>. [DDPC-10021]
- During an operating system upgrade, PBA bypass fails if a policy update is received from the server. [DDPC-10026]

## Bitlocker Manager v10.0

- No technical advisories exist.

## New Features and Functionality v1.8

- All clients with the exception of Advanced Threat Prevention, Web Protection, and Client Firewall are now supported with Windows 10 April 2018 Update (Redstone 4 release).

- As the security landscape becomes more complex, administrators are finding themselves needing to layer encryption solutions. Dell Data Security has modified how entitlements are consumed to meet this change in the landscape. Dual Encryption is now offered through volume license as a solution to customers who want to encrypt data on Windows computers using two Dell Encryption technologies. The following products can be installed and run with the Dell Encryption client on the same computer:
  - SED Manager
  - Full Disk Encryption
  - BitLocker Manager


To install and run Dell Encryption with one of these products, the computer hardware and operating system must meet the Requirements for both products before installation. For more information, see *Encryption Enterprise Advanced Installation Guide* or *Encryption Enterprise Basic Installation Guide*.

Each Dell Encryption technology will now consume one Disk Encryption license per technology on a single device, meaning if SED Manager and Policy Based Encryption are both installed on a single device to allow for two-layers of security, two Disk Encryption (DE) entitlements will be consumed for that device.

The Dell Encryption client and Full Disk Encryption are supported only on Windows 10 in UEFI mode.

Operating system upgrade is not supported with Dual Encryption in this release. Dell recommends deferring Windows 10 Feature Updates.

When using any encryption technologies in combination, it is best practice to back up data before encryption and at regular intervals.

 **NOTE:** Dell does not currently support these combinations of encryption products:

- SED Manager and Full Disk encryption
  - SED Manager and BitLocker Manager
  - Full Disk Encryption and BitLocker Manager
- The Windows 10 update process and compatibility with Windows Defender are improved when System Data Encryption is enabled. The encryption client can now identify and encrypt user files without the need to hardcode exclusion of system-generated files when System Data Encryption is enabled. This behavior is configurable and can be overridden by the administrator, if necessary. For more information on the Windows 10 Feature Update process, refer to [Dell Encryption Enterprise and Dell Encryption Personal Best Practices](#).
  - The Encryption client can now identify and encrypt user files without the need to hardcode exclusion of system files.
  - SED Manager is now compatible with HVCI.
  - SED Manager has been qualified on the following non-Dell computers:
    - HP ProBook 450 G2 (Legacy)
    - HP ProBook 450 G5 (Legacy)
    - HP ProBook 840 G4 (Legacy)
    - HP Elitebook 840 G3 (Legacy)
    - HP Elitebook 840 G4 (UEFI)
    - Lenovo ThinkPad (Legacy)
    - Lenovo T560 (UEFI)
  - A new policy enables Advanced Threat Prevention to whitelist specific scripts by certificates and hash.
  - Advanced Threat Prevention is now supported with Windows Embedded Standard 7.
  - Optional Firewall and Web Protection features are now supported with Windows 10 Fall Creators Update (Version 1709/Redstone 3).
  - Local tenants are now supported in Brazil and Japan locales for Endpoint Security Suite Enterprise.
  - The Enable Standard UI policy enables or disables standard UI for Advanced Threat Prevention in Endpoint Security Suite Enterprise web portal.
  - Full Disk Encryption is now supported with a FIPS-compliant crypto library on Windows 10.
  - Full Disk Encryption has been qualified on the following non-Dell computers:
    - HP ProBook 450 G2 (Legacy)
    - HP ProBook 450 G5 (Legacy)
    - HP ProBook 840 G4 (Legacy)
    - HP Elitebook 840 G3 (Legacy)
    - HP Elitebook 840 G4 (UEFI)
    - Lenovo ThinkPad (Legacy)
    - Lenovo T560 (UEFI)

- Starting with the Encryption Client v8.18, the authentication provider component has been fully replaced. This installer will leverage a new Dell built-in credentials provider that is part of the Client Security Framework installer. The old Digital Persona credentials provider is set to a disabled state. If leveraging the fingerprint or smart card contact-less authentication, these will no longer work after an upgrade of Encryption Client v8.18.

## Resolved Technical Advisories v1.8

### Encryption Client v8.18

- Resolved an issue with longer than usual boot times when leveraging the Policy-Based Encryption client. [DDPSUS-1950, DDPSUS-2081]
- With Fast User Switching enabled and being leveraged no longer causes Dell Encryption to fail to communicate to the Dell Security Management Server. [DDPSUS-2163]
- Re-mapped libraries no longer cause an immediate failure during install. [DDPSUS-2166]
- USB external media provisioned with Dell Encryption can now be accessed on Windows or Mac computers interchangeably without loss of key material. [DDPC-6592]
- The Dell Data Security Console shows Protection and encryption status for Policy-Based encryption. [DDPC-7046]
- Resolved an issue with the inability to white-list a device with Dell Encryption. [DDPC-7717]
- Volumes now display during recovery. [DDPC-7794]
- A memory leak no longer occurs when inserting external devices to the computer. [DDPC-8297]

### Preboot Authentication v8.18

- Resolved an issue with Thunderbolt based docking stations with the Dell Encryption Pre-Boot Authentication environment. [DDPSUS-1923]
- Resolved an issue with Pre-Boot Authentication displaying an initial access code, even though connectivity to the Dell Security Management Server is present. [DDPSUS-2198, DDPSUS-2200]
- An issue resulting with the backslash/pipe (\ |) key on an Arabic behaving differently than expected has been resolved. [DDPC-6529]
- The Windows 10 upgrade process with PBA activated is improved. [DDPC-8031]

### SED Management v8.18

- An error message no longer displays during an upgrade of Digital Persona's Auth when the Dell Data Security Console is also open during the upgrade. [DDPC-7836]
- Oberthur chip only smart card ID-One COSMO V7.0 works as expected on a UEFI copmputer. [DDPC-7985]
- Smart card readers are now detected on legacy machines. [DDPC-8030]

### Full Disk Encryption v1.2

- An error message no longer displays during an upgrade of Digital Persona's Auth when the Dell Data Security Console is also open during the upgrade. [DDPC-7836]
- FDE is now supported on Dell Optiplex 5055, XPS 13 9365, or Latitude 5495. [DDPC-7970]
- Re-activation failures no longer occur when re-imaging a device that was protected by Dell's software based Full Disk Encryption. [DDPC-8265]

### Legacy Boot Mode FDE

- Windows 7 machines boot successfully after activating PBA. [DDPC-7496]
- There is no longer a delay when switching between PBA authentication and Windows login screen on a windows 7 machine. [DDPC-7677]
- Touchpad now works after a PBA activation. [DDPC-7758]
- There is no longer a touchpad functionality issue with dual interfaces such as PS/2 and I2C. [DDPC-7865]

- A machine with a non-SED drive, is able to detect the hard drive after enabling FDE and activating PBA. [DDPC-7999]

## Bitlocker Manager v8.18

- An error message no longer displays during an upgrade of Digital Persona's Auth when the Dell Data Security Console is also open during the upgrade. [DDPC-7836]

## Technical Advisories v1.8

### Advanced Threat Prevention v1.8

- Advanced Threat Prevention events may not show immediately in the Standard UI interface. To display these events, exit and re-query for events. [DDPC-9204]

### Encryption Client v8.18

- Dell Encryption logs do not specify if insufficient disk storage caused installation failure. [DDPC-2994]
- Single Sign On is active for a 90 second period after PBA authentication on a computer in hibernation mode with the Encryption client installed. After 90 seconds, the OS user credentials must be used for authentication. [DDPC-9179]
- Added 09/2018- An issue with Dell Encryption and Symantec Endpoint Protection may result in an intermittent operating system failure [DDPC-9510]
- Added 11/2018 - Occasionally, Dell Encryption is unable to connect to the local management console. This condition results in Dell Encryption not providing the dialog to enter the password for encrypted external media, it does not prompt to encrypt unprotected media, and the About box does not contain the correct information. A computer restart resolves the issue. [DDPC-10409]

### Preboot Authentication v8.18

- Added 08/2018- After activating PBA with the Encryption Client installed on a Latitude 7404, Latitude 7204, or a Latitude 5404 Rugged computer in Legacy boot mode, an error message of "Parity Error" displays. To work around this issue, disable one of the two serial ports in BIOS.[ DDPSUS-2225, DDPC-9493]
- A local user must log in through Windows at least once on the computer before the Preboot Authentication prompts for credentials at startup for that user. If users are manually added to the computer, they must be added through User Accounts, accessed through the Control Panel. [DDPC-8569]
- In some cases, the touchpad and mouse become unresponsive during the PBA login screen on a Precision 7520 machine with Windows 10 installed in legacy mode and PBA enabled. [DDPC-8646]
- In some cases, when user tries to login using PBA after changing hibernations settings, the Single Sign On feature fails. [DDPC-8683]
- Currently, when upgrading from Fall Creators update of Windows to the April 2018 update, the initial sync to PBA appears under the task bar. [DDPC-8798]
- In rare occurrences, when upgrading from Fall Creators Update of Windows to April 2018 Update, PBA is unable to resolve DNS/DHCP successfully. To work around this issue, the user must deactivate and activate PBA again. [DDPC-8814]
- In some cases, the mouse and keyboard become unresponsive during the PBA login screen on a M4800 with Windows 10 installed in UEFI mode and PBA enabled. [DDPC-8841]
- Added 08/2018- With the computer lid closed, a black screen displays after the PBA login screen when a TB16 docking station is attached to a Precision 5530 or Precision 7730/7530 Mobile Workstation with 1.0.0 BIOS and Windows April 2018 update. To work around this issue, the computer must be reverted back to Windows 10 Fall Creators Update until an update to the BIOS has been promoted. The Precision 7730/7530 can also be attached to a TB18 docking station to resolve this issue regardless of the Windows update version. [DDPC-8945]
- Added 11/2018 - When a user logs into Windows using a password or a smart card after upgrading to v8.18, the user may be prompted to re-enroll the smart card credentials through the PBA. If the policies have changed and smart card authentication is no longer allowed, smart card re-enrollment will not be possible. If the prompt to enroll credentials continues, deactivate the PBA and then reactivate again. [DDPC-9313]

## SED Management v8.18

- When a NVME is used as a data drive with a standard 2.5" Self Encrypting Drive, a "Device Locked" message will display on the PBA screen. [DDPC-9256]

## Full Disk Encryption v1.2

- In some cases, when user tries to login using PBA after changing hibernations settings, the Single Sign On feature fails. [DDPC-8683]
- In rare circumstances, when attempting to hibernate a system with Windows 10 and FDE activated, it may not properly hibernate. [DDPC-8814]
- Currently, the FDE recovery application becomes unresponsive when selecting a recovery file stored on an encrypted volume. [DDPC-8996]

## Legacy Boot Mode FDE

- In some cases, when the primary partition of a disk does not have enough contiguous free space to create a PBA partition, then FDE activation may fail. The current work around is to free up enough space in the primary partition and apply a system reboot. [DDPC-8939]

## Bitlocker Manager v8.18

- No technical advisories

## New Features and Functionality v1.7.2

- SED Manager includes a security update addressing the Spectre and Meltdown vulnerabilities CVE-2017-5754. Customers and field teams should take v8.17.2 and all sustaining releases as a best practice.

## Resolved Technical Advisories v1.7.2

### Encryption Client v8.17.2

- The following hard-coded exclusions have been added for improved interoperability with Windows Defender and Microsoft Credential Vault:
  - C:\ProgramData\
  - C:\Program Files\
  - C:\Program Files (x86)\
  - C:\Users\\AppData\Local\Microsoft\Vault\

Due to these changes, a re-sweep will be performed to ensure that these folders are properly protected by Dell Encryption.

This sweep decrypts files that are system-generated files, but will ensure that user-generated data within these folders will stay protected as either Common encrypted or SDUser encrypted data based on currently set policies. These changes can be overridden by adding a Category 3 inclusion to SDE Encryption Rules. [DDPC-8037, DDPC-8147]

- Resolved an issue that resulted in an Operating System failure when Dell Encryption is installed and a Thunderbolt docking station is used.

 **NOTE: This is a temporary fix, and will be corrected in the next release of Dell Encryption. New drivers for thunderbolt based docking stations may be required for a final resolution.**

## Preboot Authentication v8.17.2

- The username text is now displayed in French on the PBA screen after FDE has been installed on a UEFI machine. [DDPC-8012]
- An issue where the Lock/Unlock commands were not immediately enforced even though the "check for PBA commands" policy was enabled has been resolved. [DDPC-8021]

## Legacy Boot Mode FDE

### For beta testing in non-production environments

- An issue causing the system to fail with a black screen after activating PBA and logging in to Windows has been resolved. [DDPC-6915]
- Added 05/2018 - Operating system Feature updates are supported with Full Disk Encryption. [DDPC-7527]
- Resolved an issue in Legacy BIOS based Full Disk Encryption preview where single sign-on devices from the Pre-Boot Authentication environment into Windows was failing. [DDPC-7944]

## Technical Advisories v1.7.2

### Encryption Client v8.17.2

- After installing the encryption client and opening a report of the file with WSScan, unencrypted files have "\\?\\" characters at the beginning of their directories. Only a cosmetic issue and has no effect on the system or files." [DDPC-8190]
- In some cases, after installing or upgrading encryption client, a message results of "Backup keys operation still not performed successfully..." once policies have been set. The current workaround is to reboot the machine. [DDPC-8316]

### Preboot Authentication v8.17.2

- No technical advisories.

### SED Management v8.17.2

- No technical advisories.

### Full Disk Encryption v1.1

- In rare situations, the machine stays in a locked state on Pre-Boot Authentication screen after activating FDE and rebooting the machine. The current workaround is to recover and login to Windows for FDE activation to resume automatically. [DDPC-8299]
- In rare situations, full disk encryption fail to activate on a UEFI machine. Current workaround is restart the system for FDE activation to resumes automatically. [DDPC-8302]
- The FDE script is blocked by the Encryption client. The current workaround is to exclude \ProgramData\Dell\Dell Data Protection from block on scripts before FDE activation. [DDPC-8371]

## Legacy Boot Mode FDE

### For beta testing in non-production environments

- In rare occurrences, booting to a 32-bit machine after activating FDE, the machine may fail to boot. [DDPC-8267]

## Bitlocker Manager v8.17.2

- No technical advisories

## New Features and Functionality v1.7.1

- FDE is now supported with smartcard preboot authentication on supported Dell computers running in UEFI boot mode
- FDE is now supported on non-English operating systems:
  - EN - English
  - JA - Japanese
  - ES - Spanish
  - KO - Korean
  - FR - French
  - PT-BR - Portuguese, Brazilian
  - IT - Italian
  - PT-PT - Portuguese, Portugal (Iberian)
  - DE - German
- FDE is available for beta testing in non-production environments on Dell computers running legacy boot mode.
- FDE encryption drivers are now compatible with HVCI .
- Web Protection and Client Firewall features are now supported with Windows 10 Fall Creators Update (Redstone 3 release).

## Resolved Technical Advisories v1.7.1

### Encryption Client v8.17.1

- Italian translations have been corrected for the Home/Advanced tab names. [DDPC-5825, DDPC-5826]
- An issue that resulted in a the computer becoming unresponsive when Dell Encryption and Symantec Endpoint Protection were installed on the same device has been resolved. [DDPC-7808]
- An issue causing the smart card login to fail when the smart card certificate information in the registry missing has been resolved. [DDPC-7904]
- An issue resulting with an error message of "Unable to generate catalog" after an upgrade from Redstone 2 to Redstone 3 with encryption client installed has been resolved. [DDPC-7946]

### Preboot Authentication v8.17.1

- An issue where a popup notification would warn the user to not to turn off the computer during PBA configuration has now been resolved. [DDPC-7019]
- PBA now shows the smart card certificates and smart card PIN labels. [DDPC-7066, DDPC-7976]
- An issue where PBA would crash when a smart card was plugged in after PBA loaded has been resolved. [DDPC-7676]

### Full Disk Encryption v1.1

- An issue where the Windows logo screen was taking a few minutes to appear after FDE had been activated with the machine set to hibernate and then authenticated on PBA has now been resolved. [DDPC-7804]
- An issue where Full Disk Encryption authenticated back to PBA after a combination of multiple restarts and multiple hibernations during encryption has now been resolved. [DDPC-7850]

# Technical Advisories v1.7.1

## Encryption Client v8.17.1

- In some cases, a device may not show in compliance after sweep completes. The current workaround is to reboot the device. [DDPC-7977]

## Preboot Authentication v8.17.1

- In some cases, the intensity of USB Type C mouse seems to strengthen while user is in PBA on a UEFI machine. [DDPC-7885]
- When a network cable is unplugged after loading the PBA, there is no IP address captured which causes the server sync to fail. [DDPC-7936]
- Added 05/2018- In some cases, the touchpad becomes unresponsive during the PBA login screen on a M300 machine with Windows 10 installed in UEFI mode and PBA enabled. [DDPC-8206]

## SED Management v8.17.1

- The Oberthur chip only smart card ID-One COSMO V7.0 is read by the PBA but fails to log in on a UEFI machine. [DDPC-7985]

## Full Disk Encryption v1.1

- When the network cable is disconnected during PBA recovery and then connected after FDE has been activated, the PBA screen on a UEFI machine displays "Loading data please wait" and freezes. [DDPC-8014]

## Legacy Boot Mode FDE

### For beta testing in non-production environments

- Currently, a message of "Missing OS" appears after FDE has been activated and machine has been rebooted. [DDPC-7806]
- In some cases, SSO to Windows issues appear in Legacy FDE. [DDPC-7926]

## Bitlocker Manager v8.17.1

- The policy line of: `<PasswordUse MinimumPasswordLength="8" PasswordComplexity="Allow" Usage="Allow" />` is forcing a secondary drive, which the D: drive is being seen at, to unlock with a password. Before the password unlock, this volume is not mount-able. It seems that once this is unlocked, the shield is not properly seeing this drive being mounted as a "Fixed disk", even though PCS is classifying it as:  
  
`[01.15.18 15:03:37:219 PCSInfoLogger: 53 D] [PCSQuery] Retrieved drive information from PCS driver. DeviceType: 0, Device Class: 0, Device ID: SCSI\Disk&Ven_HFS512G3&Prod_9MND-3520A\4&9e95efc&0&000200`  
  
The workaround is to change the BitLocker Policy under the Fixed Disks to: Configure Use of Passwords for Fixed Data Drives and setting this to "Disallow". The disk will use the TPM settings for the OS disk to provision a protector instead of the password that is user-defined. [DDPC-8002]

# New Features and Functionality v1.7

- Added 01/2018- Dell's Preboot Authentication environment for Self-Encrypting Drive and Full Disk Encryption now has built-in resiliency. If the data-store for user credentials in the PBA becomes corrupted, it will revert to a known-good database. This can be manually initiated by holding the Control and Alt keys, and then pressing 'b' on the keyboard.

- The Encryption client is now supported with Windows 10 Fall Creators Update (Redstone 3 release). Upgrades to Fall Creators Update are now supported.
- SED Management and Bitlocker Manager are now supported with Windows 10 Fall Creators Update (Redstone 3 release). Upgrades to Fall Creators Update are supported, except for upgrades from Windows 7.
- Full Disk Encryption is now supported with Windows 10 Fall Creators Update (Redstone 3 release). Upgrade to Fall Creators Update will be supported in v8.17.1. In 8.17, PBA deactivation/decryption are required in order to upgrade to Fall Creators Update.
- The Encryption client local console now shows status of "In Compliance" when there are no pending policies and an initial sweep is complete, regardless whether the Encryption policy is enabled on the Dell Server.

## Resolved Technical Advisories v1.7

### Advanced Threat Prevention v1.7

- Added 05/2018 - New policies are enforced by the Advanced Threat Prevention client. [CYL-611]

### Encryption Client v8.17

- An issue that resulted in Windows Explorer crashing when logged into a domain user account has been resolved. [DDPC-4620]
- An issue that resulted in the Port Control Policy for USB ports to not work properly when connected to a TB-16 dock has been resolved. [DDPC-7446]
- Encryption External Media can now be uninstalled through the Apps list in Windows 10. [DDPC-7465]
- SDE contents are now decrypted after SDE has been turned off on an encrypted machine. [DDPC-7574]
- An issue resulting in an error message "Invalid Value for 100" on the local client when character limit had been exceeded for EMS whitelisting policies has been resolved. [DDPC-7602]
- Added 03/2018- The following hard-coded exclusions have been added for improved interoperability with Windows updates. This sweep decrypts files that are system-generated files, but will ensure that user-generated data within these folders will stay protected as either Common encrypted or SDUser encrypted data based on currently set policies. These changes can be overridden by adding a Category 3 inclusion to SDE Encryption Rules.
  - %SystemRoot%
  - %SystemRoot%\CbsTemp
 [DDPC-7881]
- An issue that resulted in a hibernation when the Secure Hibernation Policy was turned on has been resolved. [DDPC-7906]

### Preboot Authentication v8.16.1

- An issue that resulted in Preboot Authentication login failure when the Dell Security Management Server is unavailable has been resolved. [DDPC-4503, DDPC-4505, DDPC-7181]
- Added 05/2018 - The touchpad is now functional at the PBA login screen on non-UEFI computers. [DDPC-5362]
- Added 05/2018 - The touchpad is now functional after the computer resumes from sleep on non-UEFI Dell Latitude computers. [DDPC-5363]
- An issue that resulted in Encryption Enterprise users to lock their screen at PBA activation for the Sync Users at PBA Activation policy has been resolved. [DDPC-6924]
- An issue that resulted in a popup notification that warned the user to not turn off the computer during PBA configuration has been resolved. [DDPC-7019]
- Added 05/2018 - With Preboot Authentication enabled for Full Disk Encryption or Self Encrypting Drive technologies, booting into the preboot environment or manually syncing server communication no longer fail if the Dell Security Management Server is unavailable. [DDPC-7181]
- An issue that resulted in an inability to log in at Preboot Authentication after shutting down the computer during PBA synchronization. [DDPC-7336, DDPC-7584]
- An issue that resulted in an error message in PBA after replacing motherboard hardware or resetting the TPM has been resolved. [DDPC-7337]

## Full Disk Encryption v1.0

- Resetting the TPM or replacing a motherboard no longer causes the PBA to lock out. [DDOC-7337]

## Technical Advisories v1.7

### All Clients

- No Technical Advisory exists for all clients

### Dell Encryption v8.17

- No Technical Advisories exist.

### Preboot Authentication v8.16.1

- Upgrade from Windows 7 to Windows 10 Fall Creators Update (Redstone 3 release) is supported according to Microsoft's supported upgrade paths. For more information, see [Windows upgrade paths](#)

### SED Management v8.16.1

- Upgrade from Windows 7 to Windows 10 Fall Creators Update (Redstone 3 release) is supported according to Microsoft's supported upgrade paths. For more information, see [Windows upgrade paths](#)

### Full Disk Encryption v1.1

- No Technical Advisories exist.

### BitLocker Manager v8.16.1

- When upgrading the Dell BitLocker Manager and using a PIN for authentication, the user may be re-prompted to re-set the PIN on the endpoint. [DDPC-7649]
- Upgrade from Windows 7 to Windows 10 Fall Creators Update (Redstone 3 release) is supported according to Microsoft's supported upgrade paths. For more information, see [Windows upgrade paths](#)

## New Features and Functionality v1.6

- Added 12/2017 - Advanced Threat Prevention is now supported with Windows 10 Fall Creators Update (Redstone 3 release), build 1441 or later. Upgrades to Fall Creators Update are supported with build 1441 or later. Fall Creators Update is supported with OneDrive; however, OneDrive files that have been stored to the computer before the initial ATP scan are not scanned until they are opened.
- Added 12/2017 - In future version of v8.17.1, Web Protection and Client Firewall features will be supported with Windows 10 Fall Creators Update (Redstone 3 release).
- Endpoint Security Suite Enterprise now supports TLS 1.2 when used with a Dell Server v9.9 or newer.
- Endpoint Security Suite Enterprise now supports IPv6.
- Web Protection and Client Firewall features are now supported with Windows 10 Creators Update (Redstone 2).
- Full Disk Encryption is now optionally available with Endpoint Security Suite Enterprise for Dell computers running in UEFI boot mode with non-SED drives. Full Disk Encryption provides administrators central management of Preboot Authentication in addition to disk encryption, with the capability to remotely disable endpoint login and lock the device. Keys are protected with the Trusted Platform Module (TPM), preventing access to encrypted data in the event that the hard drive is removed from the computer.

- Web Protection and Client Firewall features can now be installed independently of Dell Encryption.
- A new policy enables Advanced Threat Prevention to detect and address malicious payloads with the following options:
  - Ignore - No action is taken against identified memory violations.
  - Alert - Record the violation and report the incident to the Dell Server.
  - Block - Block the process call if an application attempts to call a memory violation process. The application that made the call is allowed to continue to run.
  - Terminate - Block the process call if an application attempts to call a memory violation process and terminate the application that made the call.
- The Data Security Uninstaller is now included in all installation bundles. This utility gathers the currently installed products and removes them in the appropriate order. For more information, see [How to Run the Dell Data Security Uninstaller](#).
- Password Manager has reached End of Life. For more information, see [Product Life Cycle \(End of Support and End of Life\) Policy for Dell Data Security](#).
- Endpoint Security Suite Pro has reached End of Life. For information, see [Product Life Cycle \(End of Support and End of Life\) Policy for Dell Data Security](#).

## Resolved Technical Advisories v1.6

### All Clients

- The following issues are now resolved after an encryption sweep with the Secure Post-Encryption Cleanup policy set to an Overwrite value: The Local Management Console becomes unresponsive; File Explorer filename sorting is not functioning; or Skype displays unrecognized characters. [DDPC-5764]

### Advanced Threat Prevention v1.6

#### Resolved Customer Issues

- Added 05/2018 - Enterprise policies for Advanced Threat Prevention run successfully in disconnected mode. [CYL-629]
- Added 05/2018 - The Advanced Threat Prevention selection stays checked even if the check box for the Web Protection and Firewall option is cleared. [DDPC-5722]
- The Advanced Threat Prevention selection now remains selected during installation on a server operating system if the check box for the Web Protection and Firewall option is cleared. [DDPC-6319]

### Encryption Client v8.16

- An issue that resulted in Encryption External Media leaving some files unencrypted and renamed is resolved. [DDPC-1532]
- The Windows 10 Feature Update preparation phase will no longer fail to stop the sweep state and will not fail on updating the registry on a computer running Encryption External Media. [DDPC-4254]
- Encryption sweeps no longer pause or require manual intervention to complete. [DDPC-4499]
- Pausing encryption from the system tray icon now properly pauses the encryption sweep. [DDPC-5372]
- Added 05/2018 - An issue causing the local management console to become unresponsive or file explorer filename sorting to not function after an encryption sweep the Secure Post-Encryption Cleanup policy set to an overwrite value has now been resolved. [DDPC-5764]

#### Resolved Customer Issues

- Windows now properly resumes from hibernation when the Secure Windows Hibernation File policy is enforced. [DDPSUS-1346]
- An issue that resulted in failed activation when a user's domain did not match the managed domain is resolved. [DDPC-5378]
- Registry keys are now properly removed at uninstall. [DDPC-5410]
- Server Configuration Tool logs are now included in DiagnosticInfo. [DDPC-6114]
- An issue that resulted in failed activation of endpoints is resolved. [DDPC-6119]
- An issue that resulted in the Port Control System causing intermittent BSOD during upgrades is resolved. [DDPC-6357]
- An issue resulting in BSOD when resuming from hibernation using an NVMe drive in AHCI is resolved. [DDPC-6456]
- An issue is resolved that resulted in customized Encryption External Media dialogue boxes to display incorrectly. For more information, see [Dell Encryption External Media Dialog Customization](#) [DDPC-6537]

- Applications using Microsoft's Encrypted File System no longer conflict with Policy Based Encryption. [DDPC-6846]
- A USB 3.0 driver causing BSODs when interacting with Dell Encryption is resolved. [DDPC-6893]
- Added 03/2018- The following hard-coded SDE exclusions have been added for improved interoperability with Windows upgrades. This sweep decrypts files that are system-generated files, but will ensure that user-generated data within these folders will stay protected as either Common encrypted or SDUser encrypted data based on currently set policies. These changes can be overridden by adding a Category 3 inclusion to SDE Encryption Rules.
  - %SystemDrive%\\_SMSTaskSequence

[DDPC-6932]

- Encrypt for Sharing files created on a 64-bit computer now open on a 32-bit computer. [DDPC-6998]
- An issue that resulted in BSOD after enabling HyperVisor is resolved. [DDPC-7028]

## SED and FDE Preboot Authentication v8.16

- Inserting a smart card for PBA login on the OptiPlex 3240 All-In-One now functions as expected. [DDPC-5907]
- Keys on Canadian French and British/English keyboards now function as expected on computers running in UEFI mode. [DDPC-5369, DDPC-5969]

### Resolved Customer Issues

- An issue that resulted in an incorrect error message displaying after smart card authentication failure is resolved. [DDPC-6578]

## SED Management v8.16

### Resolved Customer Issues

- An issue that caused the Local Management Console to become unresponsive following successful Policy-Based Encryption is resolved. [DDPC-5176]

## BitLocker Manager v8.16

No Resolved Technical Advisories exist.

# Technical Advisories v1.6

## Advanced Threat Prevention v1.6

- Added 12/2017 - If users attempt to run the optional Web Protection and Firewall features with Windows 10 Fall Creators Update (Redstone 3 release), the following occur:
  - If a user attempts to install Advanced Threat Prevention and optional Web Protection and Firewall features on Windows 10 Fall Creators Update (Redstone 3 release), only Advanced Threat Prevention is installed.
  - If a user attempts to upgrade to Fall Creators Update with Advanced Threat Prevention and optional Web Protection and Firewall features installed, Windows 10 Setup prompts the user to uninstall Client Firewall and Web Protection.
  - In some circumstances, the Web Protection and Client Firewall tile displays in the Data Security Console following a failed install.
- In the Data Security Console, in the Advanced Threat Prevention Tile, "Protection" is incorrectly translated to "Disabled" in Italian. [DDPC-7455]
- Command line upgrade for Client Firewall and Web Protection requires the installers to be run in a specific order. Failure to install the components in the proper order results in upgrade failure. Run the installers in the following order:
  - **\Threat Protection\EndPointSecurity**

The following installs Web Protection and Client Firewall with default parameters (silent mode, install Client Firewall and Web Protection, override Host Intrusion Prevention, no content update, no settings saved).

```
EPSetup.exe ADDLOCAL="fw,wc" /override"hips" /nocontentupdate /nopreservesettings /
l"C:\ProgramData\Dell\Dell Data Protection\Installer Logs\McAfee" /qn
```

- **\Threat Protection\ThreatProtection\WinXXR**

The following example installs the client with default parameters (suppress the reboot, no dialogue, no progress bar, no entry in Programs list).

```
DellThreatProtection.msi /qn REBOOT=ReallySuppress ARPSYSTEMCOMPONENT=1 /! *v "<C:\ProgramData\Dell\Dell Data Protection\Installer Logs\Dell> Data Protection - Threat Protection.msi.log"
```

- **\Threat Protection\SDK**

The following command line loads certificate default parameters.

```
"Threat Protection\SDK\EnsMgmtSdkInstaller.exe" -LoadCert >"C:\ProgramData\Dell\Dell Data Protection\Installer Logs\McAfeeSDKInstallerBeforeEndPoint.log"
```

- **\Threat Protection\SDK**

The following example installs the SDK.

```
EnsMgmtSdkInstaller.exe "C:\Program Files\Dell\Dell Data Protection\Threat Prevention\DellAVAgent.exe" -InstallSDK -RemoveRightClick -RemoveMcTray > "C:\ProgramData\Dell\Dell Data Protection\Installer Logs\McAfeeSDKInstallerAfterEndPoint.log"
```

## Dell Encryption v8.16

- During installation, when entering the address as part of the SERVERHOSTNAME, it must be surrounded by brackets when using IPv6. In this scenario, a port number cannot be included as it cannot be resolved as part of the address. [DDPC-7036]

## PBA Advanced Authentication v8.16

- Advanced Authentication options display only under the following conditions:
  - When upgrading to v8.16 with the PBA inactive, Advanced Authentication options display at the Windows login screen upon the first reboot after installation of v8.16. After the next reboot, Advanced Authentication options display only if PBA is activated.
  - When upgrading to v8.16 with the PBA active, Advanced Authentication options display at the Windows login screen upon the first reboot after installation of 8.16.
  - After a clean install of v8.16, Advanced Authentication login options will not display until the PBA is activated. [DDPC-7087]
- When installing Advanced Authentication to a non-default directory, files will still be written to the default location of C:\Program Files (x86)\Dell\Dell Data Protection\Authentication\bin\. These files must remain at this location. Files being written to multiple locations will not affect functionality. [DDPC-7128]

## Preboot Authentication v8.16

## SED Management v8.16

- The Latitude 5289 does not support SED Management. [DDPC-7144]

## Full Disk Encryption v1.0

- The Latitude 5289 does not support Full Disk Encryption. [DDPC-7144]
- Full Disk Encryption is supported in managed configuration only. [DDPC-7208]
- Full Disk Encryption is not supported with BitLocker or BitLocker Manager. Do not install Full Disk Encryption on a computer on which BitLocker or BitLocker Manager is installed. [DDPC-7311]
- Full Disk Encryption requires a 180 Mb partition at the end of the drive to write the Preboot Authentication environment to the local disk. The sectors used for this partition are stored within the registry for tracking within the host operating system and the Preboot Authentication environment. If the 180 Mb partition is removed, the registry key location is: HKLM\software\Dell\Dell Data Protection\NPBA.

This key and its sub-key can be safely deleted if the Preboot Authentication environment is not in place. [DDPC-7453]

- Full Disk Encryption is not supported with the Encryption client in this release. Do not install Full Disk Encryption on a computer on which the Encryption client is installed.
- Full Disk Encryption is only supported with English operating systems.

## BitLocker Manager v8.16

- No Technical Advisories exist.

## New Features and Functionality v1.5

- Added 03/2018-Dell has introduced a change to how built-in encryption exclusions are being handled. Previously, built-in exclusions would prevent the encryption of any file that was created, or copied into a folder that was defined within these exclusion lists. Future hard-coded exclusions introduced in 8.15 and later will be protected in a way that only system generated files will no longer be encrypted, all user generated data will still be encrypted that enters these folders through a file create or a file copy action. As always, file move operations will retain the encryption status of the source folder until an encryption sweep or a change to the file is enacted.
- A new policy in Security Management Server/Security Management Server Virtual v9.8 allows administrators to block more than 100 specific categories of information on the Internet, when the optional Web Protection feature is installed.
- A new policy in Security Management Server/Security Management Server Virtual v9.8 allows the administrator to enable or disable users' ability to select **Remember Me** on the PBA login screen and customize Support dialog text.
- The Encryption client drivers pass the Hypervisor Code Integrity (HVCI) checks.
- Operating system downgrade is now supported with the Encryption client.
- SSL is no longer supported with Advanced Authentication, SED Management, or BitLocker Manager. TLS 1.0, 1.1, or 1.2 should be used rather than SSL.
- The Security Tools Mobile application has reached End of Life. For more information, see [Product Life Cycle \(End of Support and End of Life\) Policy for Dell Data Security](#).
- Windows 10 Creators Update is not yet supported with the optional Web Protection and Firewall features. For this reason, installation of these features is prevented on Windows 10 Creators Update.

## Resolved Technical Advisories v1.5

### All Clients

- The user name now displays in the Authentication Required dialog during credential enrollment in the Dell Data Security Console. [DDPC-6013]

## Advanced Threat Prevention v1.5

- Decryption performance is improved on a computer running Advanced Threat Prevention after policy is set to decrypt. [DDPC-5365]
- File cleanup during uninstallation is improved. [DDPC-5594]
- Added 05/2018 - Web Protection and Firewall are now selected by default in the installer during migration from Enterprise Edition to Endpoint Security Suite Enterprise. [DDPC-5888]

### Resolved Customer Issues

- A second license is no longer consumed when the optional Web Protection and Firewall features are installed. [DDPC-6407]

### Resolved Technical Advisories - Auto-Updates

For information about periodic Advanced Threat Prevention updates for enterprises enrolled for Agent Auto Update on the Dell Server, see <http://www.dell.com/support/article/us/en/19/SLN305419/dell-data-protection-endpoint-security-suite-enterprise-and-dell-data-protection-threat-defense-release-notes?lang=EN>. Select the **SaaS Updates** tab.

For instructions on how to enroll for Agent Auto Update on the Dell Server, refer to *AdminHelp*, accessible from the Remote Management Console.

## Encryption Client v8.15

- Performance of Encryption client upgrade that begins during an encryption sweep is improved. [DDPC-4261]
- The Encryption client now displays the EMS Device Whitelist policy rather than an error when the policy setting exceeds 2048 characters. [DDPC-4382]
- The Local Management Console Preferences setting, **Indicate encryption status using Windows Shell Extension icon overlays**, is removed. Previously, the setting was present, but icon overlay behavior is controlled by Dell Server policy rather than the local setting. [DDPC-5227]
- An issue is resolved that caused the Encryption Removal Agent to occasionally become unresponsive during decryption. [DDPC-5583]
- Encrypted files can now be accessed after operating system downgrade. [DDPC-5676]
- The Encrypt for Sharing dialog no longer continues to display after the user locks the Dell Latitude 5289. [DDPC-5719]
- Added 08/2018- An issue resulting with a blue screen after upgrading from master installer v8.12 to v8.13 with Advanced Threat Prevention installed, has now been resolved. [DDPC-5761]
- Communication between a client server running Encryption and the Dell Server is hardened.

### Resolved Customer Issues

- An issue is resolved that resulted in unresponsiveness of the computer following hibernation. [DDPC-1475]
- An issue is resolved that caused the computer to become unresponsive, followed by a Windows bugcheck. [DDPC-2349, DDPC-3284]
- Two issues are resolved that led to errors in applications that were running during an encryption sweep. [DDPC-2751, DDPC-4444]
- After upgrade to Windows 10, a second restart is no longer required in certain cases for encryption to resume. [DDPC-4080]
- Added 05/2018 - When the Encryption client is installed on Windows Server 2016 Standard Edition, the OS/Version field for the Endpoint now reads "Microsoft Windows Server 2016 Datacenter/10.0.14393" in the Dell Server. [DDPC-4836]
- The computer now restarts after Port Control policies are enabled or updated. [DDPC-5255]
- Diagnostic Info performance and error messaging are improved. [DDPC-5559]
- File names on the Start menu are now correctly translated into French. [DDPC-5895]

## Preboot Authentication v8.15

### Resolved Customer Issues

- An issue is resolved that resulted in pop-up messages persisting rather than closing. [DDPC-3604]

## SED Client v8.15

- The Crypto Erase Password policy now cryptographically erases the SED, deletes the authentication tokens for all users, and locks the SED. Afterward, only an administrator can forcibly unlock the device. [DDPLP-370, DDPC-5472, 26862]

## BitLocker Manager v8.15

- An issue is resolved that caused a BitLocker encryption delay, with the log message "volume C: waiting on SED status to be reported," on a computer running Dell Encryption. [DDPC-4840]

### Resolved Customer Issues

- An issue is resolved that related with Microsoft platform validation profile changes that prevented BitLocker encryption from beginning on Windows 10. [DDPC-5790]

## Technical Advisories v1.5

### Advanced Threat Prevention v1.5

- To block all PowerShell scripts with Advanced Threat Prevention, both the PowerShell and PowerShell Console policies must be set to **Block** in the Dell Server Remote Management Console. When both policies are set to Block, no scripts can be run,

either through the PowerShell console or the Cmd console. This ensures that PowerShell one-line scripts are not vulnerable to execution. To allow approved scripts to run through the Cmd console, select the Enable Approve Scripts in Folders (and Subfolders) policy, and add the approved scripts to the Approve Scripts in Folders (and Subfolders) policy.

**NOTE:** The PowerShell Console policy applies to PowerShell v3 and later. Windows 7 includes PowerShell v2, by default. To upgrade to PowerShell v3 on Windows 7, see [www.microsoft.com/en-us/download/details.aspx?id=34595](http://www.microsoft.com/en-us/download/details.aspx?id=34595).

[CYL-619]

- After Auto-Update to v2.0.1441, the Advanced Threat Prevention tile may no longer display in the Dell Data Security Console. To work around this issue, run the following command:

```
MSIEXEC.EXE /I "ATP_CSF_Plugins_x64.msi" APPFOLDER="C:\Program Files\Dell\Dell Data Protection\Advanced Threat Protection\Plugins" /l*v "C:\ProgramData\Dell\Dell Data Protection\Installer Logs\ATP_CSF_Plugins_x64.msi.log"
```

The .msi file can be found in the following folder, extracted from the installation package: \Advanced Threat Prevention\WinXXr\

If the issue persists, contact ProSupport. [CYL-626]

- Windows 10 Creators Update is not yet supported with the optional Web Protection and Firewall features.

### Technical Advisories - Auto-Updates

For information about periodic Advanced Threat Prevention updates for enterprises enrolled for Agent Auto Update on the Dell Server, see <http://www.dell.com/support/article/us/en/19/SLN305419/dell-data-protection-endpoint-security-suite-enterprise-and-dell-data-protection-threat-defense-release-notes?lang=EN>. Select the **SaaS Updates** tab.

For instructions on how to enroll for Agent Auto Update on the Dell Server, refer to *AdminHelp*, accessible from the Remote Management Console.

## Encryption Client v8.15

- Encryption is not supported on servers that are part of distributed file systems (DFS). [DDPC-6130]
- If the CmgHiber.sys or CmgHiber.dat file is missing from C:\windows\system32\drivers on a computer that hibernates, the computer will not resume. Ensure that disk cleaner and optimization tools do not delete these files. [DDPC-6211]
- When removable media is connected to a computer running Windows 7, 8, or 8.1 with the Subclass Storage: External Drive Control policy set to Blocked, the device name is not included in the access-blocked message or in the Local Management Console. [DDPC-6503]
- Encrypted user and common data on a computer with an HCA card is unrecoverable if the user clears HCA ownership, even though the computer is not HCA-encrypted, because the user and common keys are wrapped in the GPE (HCA) key. [DDPC-6505, DDPC-6535]

## Advanced Authentication v8.15

- SSL is no longer supported. TLS 1.0, 1.1, or 1.2 should be used rather than SSL.

## Preboot Authentication v8.15

- A few keys on a Brazilian Portuguese keyboard behave differently than expected on the Dell Precision M4800 running in UEFI mode. [DDPC-5975]
- A delay in display of the PBA login screen has been observed on the following Dell computers: Optiplex 5055, Precision 5820T, Precision 7820T, and Precision 7920T. [DDPC-6375]
- Recovery of a SanDisk X300 drive with the Recovery All bundle succeeds but may require up to two minutes to complete. [DDPC-6389]
- SSL is no longer supported. TLS 1.0, 1.1, or 1.2 should be used rather than SSL.

## SED Client v8.15

- SSL is no longer supported. TLS 1.0, 1.1, or 1.2 should be used rather than SSL.

## BitLocker Manager v8.15

- The Local Management Console does not report status of a drive that is both Dell-encrypted and BitLocker-encrypted when the drive is locked. [DDPC-6329]
- SSL is no longer supported. TLS 1.0, 1.1, or 1.2 should be used rather than SSL.

## New Features and Functionality v1.4

- Endpoint Security Suite Enterprise now includes the optional features, Client Firewall and Web Protection. The Client Firewall is a stateful firewall that checks all incoming and outgoing traffic against its list of rules. Web Protection monitors web browsing and downloads to identify threats and enforce action set by policy when a threat is detected, based on ratings for websites. Prior to upgrade to the new features, follow the instructions in [Upgrade to Endpoint Security Suite Enterprise v1.4](#).
- Advanced Threat Prevention is now supported with Server 2016.
- The Encryption client is now supported with the Windows 10 Creators Update (Redstone 2 release).
- BitLocker Manager is now supported with Server 2016.
- Added 5/2017 - Remote PBA management of local user accounts is now available.
- Endpoint Security Suite Enterprise is **not** supported with Windows Server 2008 (non-R2 version).
- Users can now access ProSupport contact information from the About screen in DDP Console.

## Resolved Technical Advisories v1.4

### Advanced Threat Prevention v1.4

#### Resolved Customer Issues

- The system tray icon is now interactive as expected when running Disconnected Mode. [DDPC-5263]

#### Resolved Technical Advisories - Auto-Updates

For information about periodic Advanced Threat Prevention updates for enterprises enrolled for Agent Auto Update on the Dell Server, see <http://www.dell.com/support/article/us/en/19/SLN305419/dell-data-protection-endpoint-security-suite-enterprise-and-dell-data-protection-threat-defense-release-notes?lang=EN>. Select the **SaaS Updates** tab.

For instructions on how to enroll for Agent Auto Update on the Dell Server, refer to *AdminHelp*, accessible from the Remote Management Console.

## Encryption Client v8.13

- An issue is resolved that occasionally resulted in access denial errors for SDE-encrypted files stored in the \users folder. [DDPC-3170]
- An activation issue with Kaspersky Small Office Security installed is resolved after upgrade to the latest version of Kaspersky. [DDPC-3388]
- All text now displays as expected in Japanese Encryption Removal Agent dialogs. Previously, some text did not display in one dialog. [DDPC-4159]
- VDI client activation error handling is improved. [DDPC-4474]
- Log files are now collected when Diagnostic Info is run on a server OS. [DDPC-5206]
- Changes to Common Encryption exclusions are now enforced while the user is logged in. [DDPC-5213]

#### Resolved Customer Issues

- Setting the registry entry, EnableNGMetadata, resolves an issue that resulted in Microsoft update failure on computers with Common key-encrypted data and performance issues related to encrypting, decrypting, or unzipping large numbers of files within a folder.

Set the EnableNGMetadata registry entry in the following location:

[HKEY\_LOCAL\_MACHINE\System\CurrentControlSet\Services\CmgShieldFFE]

"EnableNGMetadata" = dword:1

0=Disabled (default)

1=Enabled

[DDPC-694, DDPC-794, DDPSUS-863]

- An issue is resolved that resulted in access denial errors for non-domain users. [DDPC-854]
- Decryption performance is improved when SDE Encryption is enabled. [DDPC-3577, DDPSUS-975]
- An issue is resolved that occasionally caused the Encryption client to become unresponsive with warnings in the log files. [DDPC-5311]

## Advanced Authentication v8.13

- When a user is removed from a computer just before the computer is shut down, the removal process is now completed as expected. [DDPC-4260]

### Resolved Customer Issues

- An issue is resolved that resulted in a delay in displaying the User Account Control prompt. [DDPC-5017]

## Preboot Authentication v8.13

- Preboot Authentication is supported on the following computers:
  - Latitude 5280
  - Latitude 5480
  - Latitude 5580
  - Latitude E7280
  - Latitude E7480
  - Precision M5520
- The smartcard reader now functions as expected for PBA login on Dell Optiplex All-in-One computers. [DDPC-3465, DDPC-5014]
- With smart card authentication, the **Sign In** button is now enabled after the user enters the smart card PIN. [DDPC-5125]
- The updated domain now displays in the Challenge/Response dialog after the domain is changed on a computer with PBA activated. [DDPC-5132]
- The correct information is now included in the "About" information accessed from the PBA login screen. [DDPC-5178]

## SED Client v8.13

- When a user is removed from a computer just before the computer is shut down, the removal process is now completed as expected. [DDPC-4260]

## BitLocker Manager v8.13

- When a user is removed from a computer just before the computer is shut down, the removal process is now completed as expected. [DDPC-4260]
- Logging is improved. [DDPC-4305]

# Technical Advisories v1.4

## Advanced Threat Prevention v1.4

- Setting an Action in a Client Firewall rule to Block IPv4 traffic prevents client connectivity with the Dell Server. Do not set such an Action when running in Connected Mode. [DDPC-5716]
- The Client Firewall and Web Protection features of Endpoint Security Suite Enterprise v1.4 require Dell Enterprise Server or VE v9.7 or later. Before upgrading clients to use these features, Dell Server v9.7 or later must be installed and the policy, Memory Action: Exclude executable files, must be **enforced** on pre-v1.4 clients. Prior to client upgrade to the new features, refer to [Upgrade to Endpoint Security Suite Enterprise v1.4](#) for the policy's new default value. Do not begin client upgrade before the new policy is enforced on the client. [DDPS-5112]
- Endpoint Security Suite Enterprise will be supported with the Windows 10 Creators Update (Redstone 2 release) in a later release.

### Technical Advisories - Auto-Updates

For instructions on how to enroll for Agent Auto Update on the Dell Server, refer to *AdminHelp*, accessible from the Remote Management Console.

## Encryption Client v8.13

- After policy update that requires reboot, the reboot prompt occasionally displays off-screen on the Dell Latitude 7280. [DDPC-5376]
- Encryption overlay icons display on unmanaged users' files when overlay icons are enabled for managed users on the same computer. [DDPC-5415]
- High resolution prevents use of the recovery option on the Precision Mobile Workstation 7520 and 7720, due to the sizing of the recovery user interface. [DDPC-5421]
- The Local Management Console temporarily displays the messages "No fixed storage is found" and "Not connected to the encryption system" when running the Encryption client on a virtual machine that is paused after an Encryption sweep with the registry entry, EnableNGMetadata, enabled. To immediately work around this issue, close then reopen the Local Management Console. [DDPC-5567]
- On some computers, a file extraction error displays during prerequisite installation. To work around this issue if it occurs, delete files in the \temp folder and resume installation. [DDPC-5582]
- An executable file cannot be run a second time from EMS Explorer if the user runs the file but then cancels the operation at the prompt after entering the EMS password. To work around this issue, close then reopen EMS Explorer and run the file. [DDPC-5781]
- On some computers, Microsoft KB4015219 may fail to install. [DDPC-5789]

## Preboot Authentication v8.13

- Amended 8/2017 - Preboot Authentication fails with some docking stations and adapters. For a list of docking stations and adapters that are supported with PBA, see [Dell Encryption Enterprise and Personal Self-Encrypting Drive Manager Hardware System Requirements](#). [DDPC-2693, DDPC-6228]

## SED Client v8.13

- Amended 7/2017 - Configuration of self-encrypting drives for Dell's SED management differ between NVMe and non-NVMe (SATA) drives, as follows.
  - Any NVMe drive that is being leveraged as an SED – The BIOS' SATA operation must be set to RAID ON, as Dell's SED management does not support AHCI on NVMe drives.
  - Any NVMe drive that is being leveraged as an SED – The BIOS's boot mode must be UEFI and Legacy option ROMs must be disabled.
  - Any non-NVMe drive that is being leveraged as an SED – The BIOS' SATA operation must be set to AHCI, as Dell's SED management does not support RAID with non-NVMe drives.

- RAID ON is not supported because access to read and write RAID-related data (at a sector that is not available on a locked non-NVMe drive) is not accessible at start-up, and cannot wait to read this data until after the user is logged on.
- The operating system will crash when switched from RAID ON > AHCI if the AHCI controller drivers are not pre-installed.

Supported OPAL compliant SEDs require updated Intel Rapid Storage Technology Drivers, located at [Dell Endpoint Security Suite Enterprise](#).

Dell recommends Intel Rapid Storage Technology Driver version 15.2.0.0 or later, with NVMe drives.

[DDPC-5941, DDPC-6219]

## BitLocker Manager v8.13

- The top part of the option "Use a password to unlock the drive" is cut off in the BitLocker Drive Encryption dialog. [DDPC-5728]
- Added 8/2017 - Due to changes to Microsoft validation profiles level (PCRs), BitLocker Manager might not begin encrypting on Windows 10. To correct this issue, obtain and apply the Enterprise Server v9.7 update that corrects this issue or upgrade to Security Management Server v9.8. For more information about the v9.7 update, see [Dell Bitlocker Manager](#). [DDPC-5790]

## New Features and Functionality v1.3

- Endpoint Security Suite Enterprise now supports persistent and non-persistent VMware and Citrix VDI clients with Dell Data Protection Server v9.6 and later.
- Added 4/2017 - The Encryption client is now supported with Windows Server 2016 - Standard Edition, Essentials Edition, and Datacenter Edition.
- Added 4/2017 - BitLocker Manager is now supported with Server 2012 and Server 2012 R2 - Standard Edition and Enterprise Edition (64-bit).
- The PBA user interface has a new look and feel.
- New policies allow the administrator to configure the maximum number of Dell Server connection attempts and the retry interval for the Encryption client running on a server OS.
- A standalone version of Encrypt for Sharing, Encrypt4Share.exe, is now added to the <installation folder>\Dell Data Protection\Encryption folder at installation and can be accessed from the Windows Start menu.

## Resolved Technical Advisories v1.3

### Advanced Threat Prevention v1.3

- Effective policies from the Dell Server are now automatically exported and stored in C:\ProgramData\Dell\Dell Data Protection\Policy\Policy-xxxxxxx.xml, where "xxxxxxx" is the sequence number of the policy. By default, the last 10 policies received from the Server are stored. To change the default number of policies stored, change the value of the following registry key. The valid range is 0 - 100.

```
["HKEY_LOCAL_MACHINE\SOFTWARE\Dell\Dell Data Protection]
```

```
"MaxPoliciesStored" =dword:00000010
```

```
Valid range = 0 - 100
```

```
[DDPC-4583]
```

Added 05/2018 - An issue resulting with a "Not Protected" message to display until the computer was rebooted has been resolved. [CYL-435]

#### Added 4/2017 - Resolved Technical Advisories v2.0.1421

The following issues are resolved in v1.3.1421, available when an organization is enrolled for Agent Auto Update on the Dell Server. For instructions on how to enroll, refer to *AdminHelp*, accessible from the Remote Management Console.

- Fixed an issue where the Agent communicated using SSL 3.0 or TLS 1.0 only.

- Fixed an issue with a Windows device failing to generate a fingerprint.
- Resolved issue with Microsoft Word template file not being recognized when added to the whitelist.
- Fixed an issue with the Windows OS version incorrectly being reported to the Console.
- Fixed an issue with the false detection of Nsight drivers on Windows devices.
- Fixed an issue on Windows x64 devices where a malicious payload detection was causing crashes upon exit.
- Fixed an issue with 64-bit Java applications crashing.
- Fixed an issue where the CPU would spike with integration service on a Windows device.
- Resolved an issue with an inconsistency on start-up on a Windows device.
- Resolved BSOD due to exception issue with Device Control when using display port.
- Resolved an issue with the Auto-Quarantine feature preventing the EventPro application user-interface from launching on a Windows device.
- Resolved an issue with the Agent sending duplicate Syslog events to the Console.
- Fixed an issue where the Agent could cause 32-bit Java applications to crash on Windows devices.
- Fixed Script Control to not block a Microsoft Windows 10 script.
- Fixed an issue where installing the Agent MSI package using the command line without including the installation token resulted in the Agent requiring an uninstall password and the Agent could not be uninstalled.
- Fixed an issue where a USB device was not being blocked upon first use on Windows XP and Windows Server 2003 devices when Device Control was enabled and set to Block.
- Fixed an issue with WMI errors occurring on Windows devices during startup and shutdown.
- Fixed an issue with Device Control events to generate a serial number when a USB mass storage device is disabled then enabled on a Windows device.
- Fixed duplication of Device Control events for iOS USB connection to a Windows device.
- Fixed duplication of Device Control events for Android USB connection to a Windows device.
- Fixed an issue with the event log on a Windows device to include the device serial number for iOS devices.
- Fixed an issue with the Application Control folder exclusions to prevent portable executable (PE) files from manually being moved on a Windows device.
- Fixed an issue that was causing threat files to be quarantined from a macOS Samba SMB mounted drive.
- Fixed an issue with the ability to recognize a trailing backslash in Application Control folder exclusions on a Windows device.
- Fixed an Application Control issue with the ability to copy a file from a non-excluded folder to an excluded folder on a Windows device.
- Fixed an issue with the Optics to only upload Windows logs that have not been uploaded before.
- Fixed an issue with the ability to downgrade the local cloud model on macOS devices.
- Fixed an issue with Device Control events to include the detection of USB floppy drives on Windows devices.
- Fixed an issue with duplicated Device Control events being generated when connecting a USB drive to a Windows device.
- Fixed an issue with the event log on a Windows device to include the device serial number when connecting a USB device to a VMware Workstation instance.
- Fixed an issue with the event log on a Windows device to include the device serial number for an Apple iPad.
- Fixed an issue with the event log on a Windows device to include the serial number for Canon cameras.
- Fixed an issue with scanning folders externally mounted to a macOS device, where the file is not local.
- Fixed an issue with the rate that the Agent checks the status of the cloud model when the Console communication is not responsive.
- Fixed an issue with the Visual Studio App Simulator from being blocked as an exploit on macOS devices.
- Fixed an issue with the timer to add a random buffer for checking in to the Console after a connection is re-established.
- Fixed a Windows issue where memory allocated to fields in DEVFLT\_CONTEXT are not freed.
- Fixed an issue where the uploader repeats when the upload limit is reached.
- Updated the localization files to ensure translations work on OS X El Capitan.
- Fixed a Windows boot issue when the Console is unavailable.
- Fixed an issue with the macOS Sierra Beta build crashing the Agent UI.

#### **Added 4/2017 - Resolved Technical Advisories v1.2.1411**

The following issues are resolved in v1.3.1411, available when an organization is enrolled for Agent Auto Update on the Dell Server. For instructions on how to enroll, refer to *AdminHelp*, accessible from the Remote Management Console.


- Resolved a compatibility issue between Memory Protection and Windows 10 Credential Guard.
- Fixed an issue where Windows Security Center registration fails when installing the Agent via GPO
- Fixed an issue where files added to the Global Safelist were not properly waived by the Agent.
- Fixed an issue to ensure quarantined files remain quarantined, even if multiple copies of the file in question get copied to the computer.

- Fixed an issue where the ScriptCache folder was consuming too much disk space if Script Control for Office Macros was enabled. Office documents are no longer cached as part of ScriptCache; only ActiveScript and PowerShell scripts are cached.
- Fixed an issue to ensure that on-demand scans are using both the Local model as well as Cloud lookups, as with background scans.
- Resolved a compatibility issue between Memory Protection and Remote Desktop on Windows 8 computers.
- Fixed an issue where the Agent does not attempt to re-deliver device system information to the Management Console if the send operation times out.
- Fixed an issue to allow Script Control exceptions for web-based locations.
- Fixed an issue to ensure that the Background Threat Detection status is accurately reported.
- Fixed an issue where the Agent may not properly send the file hash to the Management Console, resulting in an error in the Management Console.
- Fixed an issue where the Agent does not properly register with the Management Console if the Agent is installed without network access.
- Resolved a compatibility issue between Memory Protection and Passport.
- Resolved a compatibility issue between Memory Protection and NVIDIA Nsight.
- Fixed an issue where Agents deleted from the Management Console would still attempt to connect to the Management Console to upload Agent logs.
- Resolved a compatibility issue between Memory Protection, Auto-Quarantine (AQT) and Novell Zenworks Logger.
- Fixed an issue where the Advanced Threat Protection service was not properly starting on devices using .NET 4 Client Profile.
- Fixed an issue where the Windows installation would not accept the Installation Token if the device is offline.
- Fixed an issue where the Windows OS version was incorrectly reported, causing issues with Zone Rules.
- Fixed an issue to ensure Auto-Update properly updates both the Agent and Optics.
- Resolved an issue where the Agent was not updating Optics with the Device ID if Optics was installed prior to Agent registration with the Management Console.
- Fixed an issue to ensure that Local models are fully loaded before scanning files.
- Fixed an issue to ensure that USB devices encrypted with BitLocker can be accessed.
- Fixed an issue where Optics was not properly updating the product version number in Add/Remove Programs.
- Fixed an issue where the Windows theme would crash when the device starts.
- Fixed an issue where certain files paths were causing issues for Script Control exclusions.
- Resolved an issue in Windows 8 where Advanced Threat Prevention would appear as expired under certain circumstances.
- Fixed an issue where the macOS Agent and Windows installation would not accept the Installation Token if the device is offline.
- Fixed an issue where the macOS Agent blocked the Xcode debugger from running.
- Fixed an issue where the macOS Agents will repeatedly try to upload a file to the Management Console, even if the file is too large to upload.
- Fixed an issue where Watch For New Files was not properly working for long file paths on macOS systems.
- Fixed an issue where Memory Protection was not working properly on macOS computers.
- Resolved a compatibility issue with macOS Sierra and Time Machine on non-Apple network attached storage.
- Fixed an issue where Watch For New Files was incorrectly scanning mounted network drives on macOS computers.

#### **Resolved Technical Advisories v1.2.1401.84**

The following issues are resolved in v1.2.1401.84, available when an organization is enrolled for Agent Auto Update on the Dell Server. For instructions on how to enroll, refer to *AdminHelp*, accessible from the Remote Management Console.

- Increased the detail available in the debug logs.
- Fixed an issue to properly waive files contained within archives.
- Fixed an issue where files whitelisted by certificate were incorrectly labeled as "catalog."
- Fixed an issue where a portable executable (PE) file was able to be copied onto a device with Application Control enabled.
- Fixed an issue where threats are blocked but not properly terminated (killed) in some OS X environments.
- Updated Memory Protection to include support for Metro Apps.
- Fixed an issue that caused a crash on the Windows Vista operating system.
- Fixed an issue where the user-interface notifications were not properly working for archived files.
- Fixed an issue with updating the Agent.
- Fixed an issue where Alternate Data Streams (ADS) filenames were not properly handled.
- Fixed an issue where some Memory Protection and Script Control events were not properly sent to the Console..
- Fixed an issue where the Agent UI would display erroneous text caused by the localization language folders not deploying correctly to the Cylance directory and being absent from the directory.

 **NOTE:** Agent version 1401 supports Windows 10 Anniversary Edition but does not support Device Guard or Credential Guard, optional Windows 10 security features. If these features are enabled, disable them before using the Agent.

#### Added 4/2017 - Resolved Technical Advisories - Auto-Updates

For instructions on how to enroll for Agent Auto Update on the Dell Server, refer to *AdminHelp*, accessible from the Remote Management Console.

## Encryption Client v8.12

- Debug-level logging is improved. [DDPC-2307]
- Administrative Download Utility (CMGAd) and Administrative Unlock Utility (CMGAu) are now functioning as expected with non-domain users. [DDPC-4109]
- Upgrade to Windows 10 now proceeds as expected when the installation media is stored in a folder that is encrypted with the User or Common key. [DDPC-4146]
- The Secure Windows Hibernation File and Prevent Unsecured Hibernation policies are now enforced after upgrade. [DDPC-4786]
- The WSScan **Unencrypted file in Violation** option now initiates a sweep of unencrypted files as expected, without the files having to be selected or accessed. [DDPC-4790]
- An issue is resolved that resulted in Windows Update failures with Office and Windows 10 feature updates. [DDPSUS-1323]

#### Resolved Customer Issues

- An issue is resolved that resulted in a long delay after pressing **Ctrl+Alt+Del** on a computer running Dell Desktop Authority. [DDPC-500]
- An issue is resolved that resulted in multiple restart prompts. [DDPC-4484, DDPC-4535]

## Advanced Authentication v8.12

- The Enroll Credentials window no longer occasionally displays after a computer with fingerprint or smart card enrolled credentials resumes from sleep. [DDPC-4269]
- Effective policies from the Dell Server are now automatically exported and stored in C:\ProgramData\Dell\Dell Data Protection\Policy\Policy-xxxxxxx.xml, where "xxxxxxx" is the sequence number of the policy. By default, the last 10 policies received from the Server are stored. To change the default number of policies stored, change the value of the following registry key. The valid range is 0 - 100.

```
["HKEY_LOCAL_MACHINE\SOFTWARE\Dell\Dell Data Protection]
```

```
"MaxPoliciesStored" =dword:00000010
```

```
Valid range = 0 - 100
```

```
[DDPC-4583]
```

## Preboot Authentication v8.12

- Amended 4/2017 - Preboot Authentication is supported **only** with UEFI mode (with and without SecureBoot) on the following computers:
  - OptiPlex 3050 All-In-One
  - OptiPlex 5250 All-In-One
  - OptiPlex 7450 All-In-One
  - OptiPlex 3050 Tower, Small Form Factor, Micro
  - OptiPlex 5050 Tower, Small Form Factor, Micro
  - OptiPlex 7050 Tower, Small Form Factor, Micro
  - Latitude 3180
  - Latitude 3189
  - Latitude 3380
  - Latitude 3480
  - Latitude 3580
  - Latitude 5285

- Latitude 5289
- Precision 7520
- Precision 7720
- Precision 5720 All-in-One
- When the Dell Latitude 7370 with PBA activated is docked, the user is now prompted at the PBA login screen for the authentication method set by policy rather than the access code. [DDPC-2693]
- An issue with smart card single sign-on that resulted in an error, "User did not sync with PBA," is now resolved. [DDPC-3539]
- An issue is resolved that resulted in brief and intermittent PBA login screen unresponsiveness on a UEFI computer. [DDPC-3753]
- The Options menu now remains anchored to the Options button in the PBA login screen when accessed using **Tab+Enter**. [DDPC-4104]
- After upgrade to the Windows 10 Anniversary Update on non-UEFI computers with PBA activated, the Challenge/Response popup now displays as expected after the user exceeds the maximum allowed attempts to correctly enter the password and answer Recovery Questions. [DDPC-4126]
- An issue is resolved that resulted in a computer with PBA activated reporting No OPAL Drive after resuming from hibernation. [DDPC-4476]
- Keyboard layout changes are now retained on computers with PBA activated. [DDPC-4684]

## SED Client v8.12

- When installing SED Management using the child installers, the installation no longer fails if the **Validate URL** button is pressed. [DDPC-4271]
- Effective policies from the Dell Server are now automatically exported and stored in C:\ProgramData\Dell\Dell Data Protection\Policy\Policy-xxxxxxx.xml, where "xxxxxxx" is the sequence number of the policy. By default, the last 10 policies received from the Server are stored. To change the default number of policies stored, change the value of the following registry key. The valid range is 0 - 100.

["HKEY\_LOCAL\_MACHINE\SOFTWARE\Dell\Dell Data Protection]

"MaxPoliciesStored" =dword:00000010

Valid range = 0 - 100

[DDPC-4583]

## BitLocker Manager v8.12

- Effective policies from the Dell Server are now automatically exported and stored in C:\ProgramData\Dell\Dell Data Protection\Policy\Policy-xxxxxxx.xml, where "xxxxxxx" is the sequence number of the policy. By default, the last 10 policies received from the Server are stored. To change the default number of policies stored, change the value of the following registry key. The valid range is 0 - 100.

["HKEY\_LOCAL\_MACHINE\SOFTWARE\Dell\Dell Data Protection]

"MaxPoliciesStored" =dword:00000010

Valid range = 0 - 100

[DDPC-4583]

## Technical Advisories v1.3

### All Clients

- BitLocker Manager is selected by default in the Select Features dialog of the installer. To avoid installing BitLocker Manager, clear its check box in the features list. [DDPC-5016]

## Advanced Threat Prevention v1.3

- Persistent and non-persistent clients' Protected status differs in the Dell Server Remote Management Console:  
Persistent - Following the first restart after activation, the client status is Protected.  
Non-Persistent - The client status does not change to Protected after activation, since the virtual machine does not retain the client instance after restart.

## Encryption Client v8.12

- To display advanced properties PDAID, Length, and Tag on the **Properties > Encryption tab** of an encrypted file, add the following registry setting:  
[HKEY\_LOCAL\_MACHINE\SYSTEMCurrentControlSet\ServicesCmgShieldFFE]  
"CredDBCEFAAllowProcessList"=explorer.exe,explorer.ex,explorer.e,explorer.,explorer,explore,explor,dllhost.exe,dllhost.ex,dllhost.e,dllhost,dllhost  
[DDPC-4185]
- When encryption or decryption is paused, the Compliance/Provisioning status may not be accurately indicated in the Local Management Console. [DDPC-5063]
- Added 04/2018- Currently, users have to manually delete old files individually on Encrypt4Share. The current workaround is to press **Ctrl+Shift+Click all the files** and then select remove. [DDPC-8943]

## Preboot Authentication v8.12

- Added 4/2017 - Changes to the Self-Encrypting Drive policy, Self Help Question/Answer Attempts Allowed, take effect only for users activating PBA after the policy change and for existing PBA users when the updated policy value is lower than the previous value. [DDPC-4998]
- Smart cards can be provisioned for PBA authentication on UEFI computers but cannot be used for login. This will be corrected in a later release. [DDPC-5062]

# Resolved Technical Advisories v1.2

## Advanced Threat Prevention v1.2

### Added 4/2017 - Resolved Technical Advisories v2.0.1421

The following issues are resolved in v1.2.1421, available when an organization is enrolled for Agent Auto Update on the Dell Server. For instructions on how to enroll, refer to *AdminHelp*, accessible from the Remote Management Console.

- Fixed an issue where the Agent communicated using SSL 3.0 or TLS 1.0 only.
- Fixed an issue with a Windows device failing to generate a fingerprint.
- Resolved issue with Microsoft Word template file not being recognized when added to the whitelist.
- Fixed an issue with the Windows OS version incorrectly being reported to the Console.
- Fixed an issue with the false detection of Nsight drivers on Windows devices.
- Fixed an issue on Windows x64 devices where a malicious payload detection was causing crashes upon exit.
- Fixed an issue with 64-bit Java applications crashing.
- Fixed an issue where the CPU would spike with integration service on a Windows device.
- Resolved an issue with an inconsistency on start-up on a Windows device.
- Resolved BSOD due to exception issue with Device Control when using display port.
- Resolved an issue with the Auto-Quarantine feature preventing the EventPro application user-interface from launching on a Windows device.
- Resolved an issue with the Agent sending duplicate Syslog events to the Console.
- Fixed an issue where the Agent could cause 32-bit Java applications to crash on Windows devices.
- Fixed Script Control to not block a Microsoft Windows 10 script.

- Fixed an issue where installing the Agent MSI package using the command line without including the installation token resulted in the Agent requiring an uninstall password and the Agent could not be uninstalled.
- Fixed an issue where a USB device was not being blocked upon first use on Windows XP and Windows Server 2003 devices when Device Control was enabled and set to Block.
- Fixed an issue with WMI errors occurring on Windows devices during startup and shutdown.
- Fixed an issue with Device Control events to generate a serial number when a USB mass storage device is disabled then enabled on a Windows device.
- Fixed duplication of Device Control events for iOS USB connection to a Windows device.
- Fixed duplication of Device Control events for Android USB connection to a Windows device.
- Fixed an issue with the event log on a Windows device to include the device serial number for iOS devices.
- Fixed an issue with the Application Control folder exclusions to prevent portable executable (PE) files from manually being moved on a Windows device.
- Fixed an issue that was causing threat files to be quarantined from a macOS Samba SMB mounted drive.
- Fixed an issue with the ability to recognize a trailing backslash in Application Control folder exclusions on a Windows device.
- Fixed an Application Control issue with the ability to copy a file from a non-excluded folder to an excluded folder on a Windows device.
- Fixed an issue with the Optics to only upload Windows logs that have not been uploaded before.
- Fixed an issue with the ability to downgrade the local cloud model on macOS devices.
- Fixed an issue with Device Control events to include the detection of USB floppy drives on Windows devices.
- Fixed an issue with duplicated Device Control events being generated when connecting a USB drive to a Windows device.
- Fixed an issue with the event log on a Windows device to include the device serial number when connecting a USB device to a VMware Workstation instance.
- Fixed an issue with the event log on a Windows device to include the device serial number for an Apple iPad.
- Fixed an issue with the event log on a Windows device to include the serial number for Canon cameras.
- Fixed an issue with scanning folders externally mounted to a macOS device, where the file is not local.
- Fixed an issue with the rate that the Agent checks the status of the cloud model when the Console communication is not responsive.
- Fixed an issue with the Visual Studio App Simulator from being blocked as an exploit on macOS devices.
- Fixed an issue with the timer to add a random buffer for checking in to the Console after a connection is re-established.
- Fixed a Windows issue where memory allocated to fields in DEVFLT\_CONTEXT are not freed.
- Fixed an issue where the uploader repeats when the upload limit is reached.
- Updated the localization files to ensure translations work on OS X El Capitan.
- Fixed a Windows boot issue when the Console is unavailable.
- Fixed an issue with the macOS Sierra Beta build crashing the Agent UI.

#### **Added 4/2017 - Resolved Technical Advisories v1.2.1411**

The following issues are resolved in v1.2.1411, available when an organization is enrolled for Agent Auto Update on the Dell Server. For instructions on how to enroll, refer to *AdminHelp*, accessible from the Remote Management Console.


- Resolved a compatibility issue between Memory Protection and Windows 10 Credential Guard.
- Fixed an issue where Windows Security Center registration fails when installing the Agent via GPO
- Fixed an issue where files added to the Global Safelist were not properly waived by the Agent.
- Fixed an issue to ensure quarantined files remain quarantined, even if multiple copies of the file in question get copied to the computer.
- Fixed an issue where the ScriptCache folder was consuming too much disk space if Script Control for Office Macros was enabled. Office documents are no longer cached as part of ScriptCache; only ActiveScript and PowerShell scripts are cached.
- Fixed an issue to ensure that on-demand scans are using both the Local model as well as Cloud lookups, as with background scans.
- Resolved a compatibility issue between Memory Protection and Remote Desktop on Windows 8 computers.
- Fixed an issue where the Agent does not attempt to re-deliver device system information to the Management Console if the send operation times out.
- Fixed an issue to allow Script Control exceptions for web-based locations.
- Fixed an issue to ensure that the Background Threat Detection status is accurately reported.
- Fixed an issue where the Agent may not properly send the file hash to the Management Console, resulting in an error in the Management Console.
- Fixed an issue where the Agent does not properly register with the Management Console if the Agent is installed without network access.
- Resolved a compatibility issue between Memory Protection and Passport.

- Resolved a compatibility issue between Memory Protection and NVIDIA Nsight.
- Fixed an issue where Agents deleted from the Management Console would still attempt to connect to the Management Console to upload Agent logs.
- Resolved a compatibility issue between Memory Protection, Auto-Quarantine (AQT) and Novell Zenworks Logger.
- Fixed an issue where the Advanced Threat Protection service was not properly starting on devices using .NET 4 Client Profile.
- Fixed an issue where the Windows installation would not accept the Installation Token if the device is offline.
- Fixed an issue where the Windows OS version was incorrectly reported, causing issues with Zone Rules.
- Fixed an issue to ensure Auto-Update properly updates both the Agent and Optics.
- Resolved an issue where the Agent was not updating Optics with the Device ID if Optics was installed prior to Agent registration with the Management Console.
- Fixed an issue to ensure that Local models are fully loaded before scanning files.
- Fixed an issue to ensure that USB devices encrypted with BitLocker can be accessed.
- Fixed an issue where Optics was not properly updating the product version number in Add/Remove Programs.
- Fixed an issue where the Windows theme would crash when the device starts.
- Fixed an issue where certain files paths were causing issues for Script Control exclusions.
- Resolved an issue in Windows 8 where Advanced Threat Prevention would appear as expired under certain circumstances.
- Fixed an issue where the macOS Agent and Windows installation would not accept the Installation Token if the device is offline.
- Fixed an issue where the macOS Agent blocked the Xcode debugger from running.
- Fixed an issue where the macOS Agents will repeatedly try to upload a file to the Management Console, even if the file is too large to upload.
- Fixed an issue where Watch For New Files was not properly working for long file paths on macOS systems.
- Fixed an issue where Memory Protection was not working properly on macOS computers.
- Resolved a compatibility issue with macOS Sierra and Time Machine on non-Apple network attached storage.
- Fixed an issue where Watch For New Files was incorrectly scanning mounted network drives on macOS computers.

#### **Added 2/2017 - Resolved Technical Advisories v1.2.1401**

The following issues are resolved in v1.2.1401, available when an organization is enrolled for Agent Auto Update on the Dell Server. For instructions on how to enroll, refer to *AdminHelp*, accessible from the Remote Management Console.

- Increased the detail available in the debug logs.
- Fixed an issue to properly waive files contained within archives.
- Fixed an issue where files whitelisted by certificate were incorrectly labeled as "catalog."
- Fixed an issue where a portable executable (PE) file was able to be copied onto a device with Application Control enabled.
- Fixed an issue where threats are blocked but not properly terminated (killed) in some OS X environments.
- Updated Memory Protection to include support for Metro Apps.
- Fixed an issue that caused a crash on the Windows Vista operating system.
- Fixed an issue where the user-interface notifications were not properly working for archived files.
- Fixed an issue with updating the Agent.
- Fixed an issue where Alternate Data Streams (ADS) filenames were not properly handled.
- Fixed an issue where some Memory Protection and Script Control events were not properly sent to the Console.
- Fixed an issue where the Agent UI would display erroneous text caused by the localization language folders not deploying correctly to the Cylance directory and being absent from the directory.

 **NOTE:** Agent version 1401 supports Windows 10 Anniversary Edition but does not support Device Guard or Credential Guard, optional Windows 10 security features. If these features are enabled, disable them before using the Agent.

#### **Resolved Technical Advisories v1.2.1391**

The following issues are resolved in v1.2.1391, available when an organization is enrolled for Agent Auto Update on the Dell Server. For instructions on how to enroll, refer to *AdminHelp*, accessible from the Remote Management Console.

- Added support for detecting 32-bit PowerShell and Active Script processes on 64-bit operating systems.
- Fixed an Agent installation error when the Installation Token contains spaces.
- Reduced the frequency of WMI state logs in Not Verbose mode.
- Include archive files in the Daily Upload Limit and only log one upload limit exceeded message per day, once the threshold is met.
- Fixed an issue with Memory Protection incompatibilities with BeyondTrust PowerBroker and AppSense.
- Fixed an issue with Microsoft PowerPoint 2016 not launching on a Windows 10 system when Memory Protection is enabled.
- Fixed an issue with Citrix users unable to logon after installing Advanced Threat Prevention on a server.

- Addressed an issue where enabling Memory Protection on Windows Server 2012 with vShield resulted in a black screen on Remote Desktop (RDP) login/logout.
- Increased the details for Memory Protection events for Verbose logging.
- Fixed an issue where no event was reported to the Server for remote script execution.
- Addressed conflicts with the Luminex driver.
- Fixed an issue where enabling Memory Protection would cause a black screen to display when a user logged in to the device.
- Addressed an issue to handle a corrupt local Advanced Threat Prevention database gracefully.
- Fixed an issue to prevent file execution before the Advanced Threat Prevention service starts up and that renaming the installation directory cannot be used as a method to prevent Advanced Threat Prevention from starting.
- Fixed an issue with MiraCast Wi-Fi Direct on a Microsoft Windows 10 system running the Agent.
- Fixed an issue when removing a Logitech webcam from a system running the Agent.
- Fixed an issue with the Microsoft Windows 10 Anniversary Edition (build 1607) and the Agent.
- Increased the wait time for Advanced Threat Prevention services to stop during the update process.
- Addressed an issue where attaching Microsoft Word files to emails took longer than expected when Watch for New Files was enabled.
- Fixed an issue to properly report the Background Threat Detection status in the Agent UI and Console.
- Addressed an issue to better normalize file paths for Memory Protection.
- Improved the signature verification process.
- Fixed an issue where changing the Copy File Samples path in a policy in the Server would not update the path in the Agent.
- Fixed an issue where enabling Memory Protection would cause a black screen to display when a user logged in to the device

#### Added 4/2017 - Resolved Technical Advisories - Auto-Updates

For information about additional periodic Advanced Threat Prevention updates for enterprises enrolled for Agent Auto Update on the Dell Server, see <http://www.dell.com/support/article/us/en/19/SLN305419/dell-data-protection-endpoint-security-suite-enterprise-and-dell-data-protection-threat-defense-release-notes?lang=EN>. Select the **Saas Updates** tab.

For instructions on how to enroll for Agent Auto Update on the Dell Server, refer to *AdminHelp*, accessible from the Remote Management Console.

## Encryption Client v8.11

- An issue is resolved that resulted in the Local Management Console appearing unresponsive while the Encryption client performed tasks in the background. [DDPC-2769]
- Slotted activation now proceeds as expected for users who change their passwords before activation. [DDPC-3279]
- The WSScan user interface now opens to the option of Unencrypted Files, as expected, when commands `-ua-`, `-ua`, and `-uav` are used to launch the user interface. [DDPC-3473]
- An issue is resolved that caused the Shield service to occasionally crash when the user logged out. [DDPC-3939]
- Added 05/2018 - Aventail Access Manager is now supported with Encryption client on Windows 10 computers. [DDPC-4335]

#### Resolved Customer Issues

- An issue is resolved that resulted in the user's temporary inability to access User and Common encrypted files due to a timeout in communication with the Shield service. [DDPC-2230, DDPC-3486, DDPC-4134]
- Sparse files are no longer populated during encryption and decryption sweeps. [DDPC-3201]
- WSScan now functions as expected when processing file names longer than 260 characters. [DDPC-3928]

## Preboot Authentication v8.11

- An issue is resolved that resulted in the computer becoming unresponsive when a smart card was inserted during startup on the Dell Latitude E5270, E5470, E5570, E7270, E7470, or Precision M3510. [DDPC-4547]
- Preboot Authentication is supported with UEFI mode **only** on the following computers:
  - Latitude 5280
  - Latitude 5480
  - Latitude 5580
  - Latitude E7280
  - Latitude E7480
  - Precision 3520

# Technical Advisories v1.2

## Advanced Threat Prevention v1.2

- Added 8/2017 - The Advanced Threat Prevention tile displays Not Protected until the computer is restarted a second time. Occasionally, it is necessary to restart the DellMgmtAgent service. [CYL-435]

## Encryption Client v8.11

- Cumulative encryption exclusions are now automatically applied when the Encryption client is upgraded. This will require an encryption sweep for each user upgraded to v8.11 or later. However, subsequent updates will require a sweep only if the update includes new exclusions. [DDPC-1334, DDPC-5138]
- The user receives an access denied error when attempting to access removable media, although policy is set to allow full access to unShielded media. [DDPC-4523]
- After upgrade to Windows 10 Fall Update using WSProbe -E on a computer with Hardware Crypto Accelerator, during re-encryption with WSProbe -R, the Local Management Console freezes and a message displays regarding HCA key backup and provisioning. [DDPC-4645]

## Advanced Authentication v8.11

- When dual authentication is configured for a user, but one of the authentication options is not yet enrolled, the icon for the unenrolled option does not display on the user's logon screen. [DDPC-4690]

# New Features and Functionality v1.1.1

- A new Advanced Threat Protection Agent Auto Update feature is available and can be enabled from **Services Management** in the left pane of the Remote Management Console. Enabling Agent Auto Update allows clients to automatically download and apply updates from the Advanced Threat Protection server. Updates are released monthly.
- Advanced Threat Protection has Enhanced Script Controls for Powershell to mitigate against Powershell attack vectors. This feature is available for the Advanced Threat Protection client with build 1391, available in early October. To enable this feature on the client, either enable auto update or go to the FTP site to get the update to deploy.
- Advanced Threat Protection has Enhanced Script Controls to protect against malicious Microsoft Office macros. This feature is available for the Advanced Threat Protection client with build 1391, available in early October. To enable this feature on the client, either enable auto update or go to the FTP site to get the update to deploy.
- Advanced Threat Protection has enhanced "Memory Action: Exploitation" to protect against malicious payloads created using the Metasploit toolkit. This feature is available for the Advanced Threat Protection client with build 1391, available in early October. To enable this feature on the client, either enable auto update or go to the FTP site to get the update to deploy.
- The Encryption client now supports Microsoft Windows 10 Anniversary Update (Redstone release).
- Customers upgrading to Windows 10 from an earlier version of Windows OS are no longer required to decrypt and re-encrypt data at OS update.
- The Encryption client now supports Audit Mode. Audit Mode allows administrators to deploy the Encryption client as part of the corporate image, rather than using a third-party SCCM or similar solutions to deploy the Encryption client. To suppress activation until deployment is complete, install the Encryption client and perform the necessary restart when the configuration computer is in Audit Mode.
- A new policy allows the administrator to hide Encryption overlay icons in File Explorer for managed users.
- The Encryption client and BitLocker Manager are now supported with TPM 2.0.

# Resolved Technical Advisories v1.1.1

## Advanced Threat Protection v1.1.1

- If Endpoint Security Suite Enterprise is uninstalled and then reinstalled on the same computer, committing a policy change at the Dell Data Protection Server is no longer necessary for the endpoint to receive policies. [DDPC-1616, CSF-1305]

## Encryption Client v8.10.1

- A timeout message logged during a failed activation has been modified to clarify the timeout period in milliseconds. [DDPC-2625]
- On computers running Windows 10 Education Edition, log files are now stored in \ProgramData\Dell\Dell Data Protection\Encryption as expected, rather than in \ProgramData\Application Data\Dell\Dell\Data Protection\Encryption\.[DDPC-2651]
- An issue that caused the computer to very rarely become unresponsive when renaming a file has been resolved. [DDPC-3086]
- An issue that caused a prompt to reboot in some cases with SDE encryption enabled is resolved. [DDPC-3525]
- If the activation prompt times out for a second or subsequent user on a computer with an activated user, the prompt now displays again. [DDPC-3705]
- UEFI computers with Secure Boot enabled now boot as expected after Microsoft Security Bulletin MS16-100 is applied. [DDPC-4032]
- Added 12/2016 - Hardening against credential update failures within the Encryption client is now enabled by default. [DDPC-936]

## Preboot Authentication v8.10.1

- An issue is resolved that previously prevented users from authenticating on some non-UEFI computers when PBA was configured for smart card only. [DDPC-2578]

# Technical Advisories v1.1.1

## Advanced Threat Protection v1.1.1

- No Technical Advisories exist.

## Encryption Client v8.10.1

- The recovery file that is downloaded from the Dell Data Protection Server does not execute with the provided recovery image, and the following message displays: "The subsystem needed to support the image type is not present." [DDPC-2409]
- When migrating from one edition of Windows to a different edition during a Windows 10 upgrade, the Encryption client is not migrated. The same issue occurs if either the option to keep only personal files or to keep nothing is selected during a Windows 10 upgrade. To resolve this issue, reinstall the Encryption client after upgrade. [DDPC-4191]
- Direct upgrade from v8.5.1 and earlier on 32-bit operating systems is not supported. To work around this issue, uninstall the previous version then install the latest version. [DDPC-4268]

# New Features and Functionality v1.1

- Amended 6/2017 - Dell Data Protection | Endpoint Security Suite Enterprise is now supported on the following server operating systems:
  - Windows Server 2008 R2
  - Windows Server 2012

- Windows Server 2012 R2
- Dell Data Protection | Server Encryption is now supported. Server Encryption provides remote management of servers, including the following:
  - Software encryption
  - Port control
  - Removable storage encryption
  - Support for maintenance scheduling, which allows control over enforcement of policies that require reboot
- Endpoint Security Suite Enterprise now includes an automatic client update feature. This feature automatically delivers the latest advanced threat prevention updates to clients, with the latest threat detection algorithms tested and approved by Dell, without requiring a new Endpoint Security Suite Enterprise release. This feature is disabled by default. To enable the automatic update feature, contact Dell ProSupport at 877-459-7304 Ext. 4310039.
- The Windows USB selective suspend feature is now supported.
- Beginning with v8.9.3, Dell Data Protection | Hardware Crypto Accelerator is not supported. Installation and upgrade do not proceed if Hardware Crypto Accelerator is detected and the computer is disk encrypted with it. In cases where Hardware Crypto Accelerator is installed but the computer is not disk not encrypted with it, upgrade will proceed. However, Hardware Crypto Accelerator will be ignored. The last Endpoint Security Suite Enterprise client version to support Hardware Crypto Accelerator functionality is v1.0.1. Support for v1.0.1 will continue through April 8, 2020.

## Resolved Technical Advisories v1.1

### Advanced Threat Protection v1.1

- After upgrade to Windows 10 and restart, the Enrollments and Password Manager tiles display as expected in the DDP Console. [DDPC-2322]
- An issue that caused a Windows 10 computer running the Encryption client to become unresponsive after restart is resolved. [DDPC-2336]
- After upgrade from a previous Endpoint Security Suite version the popup message, "The system information has been copied to the clipboard" from the **DDP Console system tray icon > About > Copy Info**, now closes when the user presses the **Enter** key to select **OK**. [DDPC-2394]
- An issue that caused the DDP Console to become unresponsive due to an unhandled exception is resolved. [DDPC-3480]

### Encryption Client v8.9.3

- Installer logging of launch conditions is improved. [DDPC-918]
- An issue that resulted in a computer occasionally becoming unresponsive after reboot is now resolved. [DDPC-1255]
- The Encryption Removal Agent no longer crashes during decryption of HCA- or SDE-encrypted files if the key bundle is missing or inaccessible to the Agent. Instead, a message displays that files could not be decrypted. [DDPC-1359]
- An issue that caused the Shield Service to crash is now resolved. [DDPC-2189]
- An issue that led to unresponsiveness after restarting a Windows 10 computer running Advanced Threat Protection is now resolved. [DDPC-2336]
- An issue that caused a restart and lock at the Windows startup screen on Windows 7 computers running Bitdefender Antivirus is resolved. [DDPC-2561, DDPSUS-842]
- SDE encryption now proceeds on computers with HCA or a SED, and a log entry stating SDE policies are blocked due to FVE or a SED disk no longer displays. SDE Encryption is now enabled by default in new installations and upgrades, based on the registry entry HKLM\Software\Microsoft\Windows NT\CurrentVersion\Winlogon\CMgShield\AlwaysApplySDE set to "1." [DDPC-3273]
- Encryption handling of files that are always in use is improved. [DDPC-3331, DDPC-3333, DDPC-3334]
- Additional data is now provided to Dell Data Protection Server for endpoint status reporting. [DDPC-3332, DDPC-3335]
- Windows logon with a smart card now proceeds as expected. [DDPSUS-855]
- Encryption sweep performance is improved on Windows 10 computers running Sophos. [DDPSUS-866]
- An issue that resulted in occasional computer unresponsiveness after installation but before activation is resolved. [DDPSUS-1037]
- An issue that led to multiple restarts is now resolved. [DDPSUS-1087]

## Advanced Authentication v8.10

- On Dell Latitude 3450 and 3550 computers running Windows 10, fingerprint authentication now proceeds as expected. [DDPC-1598/CSF-772]
- After restoring credentials in Password Manager, a second authentication prompt no longer displays. [DDPC-1617]
- Password Manager logon now functions as expected with Dell Remote Management Console logon. [DDPC-2356]

## Preboot Authentication v8.10


- When the drive letter of a NTFS self-encrypting drive is changed on a computer with Preboot Authentication activated, the computer no longer becomes unresponsive. [DDPC-2973]

# Technical Advisories v1.1

## Advanced Threat Protection v1.1

- Policies display in the DDP Console Policies page only if they are enabled in the Remote Management Console. [DDPC-3545]
  - Added 09/2016 - If the child installer is run a second time after installation is complete, Advanced Threat Protection is uninstalled. To work around this issue, run the master installer to repair an installation. [DDPC-4155]
  - When upgrading to v1.1, the previous version must be uninstalled. Before upgrade, follow these instructions:
1. Ensure that the installation files for the currently installed client are stored in a safe location where they can be accessed after the upgrade.
  2. Obtain the product code.

Enter the following Windows PowerShell command:



```
PS C:\Users\User> Get-WmiObject Win32_Product | Where-Object {$_.Name -like '*Cylance*'} | FT IdentifyingNumber, Name, LocalPackage
IdentifyingNumber      Name      LocalPackage
-----
{6AD61075-1F1F-4F95-8D57-E62AEE41A60F} Cylance PROTECT C:\windows\Installer\b7e97f19.msi
PS C:\Users\User>
```

Figure 1. Windows power shell

3. Run the v1.1 installer to upgrade the client.  
For installation instructions, see the *Endpoint Security Suite Enterprise Advanced Installation Guide* or *Endpoint Security Suite Enterprise Basic Installation Guide*.
4. After upgrade, open a command prompt in the same location as the installation files that you stored in an accessible location in [step 1](#), and enter the following command:

```
msiexec.exe /X {6AD61075-1F1F-4F95-8D57-E62AEE41A60F} /norestart
[CYL-249]
```

## Encryption Client v8.9.3

- Standard practice is that the master installer version is the same version number as the Encryption client installer. However, in this release, the master installer is v8.10 and the Encryption installer is v8.9.3. Versions will be aligned in the future, to avoid confusion. In the event that you need support, ProSupport will need your **Encryption client** version number.
- To upgrade with HCA-encrypted data, issue a policy of Hardware Crypto Accelerator (HCA) = Off. After data is unencrypted, issue a policy of Policy-Based Encryption = On. Then run the v8.10/v8.9.3 installation. [DDPC-2608]

- Added 09/2016 - In the rare case that a user with smart card authentication becomes deactivated, smart card authentication succeeds for the first logon after restart for each user but fails on subsequent smart card logon attempts until at least one user restarts the computer. [DDPC-2721]
- After a computer crash or forced shutdown, encrypted files occasionally become unavailable. To work around this issue, run WSDDeactivate then reactivate the Encryption client. [DDPC-3228]

## SED Client v8.10

- Added 09/2016 - When PBA is activated on a Windows 7 computer without Microsoft Security Advisory 3033929 installed, the computer becomes unstable when resuming from sleep (S3). To work around this issue, install Microsoft Security Advisory 3033929 before installing the SED Client. If the SED Client is already installed, deactivate PBA and uninstall. After installing the Microsoft Security Advisory, reinstall the SED Client. For more information, see [Microsoft Security Advisory](#). [DDPC-4237]

## Preboot Authentication v8.10

- Occasionally, the access code prompt displays rather than the Preboot Authentication login screen on computers with a wired network connection. [DDPC-3188]
- Added 09/2016 - When PBA is activated on a Windows 7 computer without Microsoft Security Advisory 3033929 installed, the computer becomes unstable when resuming from sleep (S3). To work around this issue, install Microsoft Security Advisory 3033929 before installing the SED Client. If the SED Client is already installed, deactivate PBA and uninstall. After installing the Microsoft Security Advisory, reinstall the SED Client. For more information, see [Microsoft Security Advisory](#). [DDPC-4237]

## Resolved Technical Advisories v1.0.1

### All Clients

- Inaccurate "Failed to open service" error messages no longer display in the output of the FindMyProblem utility. [DDPC-1188]

### Advanced Threat Protection v1.0.1

- No Resolved Technical Advisories exist.

### Encryption Client v8.9.1

- A Dell Data Protection-encrypted Windows 10 computer can now be upgraded to the Windows 10 Fall Update, after a few prerequisites are met. The prerequisites must be met, due to a change Microsoft has made to the Windows update process beginning with Windows 10. For more information, see [Upgrade to the Windows 10 Anniversary Update](#). [DDPC-928, DDPC-1146, DDPC-1443]
- SDE key material download failures now result in a meaningful log entry, "Failed to validate key material bundle against the device." Erroneous validation failure warnings no longer display. [DDPC-960, DDPC-961]
- Corrected a misspelling of szRegValueLoginTimeout in the registry override variable and log message. [DDPC-966]
- The computer now boots as expected after Intel Rapid Storage Technology drivers are installed. [DDPC-1246]
- The HideOverlayIcons registry setting that is used to hide the encryption icons for all managed users on a computer after the original installation now works as expected. The HideOverlayIconsOverlay registry setting now effectively hides Dell Data Protection Encryption overlay icons when File Explorer is refreshed or reopened. [DDPC-1267, DDPC-1327]
- External Media Shield Explorer now launches properly after more than one incorrect password entry when accessing media that has been provisioned on a Mac. [DDPC-1273]
- A few WSProbe options have been deprecated to improve security. The WSProbe utility no longer supports the following options: -u (enable or disable Application Data Encryption), -x (exclude application from Application Data Encryption), and -i (revert an excluded application back to included in Application Data Encryption). [DDPC-1279]
- All characters of the 32-character Endpoint Code now fully display in the External Media Shield manual authentication dialog. [DDPC-1295]

- Excess logging of file-create operations no longer occurs. [DDPC-1339]
- An issue that caused excessive memory consumption has been resolved.[DDPC-1468]
- On a Windows computer, External Media Shield now successfully opens files and folders named with accented characters that are stored on external media and provisioned using a Mac computer. [DDPC-1517]
- When encryption models are changed (SDE to HCA) after an encryption sweep has completed, the computer no longer experiences a temporary blue screen. Previously, this occurred while key types were swapped, and allowing the computer to reboot typically restored functionality. [DDPC-1536]
- External Media Shield no longer displays Access Denied errors when the Windows Media Encryption and Windows Port Control policies are set to Off and Disabled. [DDPC-1572]
- Processes related with pop-up notifications during the encryption sweep have been streamlined, reducing CPU usage. [DDPC-2115]
- Decryption with the Encryption Removal Agent at uninstallation now succeeds. Previously, in a few cases, decryption began but did not finish sweeping the entire volume. [DDPSUS-751]
- An issue that caused multiple reboots during installation or upgrade on some computers is resolved. [DDPSUS-766]

## Advanced Authentication v8.9.1

- A non-administrator user can now run an application through User Account Control on a Windows 8, 8.1, or 10 computer with Security Tools installed. [CSF-1313, DDPC-1578]
- Windows password entry now succeeds when entered first in dual-factor authentication on Windows 10, after upgrade to the Windows 10 Fall Update. [DDPC-1675]

## SED Client v8.9.1

- A non-administrator user can now run an application through User Account Control on a Windows 8, 8.1, or 10 computer with Security Tools installed. [CSF-1313, DDPC-1578]
- Volumes with Unicode strings in their serial numbers are now correctly reported in inventory. [DDPC-1899]
- Added 07/2016 - The following Dell computer models are supported with UEFI:

Dell Computer Models - UEFI Support			
<ul style="list-style-type: none"> <li>○ Latitude 7370</li> <li>○ Latitude E5270</li> <li>○ Latitude E5470</li> <li>○ Latitude E5570</li> <li>○ Latitude E7240</li> <li>○ Latitude E7250</li> <li>○ Latitude E7270</li> <li>○ Latitude E7275</li> <li>○ Latitude E7350</li> <li>○ Latitude E7440</li> <li>○ Latitude E7450</li> <li>○ Latitude E7470</li> <li>○ Latitude 12 Rugged Extreme</li> <li>○ Latitude 12 Rugged Tablet (Model 7202)</li> <li>○ Latitude 14 Rugged Extreme</li> <li>○ Latitude 14 Rugged</li> </ul>	<ul style="list-style-type: none"> <li>○ Precision M3510</li> <li>○ Precision M4800</li> <li>○ Precision M5510</li> <li>○ Precision M6800</li> <li>○ Precision M7510</li> <li>○ Precision M7710</li> <li>○ Precision T3420</li> <li>○ Precision T3620</li> <li>○ Precision T7810</li> </ul>	<ul style="list-style-type: none"> <li>○ Optiplex 3040 Micro, Mini Tower, Small Form Factor</li> <li>○ Optiplex 3046</li> <li>○ Optiplex 5040 Mini Tower, Small Form Factor</li> <li>○ OptiPlex 7020</li> <li>○ Optiplex 7040 Micro, Mini Tower, Small Form Factor</li> <li>○ Optiplex 3240 All-In-One</li> <li>○ Optiplex 7440 All-In-One</li> <li>○ OptiPlex 9020 Micro</li> </ul>	<ul style="list-style-type: none"> <li>○ Venue Pro 11 (Models 5175/5179)</li> <li>○ Venue Pro 11 (Model 7139)</li> </ul>

## Preboot Authentication v8.9.1

- A non-administrator user can now run an application through User Account Control on a Windows 8, 8.1, or 10 computer with Security Tools installed. [CSF-1313, DDPC-1578]
- The issue that led to shutdown at PBA login on a computer running ActivClient v7.0.2 is resolved. [DDPC-1898]

- Volumes with Unicode strings in their serial numbers are now correctly reported in inventory. [DDPC-1899]

## BitLocker Manager v8.9.1

- Volumes with Unicode strings in their serial numbers are now correctly reported in inventory. [DDPC-1899]

## Technical Advisories v1.0.1

### Advanced Threat Protection v1.0.1

- Advanced Threat Protection cannot be upgraded in place from v1.0 to v1.0.1. To work around this issue, uninstall Advanced Threat Protection v1.0 and install Advanced Threat Protection v1.0.1:

1. Run the following command line to uninstall Advanced Threat Protection:

```
msiexec.exe /X {6AD61075-1F1F-4F95-8D57-E62AEE41A60F} /norestart
```

If uninstallation does not succeed, follow these steps:

- a. Enter the following powershell command to get the product code for the currently installed version:

```
Get-WmiObject win32_product | Where-object {$_.Name -like "*Cyl*"} | FT IdentifyingNumber, Name, Version
```

The product code displays.

- b. From an administrative command prompt, run the following command:

```
Msiexec.exe /x <productcodehere> /norestart
```

2. Extract the Endpoint Security Suite Enterprise installer:

```
DDPSuite.exe /z""EXTRACT_INSTALLERS=C:\Extracted\ ""
```

3. Run the following at a command prompt:

```
AdvancedThreatProtection_x64.msi /qn REBOOT=ReallySuppress ARPSYSTEMCOMPONENT=1 /l*v "C:\ProgramData\Dell\Dell Data Protection\Installer Logs\ATP.log" APPFOLDER="C:\Program Files\Dell\Dell Data Protection\Advanced Threat Protection"
```

[DDPKM-871]

## New Features and Functionality v1.0

Endpoint Security Suite Enterprise includes the following components:

- Advanced Threat Prevention provides real-time threat detection by analyzing potential file executions for malware in both the operating system and memory layers, to prevent the delivery of malicious payloads. Control of execution at the endpoint allows for accurate and effective detection of malicious threats - even those that have never been seen before. Advanced Threat Prevention uses machine learning techniques that allow detection of new malware, viruses, bots and unknown future variants, where signatures and sandboxes fail. Memory protection strengthens basic operating system protection features by providing an additional layer to detect and deny certain behaviors that are commonly used by exploits.
- The Dell Data Protection | Encryption client provides data-centric, policy-based protection of data on any device or external media, allowing enterprises to manage encryption policies for multiple endpoints and operating systems from the DDP Server. With the optional DDP | Hardware Crypto Accelerator, the Dell Data Protection | Encryption client offloads encryption processing to hardware for enhanced performance over software encryption and supports the highest level of FIPS 140-2 protection commercially available for system disks.
- Advanced Authentication fully integrates authentication options, including fingerprint, smart card, and contactless smart card readers, with Dell ControlVault for secure hardware credential processing. For added security, the Dell FIPS 140-2 compliant TPM is available on select Dell Latitude laptops and select Dell Precision mobile workstations.
- The SED client provides centralized, secure management of local and remote self-encrypting drives across an organization and seamlessly integrates with the other Endpoint Security Suite Enterprise components. All policy, authentication, management tasks, and storage and retrieval of encryption keys are available from the DDP Server, reducing the work of keeping critical data safe, and reducing the risk that systems are unprotected in the event of loss or attempts at unauthorized access.

- BitLocker Manager seamlessly integrates with the other Endpoint Security Suite Enterprise components through the DDP Server to provide flexible policy enforcement and TPM management, reducing the strain on an organization's IT resources. Reporting and auditing processes are simplified, with comprehensive protection and FIPS compliance. Extensive reporting and auditing capabilities and secure recovery key escrow help auditors easily determine compliance.

## Technical Advisories v1.0

### Advanced Threat Protection v1.0

- To avoid very long installation times due to Windows updates running on Windows 7, ensure that all updates are installed before beginning installation. If Windows KB2913763 is not yet installed, install it then reboot before installing Endpoint Security Suite Enterprise. For more information, see <https://support.microsoft.com/en-us/kb/2913763>. [CSF-847, DDPC-1619]
- After upgrade to Windows 10 with Advanced Threat Protection installed, the Advanced Threat Protection Service is not available. To work around this issue, either uninstall and reinstall Advanced Threat Protection or manually add the service with the appropriate command, listed below.

If Advanced Threat Protection was installed with the Endpoint Security Suite master installer, use this command:

```
sc create CylanceSvc binpath="C:\Program Files\Dell\Dell Data Protection\Advanced Threat protection\CylanceSvc.exe" start=auto displayname="Cylance PROTECT"
```

If Advanced Threat Protection was installed with the child installer, use this command:

```
sc create CylanceSvc binpath="C:\Program Files\Cylance\Desktop" start=auto displayname="Cylance PROTECT" [CSF-998, DDPC-3833]
```

- Before installation on a computer running Windows 7 and Microsoft .Net Framework 4.6, if all Windows updates have not been applied, the computer becomes unresponsive after installation. To work around this issue, ensure that all Windows updates are applied before beginning installation. [CSF-1158]
- Endpoint Security Suite Enterprise is not supported with PC Cleaner Pro. [CSF-1211]
- After a Quarantined file is Waived at the EE/VE Server and the Advanced Threat Protection client moves the file from Quarantined to Waived, the client does not send an event to the Server to indicate the file has been Waived. [CSF-1322]

### Encryption Client v8.9

- Added 04/2016 - A computer running Windows 7 hibernates although the client is unable to encrypt the hibernation data and the Prevent Unsecured Hibernation policy is enabled. [DDPC-1220]
- The organization and naming of some policies differ in the local console and EE or VE Server Remote Management Console. [DDPC-1253]
- Added 8/2017 - When the user inserts EMS-encrypted media and clicks **Access Encrypted Files** on a Windows 10 computer without the Encryption client installed, the options **Install EMS Service** and **Run EMS Explorer** are not available. [DDPC-1449]
- On HCA-encrypted computers running the Windows 10 Fall Update, HCA decryption does not start after the HCA encryption policy is changed to Off. [DDPC-1452]
- On some USB drives, External Media Shield leaves some files unencrypted and renamed with "CE????<original filename>ERR." This occurs only occasionally, with USB drives or drivers that repeatedly disconnect and reconnect the drives. To work around this issue, rename the files with their original filenames, then remove and reconnect the drive. If the EMS Scan External Media policy is On, the resulting encryption sweep will process the files. [DDPC-1532]
- If the HCA algorithm is changed after encryption, HCA encryption does not start. [DDPC-1533]

### Advanced Authentication v8.9

- On UEFI computers running the Windows 10 Fall Update and AVG Antivirus, Advanced Authentication installation with the child installer is interrupted and never completes. [CSF-1192]
- The fingerprint reader on the Latitude 7510 running Windows 10 loses functionality after upgrade to Windows 10 Fall Update. To work around this issue, perform two restarts and the fingerprint reader will function again. [CSF-1210]
- Occasionally on computers running the Windows 10 Fall Update, fingerprints may need to be re-enrolled. [CSF-1225]

## Preboot Authentication v8.9

- After recovering PBA access through recovery questions, the password change page displays a message that, if no action is taken, the user will be automatically logged in to the Windows session, although no automatic login occurs. [CSF-1083]
- Added 04/2018- When a user tries to sync to the server while using a Latitude 7204 Rugged Machine on an XFR dock with Windows 10 x32 and the Encryption client installed, the options **Sync and Network** are not available at the PBA Log in screen. [DDPC-1638]
- Added 4/2017 - Login or recovery fails when a German keyboard is used to enter special characters into the password or recovery answer fields. [DDPC-5531]

## Previous Technical Advisories

This section includes previous Technical Advisories for the Dell Data Protection | Encryption client, SED client, Advanced Authentication, and BitLocker Manager for releases of Enterprise Edition v7.0/7.0.1 - v8.7.1. Depending on the Endpoint Security Suite Enterprise deployment and operating systems of client computers, some issues are not applicable.

### Technical Advisories v8.7.1

- Added 8/2017 - The Dell Optiplex 7040 keyboard becomes unresponsive when the Advanced Boot Options menu is accessed with the PBA active. [DDPC-2684]

### Technical Advisories v8.7

#### Encryption Client

- If the HCA algorithm is changed during encryption, SDE encryption rather than HCA re-encryption begins. To work around this issue, restart the computer. After log in, HCA encryption begins normally. [DDPMTR-406]
- Reinstallation may fail with an error such as a file or folder access error or an EMSService crash, if the \temp folder was previously encrypted with the Common Encryption Key and files were not fully decrypted before uninstallation. To work around this issue, before reinstalling, remove files from the \temp folder. [DDPMTR-1647, DDPMTR-1782]
- When the Encryption Removal Agent is used to decrypt and uninstall, if an invalid Encryption Administrator Password is entered, an incorrect error message displays: "Failed to deserialize the specific file" [DDPMTR-1649]
- Running Diagnostic Info results in a file archiving error if run when files that must be accessed are locked or in use. [DDPMTR-1830]
- When running the Setup Wizard after WSDDeactivate, access to Common and User encrypted data is lost. To work around this issue, after running WSDDeactivate, do not run the Setup Wizard. Instead, perform File/Folder Encryption recovery as explained in the *Recovery Guide*. Select the option, My system does not allow me to access encrypted data.... Reboot the computer then run the Setup Wizard to re-activate the user. [DDPMTR-1831]
- When the EMS Access Code Failure Action policy is set to Apply Cooldown, the cooldown is not applied. To work around this issue, after the allowed number of password attempts, the user must manually authenticate to the device. For more information, see "EMS Authentication Failure" in *AdminHelp*, accessible from the Remote Management Console. [DDPMTR-1859]
- If EMS Service (without the full version of the Shield) is installed, uninstall it prior to installing Enterprise Edition. Otherwise, installation will fail. [DDPMTR-1871]
- After upgrade from v8.2 or later, authentication with fingerprints fails. To work around this issue, re-enroll fingerprints after upgrade. [CSF-746]
- After uninstallation, the DDP Console icon remains on the desktop. To work around this issue, delete the icon after uninstallation. [DDPMTR-1815]

#### Preboot Authentication

- If activation fails with an error message that the SED must be recovered, perform a recovery using the instructions in the *Recovery Guide*, then reinstall Advanced Authentication and re-activate. [DDPLP-305]

## Technical Advisories v8.6.1

No Technical Advisories were introduced in v8.6.1.

## Technical Advisories v8.6

### Encryption Client

- Added 09/2015 - In order to add new features, functionality, and the newest operating systems, Enterprise Edition for Windows will support Windows XP through Shield version 8.5.
- Added 08/2015 - If Microsoft TPM Base Services is improperly installed, the following functionality is affected: HCA provisioning, fingerprint enrollment in the DDP Console/Security Console, and BitLocker Manager operation. For more information and to work around this issue, refer to this KB article: <http://www.dell.com/support/article/us/en/19/SLN296706>. [CSF-454]
- If HCA policy is disabled or the HCA encryption algorithm is changed during encryption, the computer may experience a blue screen after reboot or at PBA logon. [DDPMTR-282]
- During SDE encryption, a popup notification displays to prompt the user to cancel encryption when an application is waiting for encryption of a file to complete. If this occurs rapidly during a short length of time, multiple notifications may simultaneously display. [DDPMTR-943]
- Due to Microsoft's change in the way Windows handles stopping a critical service, stopping a DDP service such as CMGShield service, EMS service, or the Dell Data Protection | Encryption process in Task Manager will result in the computer experiencing a blue screen. [DDPMTR-945]
- In Windows 10, when using EMS Explorer to open a 5GB file on encrypted removable media an error displays, "The... file is too large for notepad," and the file does not open. [DDPMTR-990]
- When opening a file on encrypted removable media through EMS Explorer on a non-Shielded computer, if the removable media is removed without being ejected, the file remains in the computer's Ems Explorer Temporary Files folder in clear text after the file is closed. Properly ejecting the removable media properly removes these clear-text files. [DDPMTR-1157]
- After recovery of a computer running Windows 10 with HCA policy enabled, if HCA policy is then disabled the computer experiences a blue screen rather than decrypting as expected. [DDPMTR-1303]

### • **Advanced Authentication**

When a user begins credential enrollment but quits without saving before enrollment is complete, the credentials are enrolled rather than discarded. To work around this issue, if policy allows the user to modify their own credentials, the user can open the DDP Console, select the **Enrollments** tile, select and delete the credentials. Otherwise, an administrator must remove them. [CSF-146]

- Password Manager does not support the Windows 10 web browser, Microsoft Edge. [CSF-281]
- When running on Windows 10, the DDP Console About window displays incorrect BIOS information and an incorrect serial number for the computer's motherboard. [CSF-291, CSF-301]
- When a contactless smart card is moved across the card reader, a popup notification prompts the user to enroll the smart card. If the card is moved multiple times in a short length of time, multiple popup notifications may simultaneously display. [CSF-293]
- Amended 08/2015 - When using the child installer, no reboot automatically occurs, but a restart is necessary. The user must manually restart the computer or, to force a restart after installation, add /forcerestart to the installation command. [CSF-336]
- On Windows 10, if the Validity Fingerprint Sensor driver is out-of-date, when PBA is activated, the computer experiences a blue screen. To work around this issue, ensure that PBA is not enabled by policy, then follow these steps:
  1. Install Dell Data Protection then reboot.
  2. In Windows Control Panel, navigate to Device Manager.
  3. Under Biometric Devices, disable the Validity Fingerprint Sensor.
  4. Activate the PBA.
  5. After reboot, the Validity Fingerprint Sensor can be re-enabled, and the fingerprint reader functions as expected.

To download the latest Validity Fingerprint Sensor driver, go to <http://www.dell.com/support/home/us/en/19/Products/?app=drivers> and select your computer model to check and download the latest driver.

[CSF-349]

- When running Windows 10 on Dell Latitude E7250 or E7450, when the computer resumes from sleep, hibernation, warm boot, or cold boot, the user may be unable to authenticate with an enrolled contactless smart card. To work around this issue, change the policy to require only password authentication. The user should log on and re-enroll the contactless smart card. After re-enrollment, the user will be able to log on with the contactless smart card. [CSF-362]

- Added 08/2015 - If Microsoft TPM Base Services is improperly installed, the following functionality is affected: HCA provisioning, fingerprint enrollment in the DDP Console/Security Console, and BitLocker Manager operation. For more information and to work around this issue, refer to this KB article: <http://www.dell.com/support/article/us/en/19/SLN296706>. [CSF-454]

#### **Preboot Authentication**

- Upgrade from v8.1 or v8.2 to v8.6 on a computer with a SED installed and PBA activated fails. [CSF-449, CSF-461]
- Upgrade on a computer with a LiteOn M3 series SSD installed and PBA activated fails due to the small disk size. To work around this issue, before upgrading, deprovision the PBA. After upgrade, the PBA can be reactivated. [CSF-528]
- With PBA activated on Dell Latitude E7450, navigation of the Advanced Boot Options menu is not possible because the native keyboard is not available. To work around this issue, deactivate the PBA, access the Advanced Boot Options menu, and keyboard navigation is available. [DDPLP-286]
- When running Windows 10 on a computer with smart card authentication through PBA activated, after resuming from hybrid sleep, single sign-on fails. [DDPLP-308]
- To protect communications against the OpenSSL CVE-2014-3566 vulnerability, Dell Enterprise Server v8.5.1 and DDP Enterprise Server - Virtual Edition v9.0 and later are set to communicate using TLS, by default. However, Dell Data Protection | Encryption SED and HCA v8.6 clients communicate with Enterprise Server using SSL. This means that when running Enterprise Server v8.5.1 and later, Dell Data Protection | Encryption SED or HCA v8.6 clients with Preboot Authentication activated will fail to communicate with Enterprise Server. To work around this issue, refer to knowledge base article SLN296006 at <http://www.dell.com/support/article/us/en/19/SLN296006>. This workaround must be implemented as soon as possible, in order to prevent PBA client communication issues with Enterprise Server v8.5.1 or Virtual Edition v9.0 and later. [DDPUP-733, DDPMTR-1331]
- On Dell Latitude E7250, E7350, E7450, and Venue Pro 11 (Model 7139), recovery fails with Dell Opal SED Recovery Utility one-time unlock of the drive. To work around this issue, use the recovery key to unlock a drive on one of these models. [DDPUP-763]

#### **Enterprise Edition for SED**

- Amended 08/2015 - When using the child installer, the installer will effect a reboot only if necessary. To force a restart after installation, add `/forcerestart` to the installation command. [CSF-246]

#### **BitLocker Manager**

- Amended 08/2015 - When using the child installer, the installer will effect a reboot only if necessary. To force a restart after installation, add `/forcerestart` to the installation command. [CSF-246]
- Added 08/2015 - If Microsoft TPM Base Services is improperly installed, the following functionality is affected: HCA provisioning, fingerprint enrollment in the DDP Console/Security Console, and BitLocker Manager operation. For more information and to work around this issue, refer to this KB article: <http://www.dell.com/support/article/us/en/19/SLN296706>. [CSF-454]

## Technical Advisories v8.5.1

No Technical Advisories were introduced in v8.5.1.

## Technical Advisories v8.4.1

### **Encryption Client**

- The Shield does not detect password changes for non-domain accounts when the password is reset from another account. As a result, when the non-domain user attempts to logon again, the logon fails because the Shield did not synchronize the password change. [DDPC-490]

#### **Advanced Authentication**

- Fingerprint enrollment does not prevent the user from using fingerprints from different fingers when enrolling a single finger. [MMW-212, MMW-724]

#### **Preboot Authentication**

- Single Sign-on intermittently fails on computers with self-encrypting drives on which Preboot Authentication is activated. [DDPLP-144]
- When replacing a provisioned self-encrypting drive (with the Preboot Authentication environment active) with a *new* self-encrypting drive and provisioning the Preboot Authentication environment, after the new SED is provisioned, the old SED can no longer be recovered. [DDPLP-150, MMW-581]

- On the Dell Latitude Rugged Extreme, the user is able to detach the tablet from the dock. However, the dock is needed to log in through the PBA. Detach the tablet only after the PBA authentication step is complete. [DDPLP-162, DDPLP-163]
- UPN name is not supported by PBA. The correct usage would be to login with a non-UPN user name, domain\username, or enter the username independently and select the domain from the drop-down menu. [DDPLP-167, DDPC-80, MMW-591]
- After successfully authenticating to the Preboot Authentication environment, the computer will not complete Single Sign-on. Instead, the computer halts at the Windows Logon screen for another user. Microsoft Windows 8.1 defaults to the Logon screen for the previously authenticated user. To complete logon, return to the User Tiles screen by selecting the back arrow in the top right of the screen and then selecting the correct user tile for the user authenticated in the PBA. SSO data captured by the PBA may still be present and once the user tile is selected, Windows authentication may be completed automatically. [MMW-564]

## Technical Advisories v8.3.2

### Encryption Client

- Local options to manage the secondary drive are unavailable in the Dell Data Protection | Encryption console until after a policy change on that drive is applied and the computer is re-booted. [29046]
- PCIe SSDs are not supported on Precision T-series computers.

## Technical Advisories v8.3

### All Clients

- If Windows updates are not installed before the master installer runs, installation may fail. [28835]

#### Encryption Client

- Windows logon fails with some new CAC smart cards, which use multiple certificates with the same name. One certificate is the authentication certificate and the other is a signing certificate. The algorithm used to select the certificate uses the newest certificate. If the newest certificate is the signing certificate, Windows logon will fail. To work around this issue, create an Active Directory entry for the principle name for the signing certificate. [27857]
- During a command line uninstall, the installer will not download the encryption keys for the computer unless Silent mode is specified using the parameter CMGSILENTMODE=1. To work around this issue, specify CMGSILENTMODE=1 in the command. [27979]
- All registry keys and installation files are not removed after uninstallation. [28219]
- After uninstallation, logon with cached credentials occasionally fails when the computer is not connected to the network. During uninstallation, the cached credentials are decrypted. If this decryption fails for any reason, the user will not be able to login while disconnected from the network. To work around this issue, reconnect to the network and log on to cache the credentials. [28277]
- The encryption icon that indicates that a drive is encrypted does not display when a drive has been encrypted using HCA. [28400]
- During an attended (non-silent) upgrade from v8.1, the installer does not prompt the user to confirm that the upgrade is desired before continuing the installation. [28574]
- Preboot Authentication uses a "Basic" disk partition and cannot be converted to "Dynamic" partition (for RAID arrays). Attempts to convert the partition will result in the PBA not being created or the PBA not starting. [28587]
- After partial decryption recovery on a computer with an HCA card, the local Dell Data Protection | Encryption console may display duplicate information about local disks. To work around this issue, reboot the computer. After the restart, disk information displays properly. [28656]
- After installation of the Dell Data Protection | Encryption client, the Microsoft Usbccid Smartcard Reader is intermittently reported as being in a problem state in Device Manager. However, smart cards and fingerprints seem to function normally. Dell ControlVault relies on the Microsoft Usbccid drivers. A premier case has been opened with Microsoft regarding this issue. [28697]
- Decryption on computers with HCA cards removes Preboot Authentication, which must be reinstalled. At the next logon, both an Encryption Administrator Password prompt and a Security Tools shutdown message display. When the computer is shut down, PBA activation begins. However, provisioning will be completed only after a subsequent reboot and entry of the Encryption Administrator Password. [28722]
- Infrequently, after HCA policy is set, the Preboot Authentication screen does not display until the computer is restarted a second time. [28762]
- During Preboot Authentication activation, if the computer is not connected to the network with access to the Enterprise Server, the Dell Data Protection | Encryption client does not enforce required shutdown and Preboot Authentication activation is not completed. If the Dell Data Protection | Encryption client cannot access the Enterprise Server to back up encryption keys and other critical data, PBA activation is not completed and the required shutdown does not occur. To

work around this issue, ensure that the computer has access to the Enterprise Server during the installation of the Dell Data Protection | Encryption client and policy deployment to back up encryption keys and other critical data, complete PBA activation, and enforce required shutdown. [28787/DDPC-37]

- After encryption is enabled, the computer intermittently logs a Critical System Event 41 in the System Event Logs with this description: "The system has rebooted without cleanly shutting down first. This error could be caused if the system stopped responding, crashed, or lost power unexpectedly." The issue occurs only during a reboot and does not impact the security of the data or the performance of the computer. [28795]
- Secure Boot is a Unified Extensible Firmware Interface (UEFI) protocol that Windows 8 and 8.1 users can enable in the computer's BIOS to ensure that the computer boots using trusted firmware signed by the computer manufacturer. The feature is not supported when the following conditions are met:
  - HCA with Dell Data Protection | Security Tools installed
  - HCA with the Dell Data Protection | Encryption client installed
  - HCA with Dell Data Protection | Security Tools and the Dell Data Protection | Encryption client installed

To upgrade to Windows 8 or 8.1 on a Dell computer with SED or HCA, Secure Boot cannot be enabled in BIOS. The Secure Boot setting is disabled by default for computers shipping with Windows 7 or Windows 8/8.1 Downgrade Rights. This setting should not be changed.

Instructions:

1. Turn on the power to your Dell computer. If the computer is already powered on, reboot it.
2. Press **F2** or **F12** continuously during boot until a message displays at the upper right of the screen that is similar to "preparing to enter setup" (F2) or "preparing one-time boot menu" (F12). This launches the system BIOS.
3. In Setting > General > Boot Sequence, ensure that the Legacy Boot List Option is selected.
4. In Settings > General > Advanced Boot Options, ensure that the Enable Legacy Options ROMs check box is selected.
5. In Settings > Secure Boot > Secure Boot Enable, ensure that the Secure Boot Enable selection is Disabled.
6. Apply the changes.
7. Now that the computer BIOS has been changed to a legacy boot mode, the computer must be re-imaged.

[28790]

- When running Windows 7, a computer that is HCA encrypted may not boot in Windows Safe Mode. [28819]
- When using EMS Explorer, cutting and pasting a file does not remove the file from its original location. [28848]
- After an upgrade from v8.2 to v8.3, the v8.2 the Dell Data Protection | Encryption client installer remains on the computer. [28885]
- During an SDE encryption sweep, although the disk is only partially encrypted based on the progress of the sweep, the Security Console Encryption screen shows the disk as Protected. [28888]
- After a user is suspended in the Remote Management Console, the Shield ID is blank rather than indicating that the Shield is unmanaged. On the client computer, the Dell Data Protection | Encryption local console does not open properly. [28893]
- Fingerprints and smart cards stop working after the Port Control System policy to disable USB ports is applied. Broadcom USH hardware is a USB-attached device. When the policy to disable USB ports is applied, it prevents data transmission to and from the Broadcom USH hardware, which prevents users from logging on with fingerprints or smart cards. The problem can be resolved by applying a combination of policies that restrict access to USB external media by setting Windows Portable Device and External Storage Device class policy to Read Only. This policy combination allows the Broadcom USH hardware to function properly but prevents data from being transferred from the computer to external media such as USB flash drives and smart phones. [28895]

### Advanced Authentication

- Removing the USB Fingerprint reader without ejecting the device causes Dell ControlVault to fail. The issue occurs because Windows handles the removal action of biometric devices incorrectly. To correct this issue, download and install the Hotfix available at <http://support.microsoft.com/kb/2913763>. [27696]
- A contactless card may not be immediately recognized, because Windows does not load its driver. To work around this issue, in Windows Device Manager, disable the smart card device. For more information, see <http://support.microsoft.com/kb/976832>. [27981]
- On Dell Venue tablets, the touch keyboard is not automatically available at the Windows logon screen. To work around this issue, touch the keyboard icon to display the touch keyboard. [28257]
- When the Password Manager option, Fill in logon data, is selected and credentials are enrolled with Password Manager, data is populated into a logon screen but log on does not occur. [28502]
- With Windows 8.1, after a Password Manager logon is deleted in the Security Console, the link to the logon page remains in the list of Password Manager logons. [28515]
- Password Manager is not available in Google Chrome until it is activated. To activate Password Manager in Google Chrome, follow these steps:
  1. In the Google Chrome Settings page, select **Make Google Chrome my default browser**.

2. Select **Show advanced settings** > **Content settings** > **Disable individual plug-ins** and then select **Always allowed** for the Dell Data Protection | Security Tools Plug-in. Close the Plug-ins page.
3. In the Google Chrome Settings page, select **Extensions** and check the Enable box next to the Dell Data Protection | Security Tools Extension.
4. Exit Google Chrome and re-launch.

When you access a site that contains a logon form you will be prompted with the pre-train icon to capture the logon credentials for the site.

[28528, 28678, 28719]

- In Password Manager, the Select Logon Data window does not show the user name of the first enrolled user. [28531]
- When using Password Manager with Firefox, double-clicking the pre-train icon does not open the Add Logon dialog. [28693]
- The Password Manager shortcut (CTRL+WIN+H) cannot be used on tablets, because the WIN button is not present. [28706]
- Password Manager prompts for credentials only when accessed for the first time after the user logs on and not again until the next log on or computer restart. This is working as designed. [28714]
- The Password Manager version number may differ across web browsers. [28808]
- In the Security Console, the Backup and Restore feature is described as providing data backup and restore functions but is specifically related to backup and restore of Password Manager data. [28856]
- When dual-factor authentication is enabled and the computer resumes from sleep, the computer intermittently stops responding and the screen is black. To recover from this situation press and hold the power button until the computer shuts down, then reboot the computer. [28900]

#### **SED Client**

- Windows logon fails with some new CAC smart cards, which use multiple certificates with the same name. One certificate is the authentication certificate and the other is a signing certificate. The algorithm used to select the certificate uses the newest certificate. If the newest certificate is the signing certificate, Windows logon will fail. To work around this issue, create an Active Directory entry for the principle name for the signing certificate. [27857]
- Preboot Authentication fails if a self-encrypting drive is configured as drive 1. To work around this issue, configure a self-encrypting drive as the boot drive (drive 0) for Preboot Authentication to function properly. [28266]
- Single Sign On does not function properly when cached credentials in UPN format are used. [28660]
- When Security Tools Authentication components are uninstalled, the user is not warned that Preboot Authentication is provisioned. Uninstalling Security Tools Authentication will impact only the user's ability to update credentials in the PBA but will not prevent the user from authenticating with existing user accounts. The proper uninstallation sequence is as follows:

Deactivate the PBA

Uninstall Security Framework (this also uninstalls the SED client)

Uninstall Security Tools Authentication

[28791]

- Attempting to upgrade from 8.0.0 or 8.0.1 to the latest release fails and an error message is displayed saying that the computer has not been modified. This issue occurs because the installer cannot deactivate the PBA and, therefore, uninstallation of the earlier version is blocked. To work around this issue, deactivate the PBA and reboot the computer before attempting to upgrade to the new version. [28817]
- The Dell Optiplex XE2 computer intermittently does not display the Windows logon or credential provider screen after waking from sleep. To work around this issue, upgrade to the latest applicable BIOS version, which is A05 as of 03/2014. In the BIOS screen, locate the option for Deep Sleep and disable it. [28862]
- Hybrid Sleep is not supported on Windows 8.1 with SED drives on the Precision M6800/M4800 platform. [28897]
- Secure Boot is a Unified Extensible Firmware Interface (UEFI) protocol that Windows 8 and 8.1 users can enable in the computer's BIOS to ensure that the computer boots using trusted firmware signed by the computer manufacturer. The feature is not supported when the following conditions are met:
  - SED with Dell Data Protection | Security Tools installed
  - SED with the Dell Data Protection | Encryption client installed
  - SED with Dell Data Protection | Security Tools and the Dell Data Protection | Encryption client installed
  - HCA with Dell Data Protection | Security Tools installed
  - HCA with the Dell Data Protection | Encryption client installed
  - HCA with Dell Data Protection | Security Tools and the Dell Data Protection | Encryption client installed

To upgrade to Windows 8 or 8.1 on a Dell computer with SED or HCA, Secure Boot cannot be enabled in BIOS. The Secure Boot setting is disabled by default for computers shipping with Windows 7 or Windows 8/8.1 Downgrade Rights. This setting should not be changed.

Instructions:

1. Turn on the power to your Dell computer. If the computer is already powered on, reboot it.
2. Press **F2** or **F12** continuously during boot until a message displays at the upper right of the screen that is similar to "preparing to enter setup" (F2) or "preparing one-time boot menu" (F12). This launches the system BIOS.
3. In Setting > General > Boot Sequence, ensure that the Legacy Boot List Option is selected.
4. In Settings > General > Advanced Boot Options, ensure that the Enable Legacy Options ROMs check box is selected.
5. In Settings > Secure Boot > Secure Boot Enable, ensure that the Secure Boot Enable selection is Disabled.
6. Apply the changes.
7. Now that the computer BIOS has been changed to legacy boot mode, the computer must be re-imaged.

[28790]

## Technical Advisories v8.2.1

### Encryption Client

- The Shield is intermittently sending invalid XML characters in the event bundle. The result is that event logs from endpoints are occasionally not parsed or logged for compliance reporting at the Enterprise Server. [28321]

#### Advanced Authentication

- When using Microsoft Windows 7 on the All-in-One computer without an external keyboard, the On-Screen Keyboard does not automatically display after the computer resumes from the sleep or hibernate state. To display the On-Screen Keyboard, select the On-Screen Keyboard button at the lower left of the Windows Login Screen. [28606]
- Integrated fingerprint readers on Latitude E6430u and Latitude E5430 do not work after installing Dell Data Protection | Security Tools 1.2.1 or later on Windows 7 (64-bit). To use the integrated fingerprint reader on these computer models, use Dell Data Protection | Security Tools 1.2 (or Dell Data Protection | Encryption 8.2). [28979/DDPC-157, MMW-393]

## Technical Advisories v8.2

### Advanced Authentication

- If the "Interactive logon: Smart card removal behavior" Group Policy Object is configured to lock or force log off when a smart card is removed, the computer will be locked or the user will be logged off during Advanced Authentication installation, because smart card reader drivers are updated during installation. To work around the issue, unmount the smart card from the reader prior to installing Advanced Authentication. [27856]
- When using Microsoft Windows 8.1, Single Sign-On with Password Manager does not work with some email providers. [28259]
- The Password Manager prompt to add a login screen displays after de-selecting "Prompt to add logons for logon screens" in the Security Console Settings or when selecting "Exclude this screen" in Internet Explorer Icon Settings. To correct the issue, download and install Microsoft KB2888505 <https://support.microsoft.com/kb/2888505>. [28334, 28445, 28536]
- Touch capability is not available for Password Manager icons on Dell Venue Pro 11 and Dell Venue Pro 8 tablets.
- Updated drivers for the Eikon to Go external fingerprint reader for Windows 8.1 can be found on support.dell.com.

## Technical Advisories v8.1

### Encryption Client

- When running Windows 8, the Shield's Fast User Switching message is hidden behind the Windows 8 log off screen. [26272]
- DVDs become corrupt after a PCS policy change to Read Only in the following scenario: When PCS is enabled for Optical Drives with 'UDF-Only' policy and the user copies files over (opens a session), before the session is closed (usually by ejecting the media) a new PCS policy comes down that sets the optical drive to 'Read-Only'. The Shield starts a reboot-snooze cycle when changing from 'UDF-Only' to another policy. If the user accepts the reboot request, Windows reboots without closing the session, because it assumes it can close after the reboot. However, after the reboot, the device is in 'Read-Only' mode and Windows cannot close the session, so whatever filesystem changes had been made in that session are now unrecoverable. [26966]

#### SED Client

- The computer does not Single Sign-on (SSO) after waking up from Hybrid Sleep. After the user enters their credentials at the Preboot Authentication (PBA) screen, the computer stops at the Windows logon screen and the user must manually log on to the computer.

Dell Data Protection | Security Tools and the SED client do not support Hybrid Sleep states and SSO when Preboot Authentication (PBA) is Active. Disable Hybrid Sleep when using Preboot Authentication if your organization intends to use SSO. [27496, 25785]

- When using a Precision M6800, Single Sign-On will fail if a USB device is currently plugged into the computer. [27595]
- With Windows 8, after a computer automatically moves from the sleep to hibernate state, when the computer resumes, Single Sign-On is not functioning properly. [27888]

#### **Advanced Authentication**

- The fingerprint reader on Latitude 10, Latitude 5530, and Latitude 5430 for OS logon does not work with Advanced Authentication.

#### **BitLocker Manager**

- When BitLocker is encrypting, if the PBA is turned on, the error message "createdatabase failed" may be received. To work around the issue, dismiss the dialog and allow BitLocker encryption to finish. [26540]
- When running on a Latitude E5430 and leaving the TPM in a cleared state and relying on EMAgent to activate and take ownership, a "GetPhysicalPresenceRequest - PpiAcpiFailure" error message displays. To work around the issue, have the TPM on and activated in the BIOS and enable the "TPM ACPI Support" check box in the BIOS. [26708]
- Using the GUI to upgrade from 8.0.1 to 8.1 does not function. Upgrading from 8.0.1 to 8.1 from the command line works as expected. Upgrading from the master installer also works as expected. [27664]

## Technical Advisories v8.0

### **Encryption Client**

- EMS cannot be used side-by-side with most third-party USB device encryption solutions, whether hardware or software. To use EMS, either add your third-party USB device to your whitelist, or remove the third-party encryption software.
- When the local console is left open and the computer sleeps, a message displays that "no fixed storage is found." Closing and re-opening the local console corrects the issue. If the local console cannot contact its internal server because the computer is sleeping, it correctly displays this message.
- Advanced Authentication cannot be installed when Dell Data Protection | Access is present on the computer. Follow the steps in the *Dell Data Protection | Endpoint Security Suite Administrator Guide* to uninstall DDP|A. [27073]
- When uninstalling the Dell Data Protection | Encryption client, an error may display stating, "An error occurred while trying to uninstall DDP|CSF." You may safely dismiss this error. The application will refresh, and Client Security Framework (CSF) will be properly uninstalled. [26866]

#### **SED Client**

- SED v7.3 cannot be directly upgraded to SED v8.0. To move to v8.0 issue a policy to deprovision the SED and re-provision after the upgrade.

#### **Advanced Authentication**

- Advanced Authentication cannot be installed when Dell Data Protection | Access is present on the computer. Follow the steps in the *Dell Data Protection | Endpoint Security Suite Administrator Guide* to uninstall DDP|A. [27073]

## Technical Advisories v7.7

### **Encryption Client**

- Due to a Windows operating system update that interacts with the Dell Data Protection PCS driver, DVD media fails to be formatted/burned when PCS is set to UDF only. *CD and USB media are not affected.* [24833]

## Technical Advisories v7.2.3

### **Encryption Client**

- Under some circumstances, the local console "compliance status" displayed for the eSATA port may be different than the actual status. To resolve the issue, reboot the computer.

- On some Dell platforms, the desktop background turns black after the computer wakes from a sleep state. To work around this issue, go to display settings and reset the desktop background. [24574]

### BitLocker Manager

- Encryption Status Reports will not exactly match the Windows BitLocker encryption dialog window. BitLocker Manager updates encryption status every 30 seconds, therefore there will be a 30 second delay in BitLocker Manager encryption status.
- If a user with local Admin rights uses the Microsoft Control Panel to turn off BitLocker encryption before the volume has been completely encrypted, the preset user authentication (PIN or Startup key) will be removed and the system will revert back to TPM only. To avoid this issue, local Admin users should not use the Microsoft Control Panel to change encryption status when two-factor authentication is set by policy.

## Technical Advisories v7.2.1

### Encryption Client

- When using a *desktop computer* and attempting to block SD card ports by using the "Port: SD" policy, blocking SD ports will not be successful. For *desktop computers*, the "Storage Class: External Drive Control" policy must be used to effectively block SD ports. The use of the "Storage Class: External Drive Control" policy blocks access to all external storage devices irrespective of what bus they are on. When using a *laptop computer*, SD ports can be blocked using the "Port: SD" policy. [23530]
- The F8 "discard the hibernation data" option *MUST* be used on the first system restart after software HCA decryption (using the recovery tool/bundle) is performed on a system drive that contains a valid hibernation file. HCA maintains a drive state value that identifies what drives are encrypted. Because of this, during hibernation resume, HCA attempts to decrypt data that is read from the disk and encrypt data that is written to the disk (this transition in the hibernation file causes disk corruption). Instructions: 1. Allow HCA decryption to complete. 2. During the first reboot after HCA decryption, before the operating system loads, press F8 and select "discard the hibernation data". The user can now resume normal operation of the computer.
- When using a computer equipped with a Hardware Crypto Accelerator, the Preboot Password Requirement dialog that is displayed is misleading regarding Hardware Crypto Accelerator usage. The message will be changed in the next major release to display: "A recent policy update requires the initial setup of the preboot authentication system. To enter the BIOS setup, reboot and click F2 during the Dell splash screen. Go to the "Security" option and select Preboot Authentication > Set System Password. Enter a password and exit the BIOS setup." [23205]
- When the Hardware Crypto Accelerator has used all of its lifecycles, the Shield erroneously asks the user for their Hardware Crypto Accelerator Password and Preboot Password. The message should notify the user that the computer does not have any remaining lifecycles and to contact their Administrator to get a replacement Hardware Crypto Accelerator. We expect this scenario to rarely occur. [22492]
- When using VMware, if the host computer is Shielded (essentially meaning that the port control drivers are installed on the host), when a user connects a USB device to their computer, and forces it to connect to the OS running on the VMware computer instead of the host OS, the VMware OS will not be able to access the files on the USB. The Dell port control driver is a filter driver running on USB stack. VMware is not compatible with USB filter drivers. For more information, see VMware KB article: [http://kb.vmware.com/selfservice/microsites/search.do?language=en\\_US&cmd=displayKC&externalId=1016809](http://kb.vmware.com/selfservice/microsites/search.do?language=en_US&cmd=displayKC&externalId=1016809). [20280, 22820, 28522]
- The Encryption Removal Agent can decrypt files with path lengths up to 256 characters. Files paths longer than 256 characters result in a decryption failure. To work around this issue, shorten the path length to less than 256 characters and re-initiate the Encryption Removal Agent. [23474, 23510]

## Technical Advisories v7.2

### Encryption Client

- When scanning very large files on removable media, there is a slight screen refresh delay between the local console and the External Media Shield dialog that displays the files name that are being processed. No loss of functionality is experienced. [23453]
- When ejecting removable storage without clicking the "safely removing devices" option in the system tray, the local console status line briefly flashes the "Not Attached to the Encryption System" message. The status resolves to the correct status within a second or two. This is slight screen refresh delay between the local console and External Media Shield. No loss of functionality is experienced. [23454]
- Repeatedly switching between multiple users and using fast user switching will eventually result in the Dell Data Protection | Encryption client becoming unmanaged. To identify if you are experiencing this issue, you will get a message from the local

console stating the "Connecting to Dell Data Protection | Encryption..." message, however, the connection will never be made. A computer restart corrects the issue. [23448]

- System Restore is not a full backup/restore utility. Only the following are restored when using System Restore:

Registry

Profiles

COM+ DB

WFP.dll cache

WMI DB

IIS Metabase

File types which are monitored by System Restore are as specified in [http://msdn.microsoft.com/library/en-us/sr/sr/monitored\\_file\\_extensions.asp](http://msdn.microsoft.com/library/en-us/sr/sr/monitored_file_extensions.asp). Using System Restore on any of these files which are encrypted by the Dell Data Protection | Encryption client can potentially cause corruption. Backup and restoration of Shield-encrypted files should be done at the folder level and not on an individual file basis. [23437]

## Technical Advisories v7.0/7.0.1

### Encryption Client

- Windows Update Issue - This issue is applicable when running 32-bit Windows XP, Windows Vista, and Windows 7. When using a policy template other than Basic Protection for System Drive Only and when encryption is managed by the Dell Enterprise Server, Windows updates may fail and cause Windows to roll back to a previous version update. To resolve this issue, apply the Basic Protection for System Drive Only template, commit the changes, and re-initiate the Windows update.

## Workarounds

Before you begin, be aware of the following workarounds that have been identified during testing.

- To host EMS, external media must have 64 MB available, plus open space on the storage that is equal to the largest file to be encrypted. To work around the issue, free up space on the storage or use media with more storage capacity. [DDPC-243]
- Encrypted data must be backed up while its owner is logged in. If encrypted files are backed up to an unencrypted location, the result is an unencrypted backup. To work around this issue, back up encrypted data while its owner is logged in. [3139, 11389, 12479]
- When Dell Encryption is installed, Guest accounts work properly, and Guest user account data is deleted at logoff, but Guest user account folder structures (located in the Windows user hives, normally Documents and Settings) may not be deleted at logoff. Because the data is deleted, the folder structures take up very little disk space. If this happens, you can work around the issue by having an administrator delete the excess folders periodically.
- If a user adds or removes smart card reader hardware without rebooting the Windows smart card, Dell Encryption may not properly recognize authentication. If this happens, the Dell Encryption prompts for alternate authentication. To work around this issue, reboot the Windows device. [9135]

# Software and Hardware Compatibility

Endpoint Security Suite Enterprise is tested with third-party software and hardware as needed. Dell reports problems found during testing to other vendors, where appropriate.

## Upgrade to the latest Windows 10 Feature Update

- To upgrade a computer running the Encryption client to the latest version of Windows 10 Feature Update, follow the instructions in the following article: [Dell Encryption Enterprise and Dell Encryption Personal Best Practices](#).

## Upgrade to Endpoint Security Suite Enterprise v1.4

### NOTE:

If you are upgrading Endpoint Security Suite Enterprise clients to Endpoint Security Suite Enterprise v1.4 and installing the new Client Firewall and Web Protection features, you must upgrade to Enterprise Server or VE v9.7 or later, then set the policy value of Memory Actions - Exclude Executable Files to the New Default Value shown below and push it to pre-v1.4 clients. Do not begin client upgrade before the new policy is enforced on the client.

For more information about setting policies, see *AdminHelp*, available in the Dell Server Remote Management Console.

After upgrade to Dell Server v9.7, enter the following exclusions as the policy value for Memory Action: Exclude executable files. Push the new policy to Endpoint Security Suite Enterprise clients before upgrade to Endpoint Security Suite Enterprise v1.4.

```

\Windows\System32\CmgShieldService.exe
\Windows\System32\EMSService.exe
\Program Files\Dell\Dell Data Protection\Threat Protection\DellAVAgent.exe
\Program Files\McAfee\Agent\cmdagent.exe
\Program Files\McAfee\Agent\FrmlInst.exe
\Program Files\McAfee\Agent\macmnsvc.exe
\Program Files\McAfee\Agent\macompatsvc.exe
\Program Files\McAfee\Agent\maconfig.exe
\Program Files\McAfee\Agent\masvc.exe
\Program Files\McAfee\Agent\x86\FrmlInst.exe
\Program Files\McAfee\Agent\x86\macompatsvc.exe
\Program Files\McAfee\Agent\x86\marepomirror.exe
\Program Files\McAfee\Agent\x86\McScanCheck.exe
\Program Files\McAfee\Agent\x86\McScript_InUse.exe
\Program Files\McAfee\Agent\x86\mctray_back.exe
\Program Files\McAfee\Agent\x86\Mue.exe
\Program Files\McAfee\Agent\x86\policyupgrade.exe
\Program Files\McAfee\Agent\x86\UpdaterUI.exe
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\ESConfigTool.exe
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\MFEConsole.exe
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\mfeesp.exe
  
```

\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\mfeProvisionModeUtility.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\PwdUninstall.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\RepairCache\CCUninst.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\RepairCache\McAfee\_Common\_x64.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\RepairCache\McAfee\_Common\_x64.msi  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\RepairCache\McAfee\_Common\_x86.msi  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\RepairCache\setupCC.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\aacinfo.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\cacheinfo.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\fwinfo.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\mfecanary.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\mfefire.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\mfehidin.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\mfemms.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\mfevtps.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\mmsinfo.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\vtppinfo.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\aacinfo.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\cacheinfo.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\fwinfo.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\mfecanary.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\mfefire.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\mfehidin.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\mfemms.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\mfevtps.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\mmsinfo.exe  
\Program Files\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\vtppinfo.exe  
\Program Files\McAfee\Endpoint Security\Firewall\FWInstCheck.exe  
\Program Files\McAfee\Endpoint Security\Firewall\FwWindowsFirewallHandler.exe  
\Program Files\McAfee\Endpoint Security\Firewall\mfefw.exe  
\Program Files\McAfee\Endpoint Security\Firewall\RepairCache\McAfee\_Firewall\_x64.msi  
\Program Files\McAfee\Endpoint Security\Firewall\RepairCache\McAfee\_Firewall\_x86.msi  
\Program Files\McAfee\Endpoint Security\Firewall\RepairCache\setupFW.exe  
\Program Files\McAfee\Endpoint Security\Web Control\McChHost.exe  
\Program Files\McAfee\Endpoint Security\Web Control\mfewc.exe  
\Program Files\McAfee\Endpoint Security\Web Control\mfewch.exe  
\Program Files\McAfee\Endpoint Security\Web Control\mfewcui.exe  
\Program Files\McAfee\Endpoint Security\Web Control\RepairCache\McAfee\_Web\_Control\_x86.msi  
\Program Files\McAfee\Endpoint Security\Web Control\RepairCache\setupWC.exe  
\Program Files\McAfee\marepomirror.exe  
\Program Files\McAfee\McScanCheck.exe  
\Program Files\McAfee\McScript\_InUse.exe  
\Program Files\McAfee\mctray\_back.exe

\Program Files\McAfee\Mue.exe  
 \Program Files\McAfee\policyupgrade.exe  
 \Program Files\McAfee\UpdaterUI.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\MaComServer.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\MFEConsole.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\mfeProvisionModeUtility.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\RepairCache\CCUninst.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\aacinfo.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\cacheinfo.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\fwinfo.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\mfecanary.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\mfefire.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\mfehidin.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\mfemms.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\mfevtps.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\mmsinfo.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\Release\vtpinfo.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\aacinfo.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\cacheinfo.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\fwinfo.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\mfecanary.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\mfefire.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\mfehidin.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\mfemms.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\mfevtps.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\mmsinfo.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Endpoint Security Platform\VSCore\_ENS\_10.1\x64\vtpinfo.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Web Control\McChHost.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Web Control\mfewc.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Web Control\mfewch.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Web Control\mfewcui.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Web Control\RepairCache\McAfee\_Web\_Control\_x64.msi  
 \Program Files (x86)\McAfee\Endpoint Security\Web Control\RepairCache\setupWC.exe  
 \Program Files (x86)\McAfee\Endpoint Security\Web Control\x64\mfewch.exe  
 \Windows\System32\mfevtps.exe  
 \Program Files\McAfee\Endpoint Security\Endpoint Security Platform\LogDebugSetter.exe  
 \Program Files\McAfee\Endpoint Security\MfeUpgradeTool.exe

## Aventail Access Manager

- Aventail Access Manager is not supported with the Encryption client on Windows 10 computers. [DDPC-4335]

## Windows Devices

- Whole-disk compression is not supported with the Encryption client.

## ePocrates Rx Pro

- Because its databases contain only formulary reference information, if your organization uses ePocrates Rx Pro, we recommend that you exclude certain databases from encryption using the Databases to Exclude from Encryption policy. See the following table for the databases to exclude.

**Table 1. Databases to Exclude**

<b>Databases to Exclude</b>		
abbreviations-nc-2	eula-nc-2	PrefsDB
altclin-nc-2	formdetails-nc-2	pricing-nc-2
cfg-nc-2	formsortorder-nc-2	prostrings-nc-2
classes-nc-2	formstatus-nc-2	SmsHEULA-nc-2
clientnames-nc-2	groupid-nc-2	sort-nc-2
clinical-nc-2	lasths-nc-2	status-nc-2
druginteractions-nc-2	p002-nc-2	strings-nc-2
drugs-nc-2	p011-nc-2	utilities-nc-2
duse-nc-2	p120-nc-2	version-nc-2

## Hacks and Utilities

- Hacks or utilities that alter device manufacturer performance specifications are not supported.