Installation of CAC*Star™* on a Dell S2815dn MFD

The contents of the box includes the CAC*Star* option, User's Guide, and a bag containing 3 screws required for securing the CAC*Star* option to the printer. The bag contains 2 M3 x 10mm screws and an M3 x 50mm screw. You will need a Phillips #1 screwdriver.

Turn off power to the S2815.

At the rear of the S2815, remove the mounting screw indicated by an arrow in the following picture:

Slide the CAC*Star* assembly onto the left hand side of the S2815 as in the picture below. The CAC*Star* will wrap around the left scanner post as shown. Align the length of the CAC*Star* with the horizontal edges of the MFD plastic skins so the CAC*Star* is level as shown.   It helps to have a second person hold the CAC*Star* in place or use a clamp.   With some practice, you can do this without a helper or clamp.

Connect the CAC*Star* Ethernet cable to the S2815 Ethernet port. Use the three supplied screws to attach the back assembly to the S2815. Use the M3 x 50mm screw for the lower hole to attach the CAC*Star* using the hole from which the screw was removed earlier. Do not overtighten this screw. Use the 2 M3 x 10mm screws for the upper holes to attach the back assembly to the base CAC*Star* assembly as shown below.

Plug the power "Y" cable into the back of the printer. Plug the thin USB power cable from the CAC*Star* into the USB charger that is plugged into the remaining Y of the power cable. This USB cable is for power only. It has no data connection. Plug the printer's power cable from the wall into the remaining end of the Y cable.

Turn on the S2815.   Refer to the CAC*Star* User's Guide for configuration.

Note: In some cases there may be a European power cable for the printer included in the CAC*Star* box.   If you are a US customer and do not need this cable, it may be discarded.