

Dell™ PowerConnect™ 2748

PowerConnect 2748 Release Notes

System Firmware Version 1.0.0.32



**Information in this document is subject to change without notice.
© 2006 Dell Inc. All rights reserved.**

Reproduction in any manner whatsoever without the written permission of Dell Inc. is strictly forbidden.

Trademarks used in this text: *Dell*, the *DELL* logo, and *PowerConnect* are trademarks of Dell Inc.;

Other trademarks and trade names may be used in this document to refer to either the entities claiming the marks and names or their products. Dell Inc. disclaims any proprietary interest in trademarks and trade names other than its own.

December 2006

Table of Contents

Introduction	1
Global Support	1
User documentation Specifications	1
Firmware Specifications	1
Known Restrictions and Limitations	2
End of Release Notes	2

PowerConnect 2748 Release Notes

Introduction

The purpose of this document is to detail the notes and limitations of the new software revision. It is recommended to use this document as a guideline prior to installing the software on the device.

It is recommended that this release note be thoroughly reviewed prior to installing or upgrading of this product.

Global Support

For information regarding firmware updates, release notes, or additional assistance, see the Dell Support website at support.dell.com.

User documentation Specifications

The following user document is available for this device:

- PowerConnect 2748 User's Guide

Firmware Specifications

This document provides specific information for the Dell PowerConnect 2748 product, firmware version 1.0.0.32. It is recommended that this release note be thoroughly reviewed prior to installing this product.

Firmware Version Details

Boot PROM Name	Version No.	Release Date
bryant48_boot-10003.rfb	1.0.0.3	Aug, 2006

Firmware Image Name	Version No.	Release Date
bryant48-10032.ros	1.0.0.32	Aug, 2006

Version Numbering Convention					
Version number	Description				
bryant48	1	0	0	32	Four part version number
			↑		Denotes the build number.
		↑			Denotes an ad hoc release of the product software.
	↑				Denotes a scheduled maintenance release of the product software.
↑					Denotes a major version number.

The firmware image version should be 1.0.0.32 on the PowerConnect 2748 switch. The boot prom image should be 1.0.0.3.

For information about loading the boot PROM software and updating the firmware image, see the Dell PowerConnect 2748 User's Guide.

PowerConnect 2748 Release Notes

Known Restrictions and Limitations

Integrated Cable Test

Title	Description	Reference
Inconsistent Integrated Cable Test results	Testing the integrated cable with the link speed set to 1000 Mbps, displays inconsistent results.	69139
Incorrect cable test result for the combo ports (shorted cable)	Testing a shorted cable (RJ45) using the Integrated Cable Test, displays the test result as Short Cable for ports G1-G44 and Unknown for G45-G48.	71496

EWS

Title	Description	Reference
Browse button for HTTP downloads in help file.	The Browse button is not mentioned in the help file for HTTP downloads.	72487
Login screen accepts any password for default username	The login screen accepts any password with the default username, admin .	71825

End of Release Notes