

Storage Center Drive Firmware Updates 2018

Drive firmware updates are installed through the Storage Center operating system. Use the storage management user interface to update Storage Center software and to download and apply the drive firmware updates.

You can either download and apply the updates immediately, or download the updates and then apply them later. See the *Dell Storage Manager Administrator's Guide* for more information.

Topics:

- [Revision History](#)
- [Update Priority](#)
- [2018 Q1 Drive Firmware Updates](#)

Revision History

Document number: 680-123-008

Revision	Date	Description
A	March 2018	Initial release

Update Priority

The following sections list the drive firmware updates by software version and product ID. Each update is assigned a priority to indicate when to perform the update:

- **Recommended:** Dell recommends applying this update during your next scheduled update cycle. The update contains feature enhancements or changes that will help keep your system software current and compatible with other system modules (firmware, BIOS, drivers and software).
- **Urgent:** Dell highly recommends applying this update as soon as possible. The update contains changes to improve the reliability and availability of your Dell system.
- **Optional:** Dell recommends the customer review specifics about the update to determine if it applies to your system. The update contains changes that impact only certain configurations, or provides new features that may/may not apply to your environment.

2018 Q1 Drive Firmware Updates

NOTE: SCOS version 6.6.x and later supports plug-and-play discovery for most new drive introductions. Drive firmware package updates are not needed to accept new drives. Plug-and-play discovery support for 4K sector drives (8 TB and 10 TB) requires SCOS version 7.1.1 or later.

Affected Software Versions

This firmware update package contains drive firmware updates for Storage Centers running the following versions of SCOS:

- Version 7.2.31, 7.2.11
- Version 7.1.30, 7.1.20, 7.1.12
- Version 6.7.40

Drive Firmware Updates in SCOS Version 7.2

The following table lists the drive firmware updates for these software releases. These updates represent Dell's latest qualification versions, and are general firmware updates (including ongoing improvements) unless otherwise noted in the comments.

Product ID (SAS Drives)	Existing Firmware Version	New Firmware Version	Priority	Comments
PX05SRB048Y	AU05	AU09	Recommended	Ongoing firmware improvements
PX05SRB096Y				
PX05SRB192Y				
PX05SRB384Y				
PX05SMB040Y				
PX05SMB080Y				
PX05SMB160Y				
HUH721008AL4204	LF04	LF12	Recommended	Ongoing firmware improvements
HUH721010AL4200	LR04	LR12	Recommended	Ongoing firmware improvements
ST300MP0005	VE0B	VE0C	Recommended	Ongoing firmware improvements
ST600MP0005				
ST450MP0005				
ST300MP0025	VEC9	VECB	Recommended	Ongoing firmware improvements
ST600MP0025				
ST1800MM0018	TE2A	TE2B	Recommended	Ongoing firmware improvements
ST600MM0088	TE0B	TE0C	Recommended	Ongoing firmware improvements
ST900MM0168				
ST1200MM0088				

Product ID (SAS Drives)	Existing Firmware Version	New Firmware Version	Priority	Comments
PX04SMB040	AN09	AN0D	Recommended	Ongoing firmware improvements
PX04SMB080				
PX04SMB160				
PX04SRB048				
PX04SRB096				
PX04SRB192				
PX04SRB384				
HUS726060AL5214	<ul style="list-style-type: none"> · KF26¹ · KF31² 	KF37	Urgent	Ongoing firmware improvements
HUH728080AL4204	<ul style="list-style-type: none"> · GF25 ¹ · GF31 ² 	GF37	Urgent	Ongoing firmware improvements

¹ Version 7.2.31

² Version 7.2.11

Drive Firmware Updates in SCOS Version 7.1

The following table lists the drive firmware updates for these software releases. These updates represent Dell's latest qualification versions, and are general firmware updates (including ongoing improvements) unless otherwise noted in the comments.

Product ID (SAS Drives)	Existing Firmware Version	New Firmware Version	Priority	Comments
PX05SRB048Y	AU05	AU09	Recommended	Ongoing firmware improvements
PX05SRB096Y				
PX05SRB192Y				
PX05SRB384Y				
PX05SMB040Y				
PX05SMB080Y				
PX05SMB160Y				
HUH721008AL4204	LF04	LF12	Recommended	Ongoing firmware improvements
HUH721010AL4200	LR04	LR12	Recommended	Ongoing firmware improvements
ST300MP0005	VE0B	VE0C	Recommended	Ongoing firmware improvements
ST600MP0005				
ST450MP0005				
ST300MP0025	VEC9	VECB	Recommended	Ongoing firmware improvements
ST600MP0025				
ST1800MM0018	TE2A	TE2B	Recommended	Ongoing firmware improvements
ST600MM0088	TE0B	TE0C	Recommended	Ongoing firmware improvements
ST900MM0168				
ST1200MM0088				
PX04SMB040	AN09	AN0D	Recommended	Ongoing firmware improvements
PX04SMB080				
PX04SMB160				
PX04SRB048				
PX04SRB096				
PX04SRB192				
PX04SRB384				
HUS726060AL5214	<ul style="list-style-type: none"> • KF26 ¹ • KF31 ² 	KF37	Urgent	Ongoing firmware improvements
HUH728080AL4204	<ul style="list-style-type: none"> • GF25 ¹ • GF31 ² 	GF37	Urgent	Ongoing firmware improvements

¹ Version 7.1.30

² Version 7.1.20, 7.1.12

Drive Firmware Updates in SCOS Versions 6.7

The following table lists the drive firmware updates for these software releases. These updates represent Dell's latest qualification versions, and are general firmware updates (including ongoing improvements) unless otherwise noted in the comments.

Product ID (SAS Drives)	Existing Firmware Version	New Firmware Version	Priority	Comments
PX05SRB048Y	AU05	AU09	Recommended	Ongoing firmware improvements
PX05SRB096Y				
PX05SRB192Y				
PX05SRB384Y				
PX05SMB040Y				
PX05SMB080Y				
PX05SMB160Y				
ST300MP0005	VE0B	VE0C	Recommended	Ongoing firmware improvements
ST600MP0005				
ST450MP0005				
ST300MP0025	VEC9	VECB	Recommended	Ongoing firmware improvements
ST600MP0025				
ST1800MM0018	TE2A	TE2B	Recommended	Ongoing firmware improvements
ST600MM0088	TE0B	TE0C	Recommended	Ongoing firmware improvements
ST900MM0168				
ST1200MM0088				
PX04SMB040	AN09	AN0D	Recommended	Ongoing firmware improvements
PX04SMB080				
PX04SMB160				
PX04SRB048				
PX04SRB096				
PX04SRB192				
PX04SRB384				
HUS726060AL5214	KF31	KF37	Urgent	Ongoing firmware improvements

Copyright © 2018 Dell Inc. or its subsidiaries. All rights reserved. Dell, EMC, and other trademarks are trademarks of Dell Inc. or its subsidiaries. Other trademarks may be trademarks of their respective owners.