

Dell PowerConnect W-AirWave Wireless Management Suite Firmware Matrix

W-Airwave Wireless Management Suite	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Dell PowerConnect						
W Series: W-620, W-650, W-651 W-3200, W-3400, W-3600 W-AP92, W-AP93 W-AP105 W-AP124, W-AP125	5.0.2	●	--	●	Telnet/TFTP	7.0.10
3Com						
8750	2.03.13	--	--	●	Telnet/TFTP	3.4.0
WX Series and APs	6.0.3.2	--	--	--	--	5.1.0
	6.0.3.2	●	●	●	Telnet/TFTP/FTP	5.3.0
	7.0.5.6	●	●	●	Telnet/TFTP/FTP	6.4.0
Apple						
(Graphite) Airport	3.84	--	--	●	--	3.2.2
Aruba						
200, 800, 6xx, 2400, 3x00, 5000, 6000 & APs	2.5.1.5	--	--	--	--	4.3.0
	2.5.1.5	--	--	●	Telnet/TFTP	4.4.0
	2.5.4.26	●	--	●	Telnet/TFTP	4.4.0
	3.1.0	--	--	●	Telnet/TFTP	5.1.0
	3.1.1	--	--	●	Telnet/TFTP	5.2.4
	3.3.0	--	--	●	Telnet/TFTP	5.3.0
	3.3.0	●	●	●	Telnet/TFTP	6.0.0
	3.3.1.11	●	●	●	Telnet/TFTP	6.1.0
	3.3.1.28	●	●	●	Telnet/TFTP	6.3.0
	3.3.1.31	●	●	●	Telnet/TFTP	6.4.0
	3.3.2.5	●	●	●	Telnet/TFTP	6.1.0
	3.3.2.10	●	●	●	Telnet/TFTP	6.2.0
	3.3.2.16	●	●	●	Telnet/TFTP	6.3.0
	3.3.2.21	●	●	●	Telnet/TFTP	6.4.0
	3.3.2.24	●	●	●	Telnet/TFTP	7.0.0
	3.3.3.0	●	●	●	Telnet/TFTP	6.4.0
	3.4.0.0	●	●	●	Telnet/TFTP	6.3.0
	3.4.0.6	●	●	●	Telnet/TFTP	6.4.0
	3.4.1.0	●	●	●	Telnet/TFTP	6.4.0
	3.4.2.1	●	●	●	Telnet/TFTP	7.0.0
3.4.3.0	●	●	●	Telnet/TFTP	7.1.0	
5.0.0.0	●	●	●	Telnet/TFTP	7.0.0	
5.0.1.0	●	●	●	Telnet/TFTP	7.1.0	
5.0.2.0	●	●	●	Telnet/TFTP	7.1.0	
6.0.0.0-beta	●	●	●	Telnet/TFTP	7.1.0	
3x00, RAP-5WN,RAP-2WG	3.3.2.10-rn-3.0.0	●	●	●	Telnet/TFTP	6.2.0
	3.3.2.14-rn-3.1.0	●	●	●	Telnet/TFTP	6.3.0
	3.3.2.18-rn-3.1.3	●	●	●	Telnet/TFTP	6.4.0
	3.3.2.24-rn-3.1.7	●	●	●	Telnet/TFTP	7.0.0
	3.3.2.24-rn-3.1.12	●	●	●	Telnet/TFTP	7.1.0
Alcatel-Lucent						
OAW-43xx OAW-4x04 OAW-6000 & APs	2.5.1.5	--	--	●	Telnet/TFTP	6.1.0
	2.5.4.26	●	--	●	Telnet/TFTP	6.1.0
	3.1.0	--	--	●	Telnet/TFTP	6.1.0
	3.1.1	--	--	●	Telnet/TFTP	6.1.0
	3.3.0	●	●	●	Telnet/TFTP	6.1.0
	3.3.1.11	●	●	●	Telnet/TFTP	6.1.0
	3.3.1.28	●	●	●	Telnet/TFTP	6.3.0
	3.3.1.31	●	●	●	Telnet/TFTP	6.4.0
	3.3.2.5	●	●	●	Telnet/TFTP	6.1.0
	3.3.2.10	●	●	●	Telnet/TFTP	6.2.0
	3.3.2.16	●	●	●	Telnet/TFTP	6.3.0
	3.3.2.21	●	●	●	Telnet/TFTP	6.4.0
	3.3.2.24	●	●	●	Telnet/TFTP	7.0.0
	3.3.3.0	●	●	●	Telnet/TFTP	6.4.0
	3.4.0.6	●	●	●	Telnet/TFTP	6.4.0
	3.4.1.0	●	●	●	Telnet/TFTP	6.4.0
	3.4.2.1	●	●	●	Telnet/TFTP	7.0.0
	5.0.0.0	●	●	●	Telnet/TFTP	7.0.0
5.0.1.0	●	●	●	Telnet/TFTP	7.1.0	
5.0.2.0	●	●	●	Telnet/TFTP	7.1.0	

Dell PowerConnect W-AirWave Wireless Management Suite Firmware Matrix

W-Airwave Wireless Management Suite	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Avaya						
AP-1/AP-2	3.95	●	●	●	SNMP/TFTP	2.2.0
AP-3	2.0	●	--	●	SNMP/TFTP	2.2.0
	2.3.3	●	--	●	SNMP/TFTP	2.3.0
	2.4.0	●	●	●	SNMP/TFTP	2.5.0
	2.4.3	●	●	●	SNMP/TFTP	2.5.0
	2.4.5	●	●	●	SNMP/TFTP	2.6.0
	2.4.11	●	●	●	SNMP/TFTP	2.8.0
	2.5.2	●	●	●	SNMP/TFTP	3.1.2
	2.5.3	●	●	●	SNMP/TFTP	3.1.3
AP-4 AP-5 AP-6	2.5.5	●	●	●	SNMP/TFTP	4.1.0
	2.3.1	●	--	●	SNMP/TFTP	2.11.0
	2.3.3	●	--	●	SNMP/TFTP	2.11.0
	2.4.3	●	●	●	SNMP/TFTP	2.11.0
	2.4.5	●	●	●	SNMP/TFTP	2.11.0
	2.4.11	●	●	●	SNMP/TFTP	2.11.0
	2.5.2	●	●	●	SNMP/TFTP	3.1.2
AP-7	2.5.3	●	●	●	SNMP/TFTP	3.1.3
	2.5.5	●	●	●	SNMP/TFTP	4.1.0
	2.5.2	●	●	●	SNMP/TFTP	3.2.1
	2.6.0	●	●	●	SNMP/TFTP	3.2.1
	3.1.0	●	●	●	SNMP/TFTP	3.3.3
	3.2.0	●	●	●	SNMP/TFTP	4.2.0
AP-8	3.2.1	●	●	●	SNMP/TFTP	4.3.0
	3.4.0	●	●	●	SNMP/TFTP	4.4.1
	2.4.5	●	●	●	SNMP/TFTP	2.11.0
	2.4.11	●	●	●	SNMP/TFTP	2.11.0
	2.4.12	●	●	●	SNMP/TFTP	3.0.2
	2.5.2	●	●	●	SNMP/TFTP	3.1.2
	2.6.0	●	●	●	SNMP/TFTP	3.1.2
	3.1.0	●	●	●	SNMP/TFTP	3.3.4
Bel Air						
200	main.2005.03.29	--	--	--	--	4.0.2
Cisco Pre-VxWorks						
4800	8.65.2	●	●	●	Telnet/TFTP	3.2.2
Cisco VxWorks						
340 350	11.01	●	--	●	SNMP/TFTP	2.2.0
	11.03	●	--	●	SNMP/TFTP	2.2.0
	11.06A	●	--	●	SNMP/TFTP	2.2.0
	11.07A	●	--	●	SNMP/TFTP	2.2.0
	11.08T1	●	--	●	SNMP/TFTP	2.2.0
	11.10T	●	--	●	SNMP/TFTP	2.2.0
	11.21	●	●	●	SNMP/TFTP	2.2.0
	11.23T	●	●	●	SNMP/TFTP	2.2.0
	12.01T1	●	●	●	SNMP/TFTP	2.5.0
	12.02T1	●	●	●	SNMP/TFTP	2.7.0
	12.03T	●	●	●	SNMP/TFTP	2.8.0
	12.04	●	●	●	SNMP/TFTP	2.9.0
	12.05	●	●	●	SNMP/TFTP	3.0.4
1200	11.40T	●	--	●	SNMP/TFTP	2.2.0
	11.42T	●	--	●	SNMP/TFTP	2.2.0
	11.54T	●	--	●	SNMP/TFTP	2.2.0
	11.56	●	●	●	SNMP/TFTP	2.2.0
	12.01T1	●	●	●	SNMP/TFTP	2.5.0
	12.02T1	●	●	●	SNMP/TFTP	2.7.0
	12.03T	●	●	●	SNMP/TFTP	2.8.0
	12.04	●	●	●	SNMP/TFTP	2.9.0
12.05	●	●	●	SNMP/TFTP	3.0.4	

Dell PowerConnect W-AirWave Wireless Management Suite Firmware Matrix

W-Airwave Wireless Management Suite	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Cisco IOS						
350 1100 1200	12.2(4)JA	●	●	●	Telnet/TFTP	2.4.0
	12.2(8)JA	●	●	●	Telnet/TFTP	2.4.0
	12.2(11)JA1	●	●	●	Telnet/TFTP	2.4.0
	12.2(13)JA	●	●	●	Telnet/TFTP	2.6.0
	12.2(13)JA1	●	●	●	Telnet/TFTP	2.8.0
	12.2(13)JA3	●	●	●	Telnet/TFTP	2.11.0
	12.2(13)JA4	●	●	●	Telnet/TFTP	2.11.0
	12.2(15)JA	●	●	●	Telnet/TFTP	2.11.0
	12.2(15)XR	●	●	●	Telnet/TFTP	3.0.2
	12.2(15)XR2	●	●	●	Telnet/TFTP	3.0.2
	12.3(2)JA	●	●	●	Telnet/TFTP	3.1.3
	12.3(2)JA2	●	●	●	Telnet/TFTP	3.2.0
	12.3(4)JA	●	●	●	Telnet/TFTP	3.3.0
	12.3(7)JA	●	●	●	Telnet/TFTP	3.4.2
	12.3(7)JA1	●	●	●	Telnet/TFTP	4.0.2
	12.3(7)JA2	●	●	●	Telnet/TFTP	4.0.2
	12.3(8)JA	●	●	●	Telnet/TFTP	4.2.0
12.3(8)JA2	●	●	●	Telnet/TFTP	4.3.0	
12.3(8)JEA	●	●	●	Telnet/TFTP	4.4.0	
12.3(11)JA	●	●	●	Telnet/TFTP	4.4.3	
1130 1240	12.2(13)JA	●	●	●	Telnet/TFTP	3.2.1
	12.3(2)JA	●	●	●	Telnet/TFTP	3.2.1
	12.3(4)JA	●	●	●	Telnet/TFTP	3.3.0
	12.3(7)JA	●	●	●	Telnet/TFTP	3.4.2
	12.3(7)JA1	●	●	●	Telnet/TFTP	4.0.2
	12.3(7)JA2	●	●	●	Telnet/TFTP	4.0.2
	12.3(8)JA	●	●	●	Telnet/TFTP	4.2.0
	12.3(8)JA2	●	●	●	Telnet/TFTP	4.3.0
	12.3(8)JEA	●	●	●	Telnet/TFTP	4.4.0
	12.3(11)JEA	●	●	●	Telnet/TFTP	4.4.1
	12.4(3g)JA	●	●	●	Telnet/TFTP	5.2.5
12.4(10b)JA	●	●	●	Telnet/TFTP	5.3.0	
12.4(10b)JDA	●	●	●	Telnet/SSH/TFTP/SCP	6.2.0	
12.4(10b)JDA3	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0	
12.4(21a)JA1	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0	
1300	12.3(2)JA2	●	●	●	Telnet/TFTP	3.4.0
	12.3(4)JA	●	●	●	Telnet/TFTP	3.4.0
	12.3(7)JA	●	●	●	Telnet/TFTP	3.4.2
	12.3(7)JA1	●	●	●	Telnet/TFTP	4.0.2
	12.3(7)JA2	●	●	●	Telnet/TFTP	4.0.2
	12.3(8)JA	●	●	●	Telnet/TFTP	4.2.0
	12.3(8)JA2	●	●	●	Telnet/TFTP	4.3.0
	12.3(8)JEA	●	●	●	Telnet/TFTP	4.4.0
	12.4(3g)JA	●	●	●	Telnet/TFTP	5.2.5
	12.4(10b)JA	●	●	●	Telnet/TFTP	5.3.0
12.4(10b)JDA	●	●	●	Telnet/SSH/TFTP/SCP	6.2.0	
12.4(10b)JDA3	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0	
12.4(21a)JA1	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0	
1250	12.4(10b)JA	●	●	●	Telnet/TFTP	5.3.0
	12.4(10b)JDA	●	●	●	Telnet/SSH/TFTP/SCP	6.2.0
	12.4(10b)JDA3	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0
	12.4(21a)JA1	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0
1400	12.4(10b)JA3	●	●	●	Telnet/SSH/TFTP/SCP	6.0.0
	12.4(10b)JDA	●	●	●	Telnet/SSH/TFTP/SCP	6.2.0
	12.4(10b)JDA3	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0
	12.4(21a)JA1	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0
1140	12.4(21a)JA1	●	●	●	Telnet/SSH/TFTP/SCP	7.0.0
871w	12.4(4)T7	--	--	●	Telnet/SSH/TFTP/SCP	6.2.0

Dell PowerConnect W-AirWave Wireless Management Suite Firmware Matrix

W-Airwave Wireless Management Suite	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Cisco WLC						
WLC 4012, 4100, 4400 LWAPP 10x0, 1130, 1200	2.2.127.4	●	--	●	--	3.2.4
	3.1.111.0	●	--	●	--	4.0.2
	3.2.78.0	●	--	●	--	4.2.3
	3.2.116.21	●	--	●	--	4.2.3
	3.2.195.10	●	--	●	--	5.1.0
WLC/IWLC 4400, 2x00, 5500 LWAPP 1130, 1140, 1240 1250, 1300, 1500	2.2.127.4	●	--	●	--	4.0.1
	3.1.111.0	●	--	●	--	4.0.2
	3.2.116.21	●	--	●	--	4.2.3
	4.0.155.0	●	--	●	--	4.4.0
	4.0.179.x	●	--	●	--	4.4.0
	4.0.206.0	●	--	●	--	5.1.0
	4.0.217.0	●	--	●	--	5.1.0
	4.1.171.0	●	--	●	--	5.1.0
	4.1.181.0	●	--	●	--	5.2.4
	4.1.185.0	●	--	●	--	5.3.0
	4.2.61.0	●	--	●	--	5.3.0
	4.2.99.0	●	--	●	--	6.0.0
	4.2.130.0	●	--	●	--	6.1.0
	4.2.207.0	●	--	●	--	7.0.0
	5.0.148.0	●	--	●	--	6.0.0
	5.1.151.0	●	--	●	--	6.2.0
	5.2.157.0	●	--	●	--	6.2.0
	5.2.178.0	●	--	●	--	6.3.0
	5.2.193.0	●	--	●	--	6.4.0
	6.0.182.0	●	--	●	--	6.4.0
6.0.196.0	●	--	●	--	7.0.0	
7.0.80.0	●	--	●	--	7.1.0	
Colubris						
200	2.2.0	●	●	●	SNMP/HTTP	3.0.7
	2.2.0	●	●	●	SNMP/HTTP	3.1.0
	3.1.0	●	●	●	SNMP/HTTP	4.2.3
	4.1.1	●	●	●	SNMP/HTTP	4.3.0
320 330	2.1.2	●	●	●	SNMP/HTTP	3.0.2
	2.2.0	●	●	●	SNMP/HTTP	3.0.7
	2.3.0	●	●	●	SNMP/HTTP	3.1.1
	2.4.0	●	●	●	SNMP/HTTP	3.1.1
	3.1.0	●	●	●	SNMP/HTTP	4.2.3
4.1.1	●	●	●	SNMP/HTTP	4.3.0	
1250	1.3.1	●	●	●	SNMP/HTTP	2.10.0
	1.3.2	●	●	●	SNMP/HTTP	2.11.0
	2.1.2	●	●	●	SNMP/HTTP	3.0.5
	2.2.0	●	●	●	SNMP/HTTP	3.0.5
3200 3300	1.3.1	●	●	●	SNMP/HTTP	2.10.0
	1.3.2	●	●	●	SNMP/HTTP	2.11.0
	2.1.2 CN	●	●	●	SNMP/HTTP	3.0.5
	2.1.3	●	●	●	SNMP/HTTP	3.0.5
	2.3.0	●	●	●	SNMP/HTTP	3.0.7
	2.4.0	●	●	●	SNMP/HTTP	3.1.0
	2.4.1	●	●	●	SNMP/HTTP	3.3.1
	3.1.0	●	●	●	SNMP/HTTP	4.2.3
4.1.1	●	●	●	SNMP/HTTP	4.3.0	
3400/3500	dev-03-3399	--	--	●	--	3.1.1
Compaq						
WL-400	2.5.3	●	●	●	SNMP/TFTP	2.3.0
Dell						
1170	2.3.3 615	●	●	●	SNMP/TFTP	2.2.0

Dell PowerConnect W-AirWave Wireless Management Suite Firmware Matrix

W-Airwave Wireless Management Suite	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Enterasys						
Roamabout 2000	6.04.13	●	●	●	SNMP/TFTP	2.2.0
Roamabout R2	3.00.12	●	●	●	SNMP/HTTP	2.6.0
	4.00.12	●	●	●	SNMP/HTTP	2.6.0
	5.01.03	●	●	●	SNMP/HTTP	2.6.0
	5.03.01	●	●	●	SNMP/HTTP	2.8.0
	5.04.08	●	●	●	SNMP/HTTP	3.0.2
	6.01.05	●	●	●	SNMP/HTTP	3.2.5
	6.08.03	●	●	●	SNMP/HTTP	4.4.0
Roamabout 3000	1.3.1	●	●	●	SNMP/TFTP	3.0.4
	2.1.0	●	●	●	SNMP/TFTP	3.0.4
	2.1.1	●	●	●	SNMP/TFTP	3.0.4
	2.1.2	●	●	●	SNMP/TFTP	3.0.4
	2.6.6	●	●	●	SNMP/TFTP	3.0.5
	3.1.0	●	●	●	SNMP/TFTP	3.3.1
	3.1.20	●	●	●	SNMP/TFTP	4.3.0
Roamabout 4102	3.1.24	●	●	●	SNMP/TFTP	4.4.0
	1.3.1	●	●	●	SNMP/TFTP	3.0.4
	1.01.25	●	●	●	SNMP/TFTP	4.3.0
RBT-8XX0 and APs	1.01.32	●	●	●	SNMP/TFTP	4.4.0
	5.0.12.5	--	--	--	--	5.1.0
	5.0.12.5	●	●	●	Telnet/TFTP/FTP	5.3.0
Ericsson						
DSSS A11	3.00.19	●	●	●	SNMP/TFTP	2.2.0
Foundry						
IronPoint 200	2.01	--	--	--	SNMP	6.1.0
	2.02	--	--	--	SNMP	6.1.0
IronPoint 250	3.0	--	--	--	SNMP	6.2.0
	3.1	--	--	--	SNMP	6.2.0
	3.2	--	--	--	SNMP	6.2.0
Funkwerk						
Artem ComPoint	4.49	●	--	●	NDC API	3.0.3
	4.78	●	--	●	NDC API	3.0.3
	4.81	●	--	●	NDC API	3.2.1
Hirschmann						
BAT-54	7.00.0070	●	●	●	SNMP/TFTP	5.0.0
	7.10.0022	●	●	●	SNMP/TFTP	5.3.0
	7.60.0165	●	●	●	SNMP/TFTP	7.0.0
IBM						
AP-500	3.95	●	●	●	SNMP/TFTP	2.2.0
Intel						
2011B	3.00-19	●	--	●	SNMP/TFTP	2.2.0
	3.51-20	●	--	●	SNMP/TFTP	2.2.0
2011	2.21-01	●	●	●	SNMP/TFTP	2.2.0
	2.51-16	●	●	●	SNMP/TFTP	2.2.0
Intermec						
2100 / 2101 / 2102	1.94	--	--	●	SNMP/TFTP	4.0.2
2106	1.90	--	--	●	SNMP/TFTP	4.0.2
WA 21 / WA 22	2.30	--	--	●	SNMP/TFTP	4.0.2
Juniper Netscreen						
Netscreen 5GT	5.0.0	--	--	●	SNMP/TFTP	3.4.2
LANCOM						
L-54g L-54ag OAP-54 Lancom 3550	4.02.0003	--	--	●	--	3.2.4
	5.02.0012	●	●	●	--	3.2.4
	5.02.0018	●	●	●	--	3.2.4
	5.02.0020	●	●	●	SNMP/TFTP	3.4.0
	6.02.0008	●	●	●	SNMP/TFTP	4.2.0
	6.10.0038	●	●	●	SNMP/TFTP	4.3.0
	7.00.0070	●	●	●	SNMP/TFTP	5.0.0
	7.22.0016	●	●	●	SNMP/TFTP	5.3.0
	7.26.0049	●	●	●	SNMP/TFTP	5.3.0

Dell PowerConnect W-AirWave Wireless Management Suite Firmware Matrix

W-Airwave Wireless Management Suite	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Meru						
MC1000 & APs	3.3-118	--	--	--	--	5.1.0
	3.4.SR5-21	--	--	--	--	5.3.0
	3.5.Beta-29	--	--	--	--	6.0.0
	3.6	--	--	--	--	6.1.0
	3.6-124	--	--	--	--	6.3.0
	3.6-127	--	--	--	--	6.3.0
	3.6-270	--	--	--	--	6.4.0
3.6.1-49	--	--	--	--	7.0.0	
NEC						
Pasolink	4.20	--	--	--	--	6.0.0
Nomadix						
HSG	2.3.234	--	--	●	SNMP/TFTP	3.1.1
	2.4.31	--	--	●	SNMP/TFTP	3.1.2
AG 2000	1.3.211	--	--	●	SNMP/TFTP	3.3.1
	1.4.129	--	--	●	SNMP/TFTP	4.0.2
AG 2100	11.4.138	--	--	●	--	4.0.2
AG 3000	21.4.139	--	--	●	--	4.0.2
AG 5000	5.4.113	--	--	●	--	4.0.2
Nortel						
WSS23x0 & APs	5.0.11.4	--	--	--	--	5.1.0
	5.0.11.4	●	●	●	Telnet/TFTP/FTP	5.3.0
	6.0.3.2	--	--	--	--	5.3.0
	6.0.3.2	●	●	●	Telnet/TFTP/FTP	5.3.0
	7.0.5.6	●	●	●	Telnet/TFTP/FTP	6.4.0
ProCurve Networking by HP						
420	2.0.38	●	●	●	Telnet/TFTP	3.0.5
	2.0.39	●	●	●	Telnet/TFTP	3.0.6
	2.1.0	●	●	●	Telnet/TFTP	3.3.2
	2.1.3	●	●	●	Telnet/TFTP	3.3.2
	2.1.5	●	●	●	Telnet/TFTP	4.3.0
	2.1.7	●	●	●	Telnet/TFTP	4.5.0
	2.2.0	●	●	●	Telnet/TFTP	5.1.6
	2.2.5	●	●	●	Telnet/TFTP	6.3.0
DWL-520	2.0	●	--	●	SNMP/TFTP	2.2.0
	2.3.3	●	--	●	SNMP/TFTP	2.3.0
	2.4.0	●	●	●	SNMP/TFTP	2.5.0
	2.4.3	●	●	●	SNMP/TFTP	2.5.0
	2.4.5	●	●	●	SNMP/TFTP	2.6.0
	2.5.2	●	●	●	SNMP/TFTP	3.1.2
530	WA.01.16	--	--	--	--	4.3.0
	WA.01.16	●	--	●	Telnet/TFTP	5.0.0
	WA.01.19	●	●	●	Telnet/TFTP	5.0.0
	WA.02.10	●	●	●	Telnet/TFTP	6.0.0
	WA.02.19	●	●	●	Telnet/TFTP	6.1.0
xl WESM & APs	WS.01.05	--	--	●	Telnet/TFTP	4.4.0
	WS.02.01	--	--	●	Telnet/TFTP	5.2.5
	WS.02.07	●	●	●	Telnet/SSH/TFTP	5.3.0
zl WESM & APs	WT.01.03	--	--	●	Telnet/SSH/TFTP	5.3.0
	WT.01.15	●	●	●	Telnet/SSH/TFTP	7.0.0
	WT.01.28	●	●	●	Telnet/SSH/TFTP	7.0.0
MSM7xx & APs	5.3.1.8-01-7189	--	--	--	--	6.4.0

Dell PowerConnect W-AirWave Wireless Management Suite Firmware Matrix

W-Airwave Wireless Management Suite	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Proxim						
AP 500/1000	3.95	●	●	●	SNMP/TFTP	2.2.0
Wavepoint II	3.95	●	●	●	SNMP/TFTP	2.2.0
AP 600	2.3.1	●	--	●	SNMP/TFTP	2.2.0
	2.3.3	●	--	●	SNMP/TFTP	2.3.0
	2.4.3	●	●	●	SNMP/TFTP	2.5.0
	2.4.5	●	●	●	SNMP/TFTP	2.6.0
	2.4.11	●	●	●	SNMP/TFTP	2.8.0
	2.5.2	●	●	●	SNMP/TFTP	3.1.2
	2.5.3	●	●	●	SNMP/TFTP	3.1.2
	2.5.4	●	●	●	SNMP/TFTP	4.1.0
AP 700	2.5.5	●	●	●	SNMP/TFTP	3.3.1
	2.5.2	●	●	●	SNMP/TFTP	3.2.1
	2.6.0	●	●	●	SNMP/TFTP	3.2.1
	3.1.0	●	●	●	SNMP/TFTP	3.4.2
	3.2.0	●	●	●	SNMP/TFTP	4.2.0
	3.2.1	●	●	●	SNMP/TFTP	4.3.4
	3.4.0	●	●	●	SNMP/TFTP	4.4.1
	3.6.2	●	●	●	SNMP/TFTP	5.3.0
AP 2000	3.7.0	●	●	●	SNMP/TFTP	6.1.0
	4.0.1	●	●	●	SNMP/TFTP	6.2.0
	4.0.2	●	●	●	SNMP/TFTP	6.3.0
	2.0	●	--	●	SNMP/TFTP	2.2.0
	2.3.3	●	--	●	--	2.3.0
	2.4.0	●	●	●	SNMP/TFTP	2.5.0
	2.4.3	●	●	●	SNMP/TFTP	2.5.0
	2.4.5	●	●	●	SNMP/TFTP	2.6.0
AP 4000	2.4.11	●	●	●	SNMP/TFTP	2.8.0
	2.5.2	●	●	●	SNMP/TFTP	3.1.2
	2.5.3	●	●	●	SNMP/TFTP	3.1.3
	2.5.4	●	●	●	SNMP/TFTP	3.3.1
	2.5.5	●	●	●	SNMP/TFTP	4.1.0
	2.4.5	●	●	●	SNMP/TFTP	2.11.0
	2.4.11	●	●	●	SNMP/TFTP	2.11.0
	2.4.12	●	●	●	SNMP/TFTP	3.0.2
AP 4000M AP 4900M	2.5.2	●	●	●	SNMP/TFTP	3.1.2
	2.6.0	●	●	●	SNMP/TFTP	3.1.3
	3.1.0	●	●	●	SNMP/TFTP	3.4.2
	3.2.0	●	●	●	SNMP/TFTP	4.2.0
	3.2.1	●	●	●	SNMP/TFTP	4.3.4
	3.4.0	●	●	●	SNMP/TFTP	4.4.1
	3.6.2	●	●	●	SNMP/TFTP	5.3.0
	3.7.0	●	●	●	SNMP/TFTP	6.1.0
Tsunami MP.16 3500(i) SS, 3500 BS	4.0.0	●	●	●	SNMP/TFTP	6.2.0
	4.0.2	●	●	●	SNMP/TFTP	6.3.0
	3.2.0	●	●	●	SNMP/TFTP	4.3.4
	3.2.1	●	●	●	SNMP/TFTP	4.3.4
	3.4.0	●	●	●	SNMP/TFTP	4.4.1
	3.6.2	●	●	●	SNMP/TFTP	5.3.0
Tsunami MP.11a	3.7.0	●	●	●	SNMP/TFTP	6.1.0
	4.0.0	●	●	●	SNMP/TFTP	6.2.0
	4.0.2	●	●	●	SNMP/TFTP	6.3.0
	2.3.0	●	●	●	SNMP/TFTP	5.0.0
Tsunami MP.11 5054,4954, 954, 2454, 5012	1.2.0(115)	●	●	●	SNMP/TFTP	5.0.0
	1.2.0(124)	●	●	●	SNMP/TFTP	5.1.0
Tsunami MP.11a	2.0.1	●	●	●	SNMP/TFTP	3.2.4
	2.2.0	●	●	●	SNMP/TFTP	3.2.4
	2.2.2	●	●	●	SNMP/TFTP	3.2.4
	2.2.6	●	●	●	SNMP/TFTP	3.4.2
Tsunami MP.11 5054,4954, 954, 2454, 5012	2.3.0	●	●	●	SNMP/TFTP	5.2.0
	4.0.0	●	●	●	SNMP/TFTP	5.2.0

Dell PowerConnect W-AirWave Wireless Management Suite Firmware Matrix

W-Airwave Wireless Management Suite	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Siemens						
W788-2 PRO	1.2.4	--	--	--	--	3.2.2
Symbol						
3021	04.01-23	●	●	●	SNMP/TFTP	4.0.1
	04.02-19	●	●	●	SNMP/TFTP	4.0.1
4121	3.52.13	●	--	●	SNMP/TFTP	2.2.0
	2.70.06	●	●	●	SNMP/TFTP	2.2.0
4131	3.51-20	●	--	●	SNMP/TFTP	2.2.0
	3.70-72	●	●	●	SNMP/TFTP	3.0.4
	3.92-29	●	●	●	SNMP/TFTP	3.0.7
	3.93-00	●	●	●	SNMP/TFTP	3.4.2
	3.94-15	●	●	●	SNMP/TFTP	4.3.0
5131	1.1.0.0.045R	--	--	--	--	5.2.1
	1.1.0.0.045R	--	--	●	Telnet/TFTP	5.2.4
	2.0.0	●	●	●	Telnet/TFTP	6.1.0
	2.1.0	●	●	●	Telnet/TFTP	6.2.0
	2.2.0	●	●	●	Telnet/TFTP	6.3.0
	2.3.1.0-004R	●	●	●	Telnet/TFTP	7.0.0
	2.4.1.0	●	●	●	Telnet/TFTP	7.1.0
5181 7131	2.5.0.0	●	●	●	Telnet/TFTP	7.1.0
	1.1.2	●	●	●	Telnet/TFTP	6.2.0
	3.2.2	●	●	●	Telnet/TFTP	7.1.0
	4.0.3	●	●	●	Telnet/TFTP	7.1.0
WS5000 & APs	1.1.2	●	●	●	Telnet/TFTP	7.1.0
	2.0.0	--	--	--	--	4.3.0
WS2000 & APs	2.0.0	--	--	--	--	4.4.0
	0.0-35R	--	--	●	Telnet/TFTP	5.0.0
	2.2.3.0-020R	--	--	●	Telnet/TFTP	6.0.0
	2.2.3.0-020R	●	--	●	Telnet/TFTP	6.1.0
	2.3.2.0-003R	●	--	●	Telnet/TFTP	6.3.0
	2.4.0.0-023R	●	--	●	Telnet/TFTP	6.3.0
WS5100 & APs	2.4.1.0-005R	●	--	●	Telnet/TFTP	6.4.0
	2.4.4.0-001R	●	--	●	Telnet/TFTP	7.1.0
	2.0.0	--	--	--	--	4.4.0
	3.0.0	--	--	●	Telnet/TFTP	5.0.0
	3.0.2	●	●	●	Telnet/TFTP	5.3.0
	3.0.3	●	●	●	Telnet/TFTP	5.3.0
	3.0.3	●	●	●	Telnet/SSH/TFTP	6.0.0
	3.1.0	●	●	●	Telnet/SSH/TFTP	6.1.0
RFSx000 and Aps	3.2.0	●	●	●	Telnet/SSH/TFTP	6.1.0
	3.3.1	●	●	●	Telnet/SSH/TFTP/FTP	6.3.0
	3.3.3	●	●	●	Telnet/SSH/TFTP/FTP	7.1.0
	1.0.0	●	--	●	Telnet/SSH/TFTP	6.0.0
	1.2.0	●	●	●	Telnet/SSH/TFTP/FTP	6.3.0
	3.2.0	●	●	●	Telnet/SSH/TFTP	6.2.0
Systimax	4.0.0.0	●	●	●	Telnet/SSH/TFTP/FTP	7.1.0
	4.1.0.0	●	●	●	Telnet/SSH/TFTP/FTP	7.1.0
	4.2.1.0	●	●	●	Telnet/SSH/TFTP/FTP	7.1.0
	4.3.0.0	●	●	●	Telnet/SSH/TFTP/FTP	7.1.0
Airspeed 542	2.4.5	●	●	●	SNMP/TFTP	3.2.0
	2.4.11	●	●	●	SNMP/TFTP	3.2.0
	2.4.12	●	●	●	SNMP/TFTP	3.2.0
	2.5.2	●	●	●	SNMP/TFTP	3.2.0
	2.6.0	●	●	●	SNMP/TFTP	3.2.0
Toshiba						
AP 500	3.95	●	●	●	--	2.2.0
Teklogix						
9150/9160	C234p	--	--	●	--	4.4.0

Dell PowerConnect W-AirWave Wireless Management Suite Firmware Matrix

W-Airwave Wireless Management Suite	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Trapeze						
MX Series & MPs	5.0.12.2	--	--	--	--	5.1.0
	5.0.12.2	●	●	●	Telnet/TFTP/FTP	5.3.0
	6.0.2.2	--	--	--	--	5.1.0
	6.0.2.2	●	●	●	Telnet/TFTP/FTP	5.3.0
	6.0.4.2	●	●	●	Telnet/TFTP/FTP	5.3.0
	7.0.5.6	●	●	●	Telnet/TFTP/FTP	6.4.0
Tropos						
4/5210, 5320, 9422, 9532	5.1.4.7	--	--	--	--	5.0.0
3/4/5210, 5320, 9422, 9532	5.1.4.7	--	--	--	--	5.3.0
	6.5.1.3	--	--	--	--	5.3.0
	6.6.0.0	--	--	--	--	5.3.0
	6.6.1.3	--	--	--	--	6.2.0
Vivato						
VP1200	1.3.1.r4	--	--	--	--	3.3.2
VA2200	1.1.r2	--	--	--	--	3.3.1
	2.2	--	--	--	--	3.4.2
VP2200	3.0.r9	--	--	--	--	5.2.4

© 2010 Aruba Networks, Inc. AirWave®, Aruba Networks®, Aruba Mobility Management System®, and other registered marks are trademarks of Aruba Networks, Inc. Dell™, the DELL™ logo, and PowerConnect™ are trademarks of Dell Inc. All rights reserved. Specifications in this manual are subject to change without notice. Originated in the USA. Any other trademarks appearing in this manual are the property of their respective companies. Open Source Code - Certain Aruba products include Open Source software code developed by third parties, including software code subject to the GNU General Public License (GPL), GNU Lesser General Public License (LGPL), or other Open Source Licenses. The Open Source code used can be found at this site: http://www.arubanetworks.com/open_source. Legal Notice - The use of Aruba Networks, Inc. switching platforms and software, by all individuals or corporations, to terminate other vendors' VPN client devices constitutes complete acceptance of liability by that individual or corporation for this action and indemnifies, in full, Aruba Networks, Inc. from any and all legal actions that might be taken against it with respect to infringement of copyright on behalf of those vendors.